

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

LONG PAINTING COMPANY (Continued)

U003027410

Facility ID: 5585
Install Date: 8/15/1978 0:00
Capacity: 10,000 TO 19,999 GALLONS
Status: Not reported
Tank Name: UNLEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

H31
WNW
1/4-1/2
1565 ft.
Lower

LONG PAINTING CO 10TH AVE
8025 10TH AVE S
SEATTLE, WA 98108
Site 3 of 6 in cluster H

FINDS 1000232092
RCRIS-LQG WAD044036747
CSCSL
WA ICR

RCRIS:

Owner: ANNE LONG
(206) 763-8050
EPA ID: WAD044036747
Contact: BRIAN VANCE
(206) 763-8050

Classification: N, Large Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported

BIENNIAL REPORTS:

Last Biennial Reporting Year: 1999

<u>Waste</u>	<u>Quantity (Lbs)</u>	<u>Waste</u>	<u>Quantity (Lbs)</u>
D001	103650.00	D002	400.00
D006	54800.00	D007	54800.00
D008	54800.00	D010	72500.00
D018	3800.00	D035	54800.00
F003	81850.00	F005	48850.00

Violation Status: Violations exist

Regulation Violated: 200(1)(B)/630(7)
Area of Violation: GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined: 05/07/1999

Enforcement Action: WRITTEN INFORMAL
Enforcement Action Date: 05/14/1999
Penalty Type: Not reported

Regulation Violated: 170(1)(A)/070(3)
Area of Violation: GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined: 05/07/1999

Enforcement Action: WRITTEN INFORMAL
Enforcement Action Date: 05/14/1999
Penalty Type: Not reported

Regulation Violated: 200(2)
Area of Violation: GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined: 05/07/1999

Enforcement Action: WRITTEN INFORMAL
Enforcement Action Date: 05/14/1999
Penalty Type: Not reported

Regulation Violated: 200(1)(B)

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

LONG PAINTING CO 10TH AVE (Continued)

1000232092

Area of Violation:	GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined:	05/07/1999
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	05/14/1999
Penalty Type:	Not reported
Regulation Violated:	200(1)(C)
Area of Violation:	GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined:	05/07/1999
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	05/14/1999
Penalty Type:	Not reported
Regulation Violated:	200(1)(B)/630(6)
Area of Violation:	GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined:	05/07/1999
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	05/14/1999
Penalty Type:	Not reported
Regulation Violated:	200(1)(e) ref 330(2)
Area of Violation:	GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined:	09/18/1996
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	10/24/1996
Penalty Type:	Not reported
Regulation Violated:	395(1)(b)(i and ii)
Area of Violation:	GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined:	09/18/1996
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	10/24/1996
Penalty Type:	Not reported
Regulation Violated:	070(7)(c)(ii)
Area of Violation:	GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined:	03/16/1994
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	06/15/1994
Penalty Type:	Not reported
Regulation Violated:	200(1)(a)
Area of Violation:	GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined:	03/16/1994
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	06/15/1994
Penalty Type:	Not reported
Regulation Violated:	200(1)(c)
Area of Violation:	GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined:	03/16/1994
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	06/15/1994
Penalty Type:	Not reported
Regulation Violated:	200(1)(b) & 630(6)
Area of Violation:	GENERATOR-GENERAL REQUIREMENTS

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

LONG PAINTING CO 10TH AVE (Continued)

1000232092

Date Violation Determined:	03/16/1994
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	06/15/1994
Penalty Type:	Not reported
Regulation Violated:	200(1)(e)&320(1),(2a,b,d)&(3)
Area of Violation:	GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined:	03/16/1994
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	06/15/1994
Penalty Type:	Not reported
Regulation Violated:	340(1)
Area of Violation:	GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined:	03/16/1994
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	06/15/1994
Penalty Type:	Not reported
Regulation Violated:	200(1)(b) & 630(7)
Area of Violation:	GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined:	03/16/1994
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	06/15/1994
Penalty Type:	Not reported
Regulation Violated:	200(1)(d)
Area of Violation:	GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined:	03/16/1994
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	06/15/1994
Penalty Type:	Not reported
Regulation Violated:	Not reported
Area of Violation:	GENERATOR-ALL REQUIREMENTS (OVERSIGHT)
Date Violation Determined:	10/04/1985
Enforcement Action:	FINAL 3008(A) COMPLIANCE ORDER
Enforcement Action Date:	11/07/1985
Penalty Type:	Final Monetary Penalty

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

EDR ID Number
EPA ID Number
Database(s)

LONG PAINTING CO 10TH AVE (Continued)

1000232092

There are 17 violation record(s) reported at this site:

<u>Evaluation</u>	<u>Area of Violation</u>	<u>Date of Compliance</u>
Compliance Evaluation Inspection	GENERATOR-GENERAL REQUIREMENTS	05/14/199
	GENERATOR-GENERAL REQUIREMENTS	06/17/199
	GENERATOR-GENERAL REQUIREMENTS	05/15/199
	GENERATOR-GENERAL REQUIREMENTS	05/14/199
	GENERATOR-GENERAL REQUIREMENTS	05/14/199
	GENERATOR-GENERAL REQUIREMENTS	05/14/199
Other Evaluation	GENERATOR-GENERAL REQUIREMENTS	09/19/199
	GENERATOR-GENERAL REQUIREMENTS	09/19/199
Compliance Evaluation Inspection	GENERATOR-GENERAL REQUIREMENTS	03/23/199
	GENERATOR-GENERAL REQUIREMENTS	03/23/199
	GENERATOR-GENERAL REQUIREMENTS	03/23/199
	GENERATOR-GENERAL REQUIREMENTS	03/23/199
	GENERATOR-GENERAL REQUIREMENTS	04/11/199
	GENERATOR-GENERAL REQUIREMENTS	06/27/199
	GENERATOR-GENERAL REQUIREMENTS	04/11/199
	GENERATOR-GENERAL REQUIREMENTS	03/23/199
Other Evaluation	GENERATOR-ALL REQUIREMENTS (OVERSIGHT)	07/04/199

FINDS:

Other Pertinent Environmental Activity Identified at Site:

- AIRŞ Facility System (AIRS/AFS)
- Biennial Reporting System (BRS)
- Facility Registry System (FRS)
- National Emissions Trends (NET)
- Resource Conservation and Recovery Act Information system (RCRAINFO)

SHWS:

Facility ID: 71678662
Responsible Unit: NW
Latitude: 47 31 48
Longitude: 122 19 17

Ecology Site Status relative to the MTCA cleanup process:

Independent Remedial Action

Independent Site Status - those sites undergoing an independent cleanup:

Independent Site Assessment of Interim Remedial Action Report received

WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):

Not reported

Affected Media: Surface Water

Media Status: S (Suspected) - Due to preliminary investigations or the nature of business operations or manufacturing processes, certain contaminants are suspected to be present at the site

Arsenic Code: Not reported

Base/Neutral/Acid Organics: Not reported

Halogenated Organic Compounds: Not reported

Horizontal Collection Method: 4

EPA Priority Pollutants - Metals and Cyanide: Suspected to be present

Metals - Other non-priority pollutant metals: Suspected to be present

Polychlorinated biPhenyls (PCBs): Not reported

Pesticides: Not reported

Petroleum Products: Suspected to be present

Phenolic Compounds: Not reported

Non-Halogenated Solvents: Not reported

Dioxin: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

LONG PAINTING CO 10TH AVE (Continued)

1000232092

Polynuclear Aromatic Hydrocarbons (PAH): Not reported
Reactive Wastes: Not reported
Corrosive Wastes: Not reported
Radioactive Wastes: Not reported
Asbestos: Not reported
Conventional Contaminants, Organic: Not reported
Conventional Contaminants, Inorganic: Not reported

Facility ID: 71678662
Responsible Unit: NW
Latitude: 47 31 48
Longitude: 122 19 17

Ecology Site Status relative to the MTCA cleanup process:
Independent Remedial Action

Independent Site Status - those sites undergoing an independent cleanup:
Independent Site Assessment of Interim Remedial Action Report received

WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):
Not reported

Affected Media: Sediments

Media Status: S (Suspected) - Due to preliminary investigations or the nature of business operations
or manufacturing processes, certain contaminants are suspected to be present at the
site

Arsenic Code: Not reported
Base/Neutral/Acid Organics: Not reported
Halogenated Organic Compounds: Not reported
Horizontal Collection Method: 4
EPA Priority Pollutants - Metals and Cyanide: Suspected to be present
Metals - Other non-priority pollutant medals: Suspected to be present
Polychlorinated biPhenyls (PCBs): Not reported
Pesticides: Not reported
Petroleum Products: Suspected to be present
Phenolic Compounds: Not reported
Non-Halogenated Solvents: Not reported
Dioxin: Not reported
Polynuclear Aromatic Hydrocarbons (PAH): Not reported
Reactive Wastes: Not reported
Corrosive Wastes: Not reported
Radioactive Wastes: Not reported
Asbestos: Not reported
Conventional Contaminants, Organic: Not reported
Conventional Contaminants, Inorganic: Not reported

Facility ID: 71678662
Responsible Unit: NW
Latitude: 47 31 48
Longitude: 122 19 17

Ecology Site Status relative to the MTCA cleanup process:
Independent Remedial Action

Independent Site Status - those sites undergoing an independent cleanup:
Independent Site Assessment of Interim Remedial Action Report received

WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):
Not reported

Affected Media: Soil

Media Status: S (Suspected) - Due to preliminary investigations or the nature of business operations
or manufacturing processes, certain contaminants are suspected to be present at the
site

Arsenic Code: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

LONG PAINTING CO 10TH AVE (Continued)

1000232092

Base/Neutral/Acid Organics:	Not reported
Halogenated Organic Compounds:	Not reported
Horizontal Collection Method:	4
EPA Priority Pollutants - Metals and Cyanide:	Suspected to be present
Metals - Other non-priority pollutant metals:	Suspected to be present
Polychlorinated biPhenyls (PCBs):	Not reported
Pesticides:	Not reported
Petroleum Products:	Suspected to be present
Phenolic Compounds:	Not reported
Non-Halogenated Solvents:	Suspected to be present
Dioxin:	Not reported
Polynuclear Aromatic Hydrocarbons (PAH):	Not reported
Reactive Wastes:	Not reported
Corrosive Wastes:	Not reported
Radioactive Wastes:	Not reported
Asbestos:	Not reported
Conventional Contaminants, Organic:	Not reported
Conventional Contaminants, Inorganic:	Not reported

WA ICR:

Date Ecology Received Report:	11/02/1999
Contaminants Found at Site:	Metals
Media Contaminated:	Surface water, Soil
Cause of Contamination:	Not reported
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	98-19
County Code:	17
Contact:	Not reported
Report Title:	Not reported

**H32
WNW
1/4-1/2
1565 ft.
Lower**

**8025 10TH AVE SO
SEATTLE, WA

Site 4 of 6 in cluster H**

**SPILLS S105394390
N/A**

WA SPILL:

Facility ID:	513570
Date Received:	09/22/2000
Business Name:	PAINTING
Material Desc :	OTHER HAZARDOUS
Medium:	AIR
Material Qty:	Not reported
Material Units:	Not reported

**H33
WNW
1/4-1/2
1565 ft.
Lower**

**LONG INTERSTATE A JOINT VENTUR
8025 10TH AVE S
SEATTLE, WA 98108

Site 5 of 6 in cluster H**

**RCRIS-SQG 1000232342
WAD980985451**

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

LONG INTERSTATE A JOINT VENTUR (Continued)

EDR ID Number
EPA ID Number

Database(s)

1000232342

RCRIS:
Owner: LONG INTERSTATE A JOINT VENTUR
(360) 555-1212
EPA ID: WAD980985451
Contact: ELLERY BERG
(206) 763-8050
Classification: Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported
Violation Status: No violations found

H34
WNW
1/4-1/2
1565 ft.
Lower

LONG PAINTING CO
8025 10TH AV S
SEATTLE, WA 98108
Site 6 of 6 in cluster H

HAZNET S104584300
N/A

HAZNET:
Gepaid: WAD044036747
Tepaid: CAD009452657
Gen County: 99
Tsd County: San Mateo
Tons: 4.4250
Category: Other organic solids
Disposal Method: Treatment, Incineration
Contact: TY LONG
Telephone: (206) 763-8050
Mailing Address: 8025 10TH AVE S
SEATTLE, WA 98108 - 4405
County: 99
Gepaid: WAD044036747
Tepaid: CAD009452657
Gen County: 99
Tsd County: San Mateo
Tons: .1500
Category: Other organic solids
Disposal Method: Disposal, Land Fill
Contact: TY LONG
Telephone: (206) 763-8050
Mailing Address: 8025 10TH AVE S
SEATTLE, WA 98108 - 4405
County: 99
Gepaid: WAD044036747
Tepaid: CAD009452657
Gen County: 99
Tsd County: San Mateo
Tons: .1000
Category: Organic liquids with metals Alkaline solution (pH <UN-> 12.5) with metals
(antimony, arsenic, barium, beryllium, cadmium, chromium, cobalt, copper,
lead, mercury, molybdenum, nickel, selenium, silver, thallium, vanadium,
and zinc)
Disposal Method: Recycler
Contact: TY LONG
Telephone: (206) 763-8050
Mailing Address: 8025 10TH AVE S

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number
Database(s)

LONG PAINTING CO (Continued)

S104584300

County SEATTLE, WA 98108 - 4405
99
Gepaid: WAD044036747
Tepaid: CAD009452657
Gen County: 99
Tsd County: San Mateo
Tons: .3000
Category: Organic liquids with metals Alkaline solution (pH <UN-> 12.5) with metals
(antimony, arsenic, barium, beryllium, cadmium, chromium, cobalt, copper,
lead, mercury, molybdenum, nickel, selenium, silver, thallium, vanadium,
and zinc)
Disposal Method: Treatment, Incineration
Contact: TY LONG
Telephone: (206) 763-8050
Mailing Address: 8025 10TH AVE S
SEATTLE, WA 98108 - 4405
County 99
Gepaid: WAD044036747
Tepaid: CAD009452657
Gen County: 99
Tsd County: San Mateo
Tons: .3000
Category: Liquids with pH <UN-> 2
Disposal Method: Treatment, Incineration
Contact: TY LONG
Telephone: (206) 763-8050
Mailing Address: 8025 10TH AVE S
SEATTLE, WA 98108 - 4405
County 99

The CA HAZNET database contains 57 additional records for this site.
Please contact your EDR Account Executive for more information.

I35 7755 E MARGINAL WAY 3-369 BLDG
NNE 7755 E MARGINAL WAY 3-369 BLDG
1/4-1/2 SEATTLE, WA 98108
1595 ft.
Higher Site 1 of 2 in cluster I

ERNS 99637188
N/A

I36 PLANT #2 7755 EAST MARGINAL WAY
NNE PLANT #2 7755 EAST MARGINAL WAY
1/4-1/2 SEATTLE, WA
1595 ft.
Higher Site 2 of 2 in cluster I

ERNS 8850501
N/A

37 1414 S CONCORD ST
South SEATTLE, WA
1/4-1/2
1643 ft.
Higher

SPILLS S105393646
N/A

WA SPILL:
Facility ID: 512275
Date Received: 07/18/2000
Business Name: LINEN SERVICE
Material Desc : CHEMICAL

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

S105393646

Medium: BUILDING/STRUCTURE
Material Qty: 40
Material Units: GALLON

J38
South
1/4-1/2
1941 ft.
Higher

TOM THURBER
1420 SOUTH HENDERSON ST
SEATTLE, WA 98108

Site 1 of 7 in cluster J

UST:

Facility ID: 101847
Install Date: 12/31/1964 0:00
Capacity: 111 to 1,100 Gallons
Status: Not reported
Tank Name: Not reported
Substance: NW
Compartment #: Not reported
Ecology Region: 1

UST U000925756
N/A

J39
South
1/4-1/2
1943 ft.
Higher

AMERICAN BATHTUB REFINISHERS INC
1412 S HENDERSON
SEATTLE, WA 98108

Site 2 of 7 in cluster J

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)

FINDS 1005127385
000009370156

J40
South
1/4-1/2
1943 ft.
Higher

AMERICAN BATHTUB REFINISHERS INC
1412 S HENDERSON
SEATTLE, WA 98108

Site 3 of 7 in cluster J

RCRIS:

Owner: AMERICAN BATHTUB REFINISHERS INC
EPA ID: WAH000010512
Contact: WILLIAM AND MIR BECK
(360) 232-1865

Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported

Violation Status: Violations exist

Regulation Violated: -141
Area of Violation: GENERATOR-ALL REQUIREMENTS (OVERSIGHT)
Date Violation Determined: 01/05/2000
Enforcement Action: WRITTEN INFORMAL
Enforcement Action Date: 01/05/2000
Penalty Type: Not reported

Regulation Violated: -145
Area of Violation: GENERATOR-ALL REQUIREMENTS (OVERSIGHT)
Date Violation Determined: 01/05/2000

RCRIS-SQG 1001969687
WAH000010512

Map ID
Direction
Distance
Distance (ft.)
Elevation

Site

MAP FINDINGS

Database(s)

EDR ID Number
EPA ID Number

AMERICAN BATHTUB REFINISHERS INC (Continued)

1001969687

Enforcement Action: WRITTEN INFORMAL
Enforcement Action Date: 01/05/2000
Penalty Type: Not reported

Regulation Violated: -060
Area of Violation: GENERATOR-ALL REQUIREMENTS (OVERSIGHT)
Date Violation Determined: 01/05/2000

Enforcement Action: WRITTEN INFORMAL
Enforcement Action Date: 01/05/2000
Penalty Type: Not reported

There are 3 violation record(s) reported at this site:

Evaluation	Area of Violation	Date of Compliance
Compliance Evaluation Inspection	GENERATOR-ALL REQUIREMENTS (OVERSIGHT)	01/05/200
	GENERATOR-ALL REQUIREMENTS (OVERSIGHT)	01/05/200
	GENERATOR-ALL REQUIREMENTS (OVERSIGHT)	01/05/200

J41
South
1/4-1/2
1944 ft.
Higher

ARTHUR J WARNER
9001 14 AVE SOUTH
SEATTLE, WA 98108

Site 4 of 7 in cluster J

UST U001126474
LUST N/A

LUST:

Facility ID:	10726	Ecology Region:	North Western
Release ID:	2970	Release Date:	1/16/1992 00:00:00
Release Status:	Cleanup Started	Status Date:	1/16/1992 00:00:00
Alternate Name:	WARNER'S AUTO REPAIR		
Affected Media:	Soil		

Facility ID:	10726	Ecology Region:	North Western
Release ID:	2970	Release Date:	1/16/1992 00:00:00
Release Status:	Reported Cleaned Up	Status Date:	6/1/1995 00:00:00
Alternate Name:	WARNER'S AUTO REPAIR		
Affected Media:	Soil		

UST:

Facility ID: 10726
Install Date: 12/31/1964 0:00
Capacity: 111 to 1,100 Gallons
Status: Not reported
Tank Name: KEROSENE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 10726
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: LEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Map ID
Direction
Distance
Distance (ft.)
Elevation

Site

MAP FINDINGS

Database(s)

EDR ID Number
EPA ID Number

ARTHUR J WARNER (Continued)

U001126474

Facility ID: 10726
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: LEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 10726
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: LEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

J42
South
1/4-1/2
1944 ft.
Higher

WARNERS AUTO REPAIR
9001 14TH AVE. S.
SEATTLE, WA 98108
Site 5 of 7 in cluster J

WA ICR 1001819828
N/A

WA ICR:
Date Ecology Received Report: 05/11/1992
Contaminants Found at Site: Petroleum products
Media Contaminated: Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Final cleanup report
Site Register Issue: 92-38
County Code: 17
Contact: Not reported
Report Title: Not reported

K43
NNE
1/4-1/2
1949 ft.
Higher

BOEING COMMERCIAL AIRPLANE PLANT II)
7755 E MARGINAL WY S PLANT II
SEATTLE, WA 98108

EMI S103531690
N/A

Site 1 of 13 in cluster K

WA AIR EMISSIONS:
Facility ID: Not reported
SO2 Chemical: Not reported
VOC Chemical: Not reported
PM10 Chemical: Not reported
Mailing Name: BOEING COMMERCIAL AIRPLANE (PLANT II)
PO BOX 3707 M/S 63-41
SEATTLE, 53
Year Of Info: Not reported
Mail Add Zip 2: Not reported
Point Num: Not reported
Tot Suspended Particulate Tons/Yr: Not reported
Local ID: Not reported
NO2 Chemical: Not reported
CO Chemical: Not reported
Point Desc: Not reported
Local ID: C
NO2 Chemical: 26

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

BOEING COMMERCIAL AIRPLANE PLANT II) (Continued)

S103531690

VOC Chemical: 9 CO Chemical: 6
PM10 Chemical: 1
Mailing Name: BOEING COMMERCIAL AIRPLANE (PLANT II)
PO BOX 3707 M/S 63-41
SEATTLE, 53 98124
Year Of Info: 96
Mail Add Zip 2: 2207
Point Num: Not reported Point Desc: Not reported
Tot Suspended Particulate Tons/Yr: Not reported

K44
NNE
1/4-1/2
1949 ft.
Higher

BOEING PLANT 2
7755 E MARGINAL WAY S
SEATTLE, WA 98108

CSCSL S101856267
N/A

Site 2 of 13 in cluster K

SHWS:

Facility ID: 2100
Responsible Unit: NW
Latitude: 47 32 10
Longitude: 122 18 48

Ecology Site Status relative to the MTCA cleanup process:
Independent Remedial Action

Independent Site Status - those sites undergoing an independent cleanup:
Independent Site Assessment of Interim Remedial Action Report received

WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):
1 - Greatest assessed risk to human health and to the environment

Affected Media: Surface Water

Media Status: C (Confirmed) - The presence of hazardous substances above MTCA cleanup levels has
been confirmed by laboratory analysis (or field determination in the case of petroleum
contamination)

Arsenic Code: Not reported
Base/Neutral/Acid Organics: Not reported
Halogenated Organic Compounds: Not reported
Horizontal Collection Method: 4
EPA Priority Pollutants - Metals and Cyanide: Not reported
Metals - Other non-priority pollutant metals: Not reported
Polychlorinated biPhenyls (PCBs): Not reported
Pesticides: Not reported
Petroleum Products: Confirmed above MTCA cleanup levels
Phenolic Compounds: Not reported
Non-Halogenated Solvents: Not reported
Dioxin: Not reported
Polynuclear Aromatic Hydrocarbons (PAH): Not reported
Reactive Wastes: Not reported
Corrosive Wastes: Not reported
Radioactive Wastes: Not reported
Asbestos: Not reported
Conventional Contaminants, Organic: Not reported
Conventional Contaminants, Inorganic: Not reported

Facility ID: 2100
Responsible Unit: NW
Latitude: 47 32 10
Longitude: 122 18 48

Ecology Site Status relative to the MTCA cleanup process:
Independent Remedial Action

Independent Site Status - those sites undergoing an independent cleanup:
Independent Site Assessment of Interim Remedial Action Report received

Map ID
Direction
Distance
Distance (ft.)
Elevation

Site

MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

BOEING PLANT 2 (Continued)

S101856267

WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):

1 - Greatest assessed risk to human health and to the environment

Affected Media: Air

Media Status: C (Confirmed) - The presence of hazardous substances above MTCA cleanup levels has been confirmed by laboratory analysis (or field determination in the case of petroleum contamination)

Arsenic Code: Not reported

Base/Neutral/Acid Organics: Not reported

Halogenated Organic Compounds: Confirmed above MTCA cleanup levels

Horizontal Collection Method: 4

EPA Priority Pollutants - Metals and Cyanide: Suspected to be present

Metals - Other non-priority pollutant medals: Not reported

Polychlorinated biPhenyls (PCBs): Not reported

Pesticides: Not reported

Petroleum Products: Confirmed above MTCA cleanup levels

Phenolic Compounds: Not reported

Non-Halogenated Solvents: Not reported

Dioxin: Not reported

Polynuclear Aromatic Hydrocarbons (PAH): Confirmed above MTCA cleanup levels

Reactive Wastes: Not reported

Corrosive Wastes: Not reported

Radioactive Wastes: Not reported

Asbestos: Not reported

Conventional Contaminants, Organic: Not reported

Conventional Contaminants, Inorganic: Not reported

Facility ID: 2100

Responsible Unit: NW

Latitude: 47 32 10

Longitude: 122 18 48

Ecology Site Status relative to the MTCA cleanup process:

Independent Remedial Action

Independent Site Status - those sites undergoing an independent cleanup:

Independent Site Assessment of Interim Remedial Action Report received

WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):

1 - Greatest assessed risk to human health and to the environment

Affected Media: Ground Water

Media Status: C (Confirmed) - The presence of hazardous substances above MTCA cleanup levels has been confirmed by laboratory analysis (or field determination in the case of petroleum contamination)

Arsenic Code: Not reported

Base/Neutral/Acid Organics: Not reported

Halogenated Organic Compounds: Confirmed above MTCA cleanup levels

Horizontal Collection Method: 4

EPA Priority Pollutants - Metals and Cyanide: Confirmed above MTCA cleanup levels

Metals - Other non-priority pollutant medals: Not reported

Polychlorinated biPhenyls (PCBs): Confirmed above MTCA cleanup levels

Pesticides: Not reported

Petroleum Products: Confirmed above MTCA cleanup levels

Phenolic Compounds: Not reported

Non-Halogenated Solvents: Confirmed above MTCA cleanup levels

Dioxin: Not reported

Polynuclear Aromatic Hydrocarbons (PAH): Confirmed above MTCA cleanup levels

Reactive Wastes: Not reported

Corrosive Wastes: Not reported

Radioactive Wastes: Not reported

Asbestos: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

EDR ID Number
EPA ID Number
Database(s)

BOEING PLANT 2 (Continued)

S101856267

Conventional Contaminants, Organic: Not reported
Conventional Contaminants, Inorganic: Not reported

Facility ID: 2100
Responsible Unit: NW
Latitude: 47 32 10
Longitude: 122 18 48

Ecology Site Status relative to the MTCA cleanup process:
Independent Remedial Action

Independent Site Status - those sites undergoing an independent cleanup:
Independent Site Assessment of Interim Remedial Action Report received

WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):
1 - Greatest assessed risk to human health and to the environment

Affected Media: Soil

Media Status: C (Confirmed) - The presence of hazardous substances above MTCA cleanup levels has been confirmed by laboratory analysis (or field determination in the case of petroleum contamination)

Arsenic Code: Not reported

Base/Neutral/Acid Organics: Not reported
Halogenated Organic Compounds: Confirmed above MTCA cleanup levels
Horizontal Collection Method: 4
EPA Priority Pollutants - Metals and Cyanide: Confirmed above MTCA cleanup levels
Metals - Other non-priority pollutant metals: Not reported
Polychlorinated biPhenyls (PCBs): Confirmed above MTCA cleanup levels
Pesticides: Not reported
Petroleum Products: Confirmed above MTCA cleanup levels
Phenolic Compounds: Not reported
Non-Halogenated Solvents: Confirmed above MTCA cleanup levels
Dioxin: Not reported
Polynuclear Aromatic Hydrocarbons (PAH): Confirmed above MTCA cleanup levels
Reactive Wastes: Not reported
Corrosive Wastes: Not reported
Radioactive Wastes: Not reported
Asbestos: Not reported
Conventional Contaminants, Organic: Not reported
Conventional Contaminants, Inorganic: Not reported

Facility ID: 2100
Responsible Unit: NW
Latitude: 47 32 10
Longitude: 122 18 48

Ecology Site Status relative to the MTCA cleanup process:
Independent Remedial Action

Independent Site Status - those sites undergoing an independent cleanup:
Independent Site Assessment of Interim Remedial Action Report received

WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):
1 - Greatest assessed risk to human health and to the environment

Affected Media: Sediments

Media Status: S (Suspected) - Due to preliminary investigations or the nature of business operations or manufacturing processes, certain contaminants are suspected to be present at the site

Arsenic Code: Not reported

Base/Neutral/Acid Organics: Not reported
Halogenated Organic Compounds: Suspected to be present
Horizontal Collection Method: 4
EPA Priority Pollutants - Metals and Cyanide: Suspected to be present
Metals - Other non-priority pollutant metals: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

BOEING PLANT 2 (Continued)

S101856267

Polychlorinated biPhenyls (PCBs):	Suspected to be present
Pesticides:	Not reported
Petroleum Products:	Suspected to be present
Phenolic Compounds:	Not reported
Non-Halogenated Solvents:	Suspected to be present
Dioxin:	Not reported
Polynuclear Aromatic Hydrocarbons (PAH):	Suspected to be present
Reactive Wastes:	Not reported
Corrosive Wastes:	Not reported
Radioactive Wastes:	Not reported
Asbestos:	Not reported
Conventional Contaminants, Organic:	Not reported
Conventional Contaminants, Inorganic:	Not reported

K45
NNE
1/4-1/2
1949 ft.
Higher

BOEING AEROSPACE CO PLANT 2
7755 E MARGINAL WAY S
SEATTLE, WA 98108

FTTS 1004624543
N/A

Site 3 of 13 in cluster K

FTTS:

Case Number:	Not reported
Docket Number:	1090-06-10-325
Complaint Issued:	07/10/90
Complaint Closed:	10/22/90
Abatement Amount:	10/22/90
Proposed Penalty:	85000
Final Assessment:	72250
Final Order Date:	0
Close Date:	10/22/90
Violation:	EPCRA, Nonreporting/Failure to RPT to EPA

FTTS Insp:

Region:	10
Inspected Date:	01/18/90
Insp Number:	01/18/90
Violation occurred:	Yes
Inspector:	DAVIS
Investigation Type:	EPCRA, Enforcement, SEE Conducted
Facility Function:	Manufacturer
Investig Reason:	Neutral Scheme, Region
Legislation Code:	EPCRA

K46
NNE
1/4-1/2
1949 ft.
Higher

7755 EAST MARGINAL WAY
7755 EAST MARGINAL WAY
SEATTLE, WA

ERNS 8853633
N/A

Site 4 of 13 in cluster K

K47
NNE
1/4-1/2
1949 ft.
Higher

BOEING COMMERCIAL AIRPLANE GRP-PLTII
7755 E MARGINAL WY S PLANT II
SEATTLE, WA 98108

EMI S102456356
N/A

Site 5 of 13 in cluster K

WA AIR EMISSIONS:

Facility ID:	0156
SO2 Chemical:	0.1105

Local ID:	C
NO2 Chemical:	25.8320

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

BOEING COMMERCIAL AIRPLANE GRP-PLTII (Continued)

S102456356

VOC Chemical: 9.6370 CO Chemical: 6.4580
PM10 Chemical: 1.1450
Mailing Name: BOEING COMMERCIAL AIRPLANE GROUP-PLT II
7755 E MARGINAL WY S
SEATTLE, 53 98108
Year Of Info: Not reported
Mail Add Zip 2: Not reported
Point Num: Not reported Point Desc: Not reported
Tot Suspended Particulate Tons/Yr: Not reported

K48 7755 E MARGINAL WAY
NNE 7755 E MARGINAL WAY
1/4-1/2 SEATTLE, WA
1949 ft.
Higher Site 6 of 13 in cluster K

ERNS 90160682
N/A

K49 BOEING PLANT 2
NNE 7755 E MARGINAL WAY S
1/4-1/2 SEATTLE, WA 98108
1949 ft.
Higher Site 7 of 13 in cluster K

FINDS 1000257078
RCRIS-LQG 98108BNGRS77
TRIS
RCRIS-TSD
CORRACTS
CERC-NFRAP
WA ICR
CA HAZNET

CERCLIS-NFRAP Classification Data:

Site Incident Category: Not reported
Non NPL Code: NFRAP
Ownership Status: Other

Federal Facility: Not a Federal Facility

NPL Status: Not on the NPL

CERCLIS-NFRAP Assessment History:

Assessment: DISCOVERY
Assessment: PRELIMINARY ASSESSMENT
Assessment: PRELIMINARY ASSESSMENT

Completed: 04/01/1980

Completed: 05/06/1985

Completed: 07/12/1988

CERCLIS-NFRAP Alias Name(s):

BOEING COMPANY COORPORATE
BOEING AEROSPACE CO - PLT #2
DUWAMISH RIV ADJACENT TO BOEING PLT #2
BOEING PLT II - S YARD

CORRACTS Data:

EPA Id: WAD009256819
Region: 10
State: Not reported
Area Name: AOC 2-10.3A SOUTH TCE DEGREASER
Original Scheduled Date: 1/13/2003
New Scheduled Date: Not reported
Actual Date: / /
Corrective Action: CA650 - Stabilization Construction Completed

EPA Id: WAD009256819
Region: 10
State: Not reported
Area Name: AOC 2-10.4A NORTH TCE DEGREASER
Original Scheduled Date: 1/13/2003
New Scheduled Date: Not reported
Actual Date: / /
Corrective Action: CA650 - Stabilization Construction Completed

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

BOEING PLANT 2 (Continued)

Database(s)

EDR ID Number
EPA ID Number

1000257078

EPA Id: WAD009256819
Region: 10
State: Not reported
Area Name: FACILITY-WIDE
Original Scheduled Date: Not reported
New Scheduled Date: Not reported
Actual Date: 09/22/1998
Corrective Action: CA200 - RFI Approved

EPA Id: WAD009256819
Region: 10
State: Not reported
Area Name: FACILITY-WIDE
Original Scheduled Date: Not reported
New Scheduled Date: Not reported
Actual Date: 08/05/1992
Corrective Action: CA225YE - Stabilization Measures Evaluation, This facility is amenable to stabilization activity based on the status of corrective action work at the facility, technical factors, the degree of risk, timing considerations and administrative considerations

EPA Id: WAD009256819
Region: 10
State: Not reported
Area Name: FACILITY-WIDE
Original Scheduled Date: Not reported
New Scheduled Date: Not reported
Actual Date: 12/07/1992
Corrective Action: CA225IN - Stabilization Measures Evaluation, This facility is not , amenable to stabilization activity because of, a lack of technical data. An evaluation has been completed, but further data is necessary to determine stabilization measures, feasibility or appropriateness. This status should be changed when data becomes available

The CORRACTS database contains 35 additional records for this site.
Please contact your EDR Account Executive for more information.

RCRIS Corrective Action Summary:

Event: Date For Remedy Selection (CM Imposed)
Event Date: Not reported

Event: Corrective Measures Design Approved
Event Date: Not reported

Event: Stabilization Construction Completed
Event Date: Not reported

Event: Stabilization Construction Completed
Event Date: Not reported

Event: Stabilization Construction Completed
Event Date: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

BOEING PLANT 2 (Continued)

EDR ID Number
EPA ID Number

Database(s)

1000257078

Event:	Stabilization Construction Completed
Event Date:	Not reported
Event:	Stabilization Construction Completed
Event Date:	Not reported
Event:	Stabilization Construction Completed
Event Date:	Not reported
Event:	Stabilization Construction Completed
Event Date:	Not reported
Event:	Stabilization Construction Completed
Event Date:	08/23/2000
Event:	Stabilization Construction Completed
Event Date:	08/23/2000
Event:	Stabilization Measures Implemented, Primary measure is source removal and/or treatment (e.g., soil or waste excavation, in-situ soil treatment, off-site treatment).
Event Date:	07/30/1999
Event:	CMS Approved
Event Date:	07/13/1999
Event:	Stabilization Measures Implemented, Primary measure is source removal and/or treatment (e.g., soil or waste excavation, in-situ soil treatment, off-site treatment).
Event Date:	05/05/1999
Event:	Current Human Exposures under Control, Current human exposures are NOT under control.
Event Date:	03/18/1999
Event:	Igration of Contaminated Groundwater under Control, Unacceptable migration of contaminated groundwater is observed or expected.
Event Date:	03/18/1999
Event:	Stabilization Measures Implemented, Primary measure is source removal and/or treatment (e.g., soil or waste excavation, in-situ soil treatment, off-site treatment).
Event Date:	02/08/1999
Event:	CMS Workplan Approved
Event Date:	11/17/1998
Event:	RFI Approved
Event Date:	09/22/1998
Event:	CA Prioritization, Facility or area was assigned a high corrective action priority.
Event Date:	08/10/1998
Event:	Igration of Contaminated Groundwater under Control, More information is needed to make a determination.
Event Date:	08/10/1998

Map ID
Direction
Distance
Distance (ft.)
Elevation

Site

MAP FINDINGS

Database(s)

EDR ID Number
EPA ID Number

BOEING PLANT 2 (Continued)

1000257078

Event: Current Human Exposures under Control, More information is needed to make a determination.
Event Date: 08/10/1998

Event: Stabilization Measures Implemented, Primary measure is source removal and/or treatment (e.g., soil or waste excavation, in-situ soil treatment, off-site treatment).
Event Date: 06/22/1998

Event: Stabilization Measures Implemented, Primary measure is source removal and/or treatment (e.g., soil or waste excavation, in-situ soil treatment, off-site treatment).
Event Date: 03/04/1998

Event: CA Prioritization, Facility or area was assigned a high corrective action priority.
Event Date: 09/26/1997

Event: Stabilization Construction Completed
Event Date: 06/20/1997

Event: Stabilization Measures Implemented, Primary measure is source removal and/or treatment (e.g., soil or waste excavation, in-situ soil treatment, off-site treatment).
Event Date: 10/01/1996

Event: Stabilization Measures Evaluation, This facility is amenable to stabilization activity based on the status of corrective action work at the facility, technical factors, the degree of risk, timing considerations and administrative considerations.
Event Date: 09/26/1996

Event: CA Prioritization, Facility or area was assigned a high corrective action priority.
Event Date: 08/06/1996

Event: Stabilization Measures Evaluation, This facility is amenable to stabilization activity based on the status of corrective action work at the facility, technical factors, the degree of risk, timing considerations and administrative considerations.
Event Date: 08/06/1996

Event: RFI Workplan Approved
Event Date: 05/03/1995

Event: RFI Workplan Approved
Event Date: 05/03/1995

Event: RFI Imposition, Focused data collection required for stabilization evaluation.
Event Date: 01/18/1994

Event: Stabilization Measures Evaluation, This facility is not amenable to stabilization activity because of a lack of technical data. An evaluation has been completed, but further data is necessary to determine stabilization measures, feasibility or appropriateness. This status should be changed when data becomes available.
Event Date: 12/07/1992

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

BOEING PLANT 2 (Continued)

1000257078

Event: RFA Determination Of Need For An RFI, RFI is Necessary;
Event Date: 11/10/1992
Event: CA Prioritization, Facility or area was assigned a high corrective action priority.
Event Date: 09/09/1992
Event: Stabilization Measures Evaluation, This facility is amenable to stabilization activity based on the status of corrective action work at the facility, technical factors, the degree of risk, timing considerations and administrative considerations.
Event Date: 08/05/1992

RCRIS:

Owner: BOEING CO
(425) 865-2400
EPA ID: WAD009256819
Contact: LOUIS BABICH III
(425) 234-1766
Rank Status: 2
Rank Date: 10/01/1995
Classification: N, Large Quantity Generator, TSDF
Used Oil Recyc: No
TSDF Activities: Not reported

BIENNIAL REPORTS:

Last Biennial Reporting Year: 1999

<u>Waste</u>	<u>Quantity (Lbs)</u>	<u>Waste</u>	<u>Quantity (Lbs)</u>
D001	15030.55	D002	2610.00
D004	23860.00	D005	18203.22
D006	117530.37	D007	391238.87
D008	148111.22	D009	26770.00
D010	18533.22	D011	2000.00
D018	660.00	D035	110.00
F001	385.00	F002	335268.54
F003	320115.54	F005	320115.54
U228	6858663.90		

Violation Status: Violations exist

Regulation Violated: 200(1)(b), 630(5)(b)
Area of Violation: GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined: 06/07/1993
Enforcement Action: WRITTEN INFORMAL
Enforcement Action Date: 06/07/1993
Penalty Type: Not reported
Regulation Violated: 400 (3)(a)(i)
Area of Violation: GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined: 06/07/1993
Enforcement Action: WRITTEN INFORMAL
Enforcement Action Date: 06/07/1993
Penalty Type: Not reported
Regulation Violated: -200(2)(C)
Area of Violation: GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined: 05/17/1991
Enforcement Action: WRITTEN INFORMAL

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

BOEING PLANT 2 (Continued)

Database(s)
EDR ID Number
EPA ID Number

1000257078

Enforcement Action Date:	03/08/1985
Penalty Type:	Not reported
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	07/10/1991
Penalty Type:	Not reported
Regulation Violated:	-300 (5)
Area of Violation:	TSD-GENERAL STANDARDS
Date Violation Determined:	05/17/1991
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	09/23/1987
Penalty Type:	Not reported
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	07/10/1991
Penalty Type:	Not reported
Regulation Violated:	-370(2)(A)
Area of Violation:	TSD-MANIFEST REQUIREMENTS
Date Violation Determined:	05/17/1991
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	07/10/1991
Penalty Type:	Not reported
Regulation Violated:	-630(5)(A)
Area of Violation:	TSD-CONTAINERS REQUIREMENTS
Date Violation Determined:	05/17/1991
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	07/10/1991
Penalty Type:	Not reported
Regulation Violated:	-400
Area of Violation:	TSD-TANKS REQUIREMENTS
Date Violation Determined:	05/17/1991
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	07/10/1991
Penalty Type:	Not reported
Regulation Violated:	Not reported
Area of Violation:	TSD-FINANCIAL RESPONSIBILITY REQUIREMENTS
Date Violation Determined:	03/08/1985
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	03/08/1985
Penalty Type:	Not reported
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	07/10/1991
Penalty Type:	Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

EDR ID Number
EPA ID Number
Database(s)

BOEING PLANT 2 (Continued)

1000257078

There are 8 violation record(s) reported at this site:

<u>Evaluation</u>	<u>Area of Violation</u>	<u>Date of Compliance</u>
Compliance Evaluation Inspection	GENERATOR-GENERAL REQUIREMENTS	08/02/199
	GENERATOR-GENERAL REQUIREMENTS	08/02/199
Compliance Evaluation Inspection	GENERATOR-GENERAL REQUIREMENTS	08/02/199
	GENERATOR-GENERAL REQUIREMENTS	08/02/199
Compliance Evaluation Inspection	GENERATOR-GENERAL REQUIREMENTS	09/23/199
	TSD-GENERAL STANDARDS	09/23/199
	TSD-MANIFEST REQUIREMENTS	09/23/199
	TSD-TANKS REQUIREMENTS	09/23/199
	TSD-CONTAINERS REQUIREMENTS	09/23/199
Compliance Evaluation Inspection	TSD-GENERAL STANDARDS	09/23/199
Financial Record Review	TSD-FINANCIAL RESPONSIBILITY REQUIREMENTS	04/08/198

FINDS:

Other Pertinent Environmental Activity Identified at Site:

AIRS Facility System (AIRS/AFS)
Biennial Reporting System (BRS)
Enforcement Docket System (DOCKET)
Facility Registry System (FRS)
National Compliance Database (NCDB)
National Emissions Trends (NET)
National Toxics Inventory (NTI)
Resource Conservation and Recovery Act Information system (RCRAINFO)
Toxic Chemical Release Inventory System (TRIS)

WA ICR:

Date Ecology Received Report:	05/17/1993
Contaminants Found at Site:	Halogenated Solvents Total petroleum hydrocarbons Metals
Media Contaminated:	Groundwater, Soil
Cause of Contamination:	Not reported
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	92-51
County Code:	17
Contact:	Not reported
Report Title:	Not reported
Date Ecology Received Report:	12/11/1992
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Soil
Cause of Contamination:	Tank
Region:	North Western
Type of Report Ecology Received:	Final cleanup report
Site Register Issue:	92-40
County Code:	17
Contact:	Not reported
Report Title:	Not reported
Date Ecology Received Report:	05/15/1991
Contaminants Found at Site:	Halogenated organic compounds Metals PCB's

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

BOEING PLANT 2 (Continued)

1000257078

Media Contaminated: Petroleum products
Cause of Contamination: Non-haologenated solvents
Region: Soil, Groundwater, Surface water
Type of Report Ecology Received: Not reported
Site Register Issue: North Western
County Code: 91-30
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 05/17/1993
Contaminants Found at Site: Solvents
Metals
Total petroleum hydrocarbons
Not reported

Media Contaminated: Groundwater, Soil
Cause of Contamination: Not reported
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 92-51
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 03/30/1992
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 92-21
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 06/15/1992
Contaminants Found at Site: Halogenated organic compounds
Total petroleum hydrocarbons
Media Contaminated: Groundwater, Soil
Cause of Contamination: Not reported
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 92-27
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: / /
Contaminants Found at Site: Metals
Non-haologenated solvents
Polynuclear aromatic hydrocarbons
Media Contaminated: Groundwater
Cause of Contamination: Not reported
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 92-27

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

BOEING PLANT 2 (Continued)

1000257078

County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 05/17/1993
Contaminants Found at Site: Metals
PCB's
Solvents

Media Contaminated: Groundwater, Soil
Cause of Contamination: Not reported
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 92-51
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 05/17/1993
Contaminants Found at Site: Total petroleum hydrocarbons
Solvents
Metals
PCB's

Media Contaminated: Groundwater, Soil
Cause of Contamination: Not reported
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 92-51
County Code: 17
Contact: Not reported
Report Title: Not reported

HAZNET:

Gepaid: WAD009256819
Tepaid: CAD050806850
Gen County: 99
Tsd County: Los Angeles
Tons: 3.7530
Category: Liquids with pH <UN-> 2 with metals
Disposal Method: Treatment, Tank
Contact: THE BOEING COMPANY
Telephone: (206) 655-7431
Mailing Address: PO BOX 3707 M/S 63-41
SEATTLE, WA 98124 - 2207
County: 99

Gepaid: WAD009256819
Tepaid: CAD009452657
Gen County: 99
Tsd County: San Mateo
Tons: .1950
Category: Liquids with mercury > 20 mg/l
Disposal Method: Recycler
Contact: THE BOEING COMPANY
Telephone: (206) 655-7431
Mailing Address: PO BOX 3707 M/S 63-41
SEATTLE, WA 98124 - 2207
County: 99

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

BOEING PLANT 2 (Continued)

EDR ID Number
EPA ID Number

Database(s)

1000257078

Gepaid: WAD009256819
Tepaid: CAD009452657
Gen County: 99
Tsd County: San Mateo
Tons: .2590
Category: Liquids with chromium (VI) > 500 mg/l
Disposal Method: Recycler
Contact: THE BOEING COMPANY
Telephone: (206) 655-7431
Mailing Address: PO BOX 3707 M/S 63-41
SEATTLE, WA 98124 - 2207
County 99
Gepaid: WAD009256819
Tepaid: CAD009452657
Gen County: 99
Tsd County: San Mateo
Tons: .2090
Category: Off-specification, aged, or surplus inorganics
Disposal Method: Recycler
Contact: THE BOEING COMPANY
Telephone: (206) 655-7431
Mailing Address: PO BOX 3707 M/S 63-41
SEATTLE, WA 98124 - 2207
County 99
Gepaid: WAD009256819
Tepaid: CAD009452657
Gen County: 99
Tsd County: San Mateo
Tons: 5.6120
Category: Other organic solids
Disposal Method: Recycler
Contact: THE BOEING COMPANY
Telephone: (206) 655-7431
Mailing Address: PO BOX 3707 M/S 63-41
SEATTLE, WA 98124 - 2207
County 99

The CA HAZNET database contains 102 additional records for this site.
Please contact your EDR Account Executive for more information.

K50 7755 EAST MARGINAL WAY SOUTH
NNE 7755 EAST MARGINAL WAY SOUTH
1/4-1/2 SEATTLE, WA 98124
1949 ft.
Higher Site 8 of 13 in cluster K

ERNS 92264261
N/A

K51 BOEING COMMERCIAL AIRPLANE NBF)
NNE 7755 E MARGINAL WY S 2-25 BLDG
1/4-1/2 SEATTLE, WA 98108
1949 ft.
Higher Site 9 of 13 in cluster K

EMI S103531689
N/A

WA AIR EMISSIONS:

Facility ID: Not reported
SO2 Chemical: Not reported
VOC Chemical: Not reported

Local ID: Not reported
NO2 Chemical: Not reported
CO Chemical: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

BOEING COMMERCIAL AIRPLANE NBF) (Continued)

EDR ID Number
EPA ID Number

Database(s)

S103531689

PM10 Chemical: Not reported
Mailing Name: BOEING COMMERCIAL AIRPLANE (NBF)
PO BOX 3707 M/S 63-41
SEATTLE, 53
Year Of Info: Not reported
Mail Add Zip 2: Not reported
Point Num: Not reported Point Desc: Not reported
Tot Suspended Particulate Tons/Yr: Not reported

Facility ID: 0146 Local ID: C
SO2 Chemical: 1 NO2 Chemical: 11
VOC Chemical: 29 CO Chemical: 3
PM10 Chemical: 0

Mailing Name: BOEING COMMERCIAL AIRPLANE (NBF)
PO BOX 3707 M/S 63-41
SEATTLE, 53 98124
Year Of Info: 96
Mail Add Zip 2: 2207
Point Num: Not reported Point Desc: Not reported
Tot Suspended Particulate Tons/Yr: Not reported

K52
NNE
1/4-1/2
1949 ft.
Higher

7755 EAST MARGINAL WAY S NW AREA OUTSIDE BLDG 266 PARKING LO
7755 EAST MARGINAL WAY S NW AREA OUTSIDE BLDG 266 PARKING LO
SEATTLE, WA

ERNS 96482859
N/A

Site 10 of 13 in cluster K

K53
NNE
1/4-1/2
1949 ft.
Higher

BOEING CO. PLANT 2 - BLDG. 2-66
7755 E. MARGINAL WAY S.
SEATTLE, WA 98108

WA ICR S104486100
N/A

Site 11 of 13 in cluster K

WA ICR:
Date Ecology Received Report: 01/23/1991
Contaminants Found at Site: Metals
Media Contaminated: Soil
Cause of Contamination: Not reported
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 91-24
County Code: 17
Contact: Not reported
Report Title: Not reported

K54
NNE
1/4-1/2
1949 ft.
Higher

BOEING
7755 E MARGINAL WAY S
SEATTLE, WA 98108

FTTS 1004624540
N/A

Site 12 of 13 in cluster K

FTTS Insp:
Region: 10
Inspected Date: 09/28/90
Insp Number: 09/28/90
Violation occurred: Not reported
Inspector: MILTON

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

BOEING (Continued)

EDR ID Number
EPA ID Number

Database(s)

1004624540

Investigation Type: Section 8 Confidential Inspections
Facility Function: Manufacturer
Investig Reason: Neutral Scheme, Region
Legislation Code: TSCA

K55
NNE
1/4-1/2
1949 ft.
Higher

PLANT II
7755 E MARGINAL WAY S
SEATTLE, WA 98108

UST U003025356
LUST N/A

Site 13 of 13 in cluster K

LUST:

Facility ID: 10412 Ecology Region: North Western
Release ID: 1719 Release Date: 2/2/1990 00:00:00
Release Status: Cleanup Started Status Date: 6/1/1995 00:00:00
Alternate Name: BOEING PLANT 2
Affected Media: Soil

Facility ID: 10412 Ecology Region: North Western
Release ID: 2667 Release Date: 9/27/1991 00:00:00
Release Status: Cleanup Started Status Date: 6/1/1995 00:00:00
Alternate Name: BOEING PLANT 2 BLDG 2-01 (EXEMPT)
Affected Media: Soil

Facility ID: 10412 Ecology Region: North Western
Release ID: 4073 Release Date: 12/11/1992 00:00:00
Release Status: Cleanup Started Status Date: 12/11/1992 00:00:00
Alternate Name: BOEING PLANT 2 BLDG 2-08
Affected Media: Soil

Facility ID: 10412 Ecology Region: North Western
Release ID: 4073 Release Date: 12/11/1992 00:00:00
Release Status: Reported Cleaned Up Status Date: 6/1/1995 00:00:00
Alternate Name: BOEING PLANT 2 BLDG 2-08
Affected Media: Soil

UST:

Facility ID: 10412
Install Date: 7/16/1986 0:00
Capacity: 10,000 TO 19,999 GALLONS
Status: Not reported
Tank Name: DIESEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 10412
Install Date: 12/31/1964 0:00
Capacity: 111 to 1,100 Gallons
Status: Not reported
Tank Name: USED OIL/WASTE OIL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

PLANT II (Continued)

U003025356

Facility ID: 10412
Install Date: 12/31/1964 0:00
Capacity: 111 TO 1,000 GALLONS
Status: Not reported
Tank Name: KEROSENE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 10412
Install Date: 12/31/1964 0:00
Capacity: 1,101 TO 2,000 GALLONS
Status: Not reported
Tank Name: HAZARDOUS SUBSTANCE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 10412
Install Date: 12/31/1964 0:00
Capacity: 2,001 TO 4,999 GALLONS
Status: Not reported
Tank Name: UNKNOWN
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 10412
Install Date: 12/31/1964 0:00
Capacity: 1,101 TO 2,000 GALLONS
Status: Not reported
Tank Name: DIESEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 10412
Install Date: 12/31/1964 0:00
Capacity: 111 to 1,100 Gallons
Status: Not reported
Tank Name: USED OIL/WASTE OIL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 10412
Install Date: 12/31/1964 0:00
Capacity: 2,001 TO 4,999 GALLONS
Status: Not reported
Tank Name: USED OIL/WASTE OIL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

PLANT II (Continued)

EDR ID Number
EPA ID Number

Database(s)

U003025356

Facility ID: 10412
Install Date: 12/31/1964 0:00
Capacity: 20,000 TO 29,999 GALLONS
Status: Not reported
Tank Name: USED OIL/WASTE OIL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 10412
Install Date: 12/31/1964 0:00
Capacity: 1,101 TO 2,000 GALLONS
Status: Not reported
Tank Name: USED OIL/WASTE OIL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 10412
Install Date: 12/31/1964 0:00
Capacity: 2,001 TO 4,999 GALLONS
Status: Not reported
Tank Name: USED OIL/WASTE OIL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 10412
Install Date: 7/16/1986 0:00
Capacity: 10,000 TO 19,999 GALLONS
Status: Not reported
Tank Name: UNLEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 10412
Install Date: 9/29/1991 0:00
Capacity: 111 to 1,100 Gallons
Status: Not reported
Tank Name: HAZARDOUS SUBSTANCE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 10412
Install Date: 5/26/1988 0:00
Capacity: 111 to 1,100 Gallons
Status: Not reported
Tank Name: DIESEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

PLANT II (Continued)

EDR ID Number
EPA ID Number

Database(s)

U003025356

Facility ID: 10412
Install Date: 1/1/1951 0:00
Capacity: 111 to 1,100 Gallons
Status: Not reported
Tank Name: LEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 10412
Install Date: 12/31/1964 0:00
Capacity: 20,000 TO 29,999 GALLONS
Status: Not reported
Tank Name: HEATING FUEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 10412
Install Date: 12/31/1964 0:00
Capacity: 10,000 TO 19,999 GALLONS
Status: Not reported
Tank Name: HEATING FUEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 10412
Install Date: 12/31/1964 0:00
Capacity: 20,000 TO 29,999 GALLONS
Status: Not reported
Tank Name: HEATING FUEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

J56
South
1/4-1/2
1964 ft.
Higher

BUS AND AIR PARCEL SERVICE INCORPORATE
9004 14TH SOUTH
SEATTLE, WA 98108

UST U003027355
LUST N/A

Site 6 of 7 in cluster J

LUST:

Facility ID:	5423	Ecology Region:	North Western
Release ID:	2040	Release Date:	10/18/1990 00:00:00
Release Status:	Cleanup Started	Status Date:	6/1/1995 00:00:00
Alternate Name:	DBA & AIRBUS		
Affected Media:	Soil		

Facility ID:	5423	Ecology Region:	North Western
Release ID:	2040	Release Date:	10/18/1990 00:00:00
Release Status:	Reported Cleaned Up	Status Date:	4/25/2000 00:00:00
Alternate Name:	DBA & AIRBUS		
Affected Media:	Soil		

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

BUS AND AIR PARCEL SERVICE INCORPORATE (Continued)

EDR ID Number
EPA ID Number

Database(s)

U003027355

UST:

Facility ID: 5423
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: UNLEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 5423
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: UNLEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 5423
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: UNLEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 5423
Install Date: 12/31/1964 0:00
Capacity: 111 to 1,100 Gallons
Status: Not reported
Tank Name: USED OIL/WASTE OIL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

J57
South
1/4-1/2
2012 ft.
Higher

**PETROCARD SYSTEMS, INC.
9014 14TH AVE S
SEATTLE, WA 98108**

Site 7 of 7 in cluster J

UST U003294895
N/A

UST:

Facility ID: 436032
Install Date: 10/15/1997 0:00
Capacity: Not reported
Status: Not reported
Tank Name: DIESEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

PETROCARD SYSTEMS, INC. (Continued)

EDR ID Number
EPA ID Number

Database(s)

U003294895

Facility ID: 436032
Install Date: 10/15/1997 0:00
Capacity: Not reported
Status: Not reported
Tank Name: UNLEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 436032
Install Date: 10/15/1997 0:00
Capacity: Not reported
Status: Not reported
Tank Name: UNLEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 2

58
WSW
1/4-1/2
2213 ft.
Higher

SEATTLE FIRE STATION 26
800 S CLOVERDALE ST
SEATTLE, WA 98108

UST U000592346
N/A

UST:

Facility ID: 7900
Install Date: 1/1/1982 0:00
Capacity: 111 to 1,100 Gallons
Status: Not reported
Tank Name: DIESEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

L59
North
1/4-1/2
2217 ft.
Lower

7700 EAST MARGINAL WAY S
7700 EAST MARGINAL WAY S
SEATTLE, WA
Site 1 of 3 in cluster L

ERNS 92282971
N/A

L60
North
1/4-1/2
2217 ft.
Lower

7700 E. MARGINAL WAY SOUTH
7700 E. MARGINAL WAY SOUTH
SEATTLE, WA
Site 2 of 3 in cluster L

ERNS 90184798
N/A

L61
North
1/4-1/2
2217 ft.
Lower

DUWAMISH RIV ADJ TO BOEING PLT
7700 E MARGINAL WAY S
SEATTLE, WA 98108
Site 3 of 3 in cluster L

FINDS 1005180788
000010127830

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DUWAMISH RIV ADJ TO BOEING PLT (Continued)

1005180788

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Enforcement Docket System (DOCKET)

62
South
1/4-1/2
2240 ft.
Higher

HEARTWOOD INC
1414 S DIRECTOR ST
SEATTLE, WA 98108

RCRIS-SQG 1000370350
FINDS WAD982656431

RCRIS:

Owner: HOWARD EUSTIS
(206) 767-9787
EPA ID: WAD982656431
Contact: DAVID BELISLE
(206) 767-9787

Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

M63
South
1/4-1/2
2341 ft.
Higher

SBC TECHNOLOGIES INC
9100 15TH PL S BLDG G STE A
SEATTLE, WA 98108

RCRIS-SQG 1000133528
FINDS WAD085808038

Site 1 of 3 in cluster M

RCRIS:

Owner: SBC TECHNOLOGIES INC
(360) 555-1212
EPA ID: WAD085808038
Contact: WAYNE BORTZ
(206) 767-3040

Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

M64
South
1/4-1/2
2341 ft.
Higher

UNITOR SHIPS SVC INC 15TH PL
9100 15TH PL S STE A
SEATTLE, WA 98108

RCRIS-SQG 1001226367
WAH000003384

Site 2 of 3 in cluster M

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

UNITOR SHIPS SVC INC 15TH PL (Continued)

EDR ID Number
EPA ID Number

Database(s)

1001226367

RCRIS:

Owner: UNITOR SHIPS SVC
(206) 767-2770

EPA ID: WAH000003384

Contact: JOHN MALLINGER
(206) 767-2770

Classification: Small Quantity Generator

Used Oil Recyc: No

TSDF Activities: Not reported

Violation Status: No violations found

M65
South
1/4-1/2
2341 ft.
Higher

UNITOR SHIPS SVC INC 15TH PL
9100 15TH PL S STE A
SEATTLE, WA 98108

FINDS 1004957499
000006844590

Site 3 of 3 in cluster M

N66
SSW
1/4-1/2
2358 ft.
Higher

KASPAC CHIYODA PROPERTY
1237 S DIRECTOR ST
SEATTLE, WA 98108

RCRIS-SQG 1000121345
FINDS WAD027460955
UST
CSCSL NFA

Site 1 of 4 in cluster N

RCRIS:

Owner: KASPAC CORP
(360) 555-1212

EPA ID: WAD027460955

Contact: TERRY EASTBURN

Classification: Small Quantity Generator

Used Oil Recyc: No

TSDF Activities: Not reported

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:

Facility Registry System (FRS)

Resource Conservation and Recovery Act Information system (RCRAINFO)

WA NFA:

Facility/Site Id : 2489
Ecology Status : Independent Remedial Action
Independent Status Code : Final Independent RA Report received
WARM Bin Number : Not reported
NFA Code : NFA after Assesment IRAP or VCP
NFA Date : 5/16/1998 00:00:00

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

KASPAC CHIYODA PROPERTY (Continued)

1000121345

UST:

Facility ID: 2283
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: LEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

N67
SSW
1/4-1/2
2358 ft.
Higher

CHIYODA INTERNATIONAL/KASPAC
1237 S. DIRECTOR ST.
SEATTLE, WA 98108

WA ICR S104486333
N/A

Site 2 of 4 in cluster N

WA ICR:

Date Ecology Received Report: 07/09/1992
Contaminants Found at Site: Halogenated organic compounds
 Non-haologenated solvents
Media Contaminated: Groundwater, Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Final cleanup report
Site Register Issue: 92-28
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 10/14/1992
Contaminants Found at Site: Non-haologenated solvents
Media Contaminated: Groundwater
Cause of Contamination: Not reported
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 92-35
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 08/16/1993
Contaminants Found at Site: Metals
 Volatile Organic Compounds
Media Contaminated: Groundwater
Cause of Contamination: Not reported
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 93-09
County Code: 17
Contact: Not reported
Report Title: Not reported

N68
SSW
1/4-1/2
2363 ft.
Higher

PRECISION ENGINEERING
1231 S DIRECTOR
SEATTLE, WA 98108

FINDS 1000172415
RCRIS-LQG WAD041338252
CSCSL NFA
WA ICR

Site 3 of 4 in cluster N

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

PRECISION ENGINEERING (Continued)

1000172415

RCRIS:

Owner: PRECISION ENGINEERING
EPA ID: WAD041338252
Contact: GEORGE CARDILE
 (503) 289-1145

Classification: N, Large Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported

BIENNIAL REPORTS:

Last Biennial Reporting Year: 1999

<u>Waste</u>	<u>Quantity (Lbs)</u>	<u>Waste</u>	<u>Quantity (Lbs)</u>
D001	2315.42	D002	41711.24
D006	3420.00	D007	53774.97
D008	17235.49	D018	1145.74
D039	1145.74	F005	1169.68
F006	5113.71		

Violation Status: Violations exist

Regulation Violated: -170(3)(b)
Area of Violation: GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined: 11/10/1998

Enforcement Action: WRITTEN INFORMAL
Enforcement Action Date: 01/28/1999
Penalty Type: Not reported

Regulation Violated: -220(1)(a)
Area of Violation: GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined: 11/10/1998

Enforcement Action: WRITTEN INFORMAL
Enforcement Action Date: 01/28/1999
Penalty Type: Not reported

Regulation Violated: -200(1)(b)&-630(5)(a)
Area of Violation: GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined: 11/10/1998

Enforcement Action: WRITTEN INFORMAL
Enforcement Action Date: 01/28/1999
Penalty Type: Not reported

Regulation Violated: -200(1)(d)
Area of Violation: GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined: 11/10/1998

Enforcement Action: WRITTEN INFORMAL
Enforcement Action Date: 01/28/1999
Penalty Type: Not reported

Regulation Violated: -200(1)(b)&-640
Area of Violation: GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined: 11/10/1998

Enforcement Action: WRITTEN INFORMAL
Enforcement Action Date: 01/28/1999
Penalty Type: Not reported

Regulation Violated: -180
Area of Violation: GENERATOR-GENERAL REQUIREMENTS

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

PRECISION ENGINEERING (Continued)

EDR ID Number
EPA ID Number

Database(s)

1000172415

Date Violation Determined: 06/03/1992
Enforcement Action: WRITTEN INFORMAL
Enforcement Action Date: 07/06/1992
Penalty Type: Not reported
Regulation Violated: -200
Area of Violation: GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined: 06/03/1992
Enforcement Action: WRITTEN INFORMAL
Enforcement Action Date: 07/06/1992
Penalty Type: Not reported
Regulation Violated: Not reported
Area of Violation: GENERATOR-ALL REQUIREMENTS (OVERSIGHT)
Date Violation Determined: 11/17/1987
Enforcement Action: WRITTEN INFORMAL
Enforcement Action Date: 01/29/1988
Penalty Type: Not reported

There are 8 violation record(s) reported at this site:

<u>Evaluation</u>	<u>Area of Violation</u>	<u>Date of Compliance</u>
Compliance Evaluation Inspection	GENERATOR-GENERAL REQUIREMENTS	03/01/1999
	GENERATOR-GENERAL REQUIREMENTS	03/01/1999
	GENERATOR-GENERAL REQUIREMENTS	02/15/1999
	GENERATOR-GENERAL REQUIREMENTS	02/15/1999
	GENERATOR-GENERAL REQUIREMENTS	06/29/2000
Compliance Evaluation Inspection	GENERATOR-GENERAL REQUIREMENTS	08/12/1999
	GENERATOR-GENERAL REQUIREMENTS	08/12/1999
Compliance Evaluation Inspection	GENERATOR-ALL REQUIREMENTS (OVERSIGHT)	07/04/1999

FINDS:

Other Pertinent Environmental Activity Identified at Site:
AIRS Facility System (AIRS/AFS)
Biennial Reporting System (BRS)
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)
Toxic Chemical Release Inventory System (TRIS)

WA NFA:

Facility/Site Id : 2056
Ecology Status : RA and all activities completed, No Monitoring
Independent Status Code : Final Independent RA Report received
WARM Bin Number : 1
NFA Code : Removed from HSL
NFA Date : 2/13/1996 00:00:00

WA ICR:

Date Ecology Received Report: 09/07/1990
Contaminants Found at Site: Metals
Media Contaminated: Soil
Cause of Contamination: Handling practices, Spill
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 90-11
County Code: 17
Contact: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

PRECISION ENGINEERING (Continued)

EDR ID Number
EPA ID Number

Database(s)

1000172415

Report Title: Not reported

N69
SSW
1/4-1/2
2363 ft.
Higher

PRECISION ENGINEERING INC.
1231 SOUTH DIRECTOR STREET
SEATTLE, WA 98108

UST U003028400
N/A

Site 4 of 4 in cluster N

UST:

Facility ID: 8205
Install Date: 12/31/1964 0:00
Capacity: 111 to 1,100 Gallons
Status: Not reported
Tank Name: Not reported
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 8205
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: HAZARDOUS SUBSTANCE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 8205
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: HAZARDOUS SUBSTANCE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 8205
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: HAZARDOUS SUBSTANCE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 8205
Install Date: 12/31/1964 0:00
Capacity: 111 to 1,100 Gallons
Status: Not reported
Tank Name: HAZARDOUS SUBSTANCE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

PRECISION ENGINEERING INC. (Continued)

EDR ID Number
EPA ID Number

Database(s)

U003028400

Facility ID: 8205
Install Date: 12/31/1964 0:00
Capacity: 111 to 1,100 Gallons
Status: Not reported
Tank Name: HAZARDOUS SUBSTANCE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 8205
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: HAZARDOUS SUBSTANCE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 8205
Install Date: 12/31/1964 0:00
Capacity: 111 to 1,100 Gallons
Status: Not reported
Tank Name: HAZARDOUS SUBSTANCE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 8205
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: HAZARDOUS SUBSTANCE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 8205
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: HAZARDOUS SUBSTANCE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

O70
North
1/4-1/2
2384 ft.
Lower

BOC GASES 14TH AVE
7700 14TH AVE S
SEATTLE, WA 98108

Site 1 of 4 in cluster O

SHWS:

Facility ID: 2081
Responsible Unit: NW
Latitude: 47 32 7
Longitude: 122 18 52
Ecology Site Status relative to the MTCA cleanup process:
Independent Remedial Action

CSCSL NFA S104971576
CSCSL N/A
SPILLS

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

BOC GASES 14TH AVE (Continued)

S104971576

Independent Site Status - those sites undergoing an independent cleanup:

Independent Site Assessment of Interim Remedial Action Report received

WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):

Not reported

Affected Media:

Ground Water

Media Status: C (Confirmed) - The presence of hazardous substances above MTCA cleanup levels has been confirmed by laboratory analysis (or field determination in the case of petroleum contamination)

Arsenic Code: Not reported

Base/Neutral/Acid Organics: Not reported

Halogenated Organic Compounds: Not reported

Horizontal Collection Method: 3

EPA Priority Pollutants - Metals and Cyanide: Confirmed above MTCA cleanup levels

Metals - Other non-priority pollutant metals: Not reported

Polychlorinated biPhenyls (PCBs): Not reported

Pesticides: Not reported

Petroleum Products: Suspected to be present

Phenolic Compounds: Not reported

Non-Halogenated Solvents: Not reported

Dioxin: Not reported

Polynuclear Aromatic Hydrocarbons (PAH): Not reported

Reactive Wastes: Not reported

Corrosive Wastes: Suspected to be present

Radioactive Wastes: Suspected to be present

Asbestos: Not reported

Conventional Contaminants, Organic: Not reported

Conventional Contaminants, Inorganic: Not reported

Facility ID: 2081

Responsible Unit: NW

Latitude: 47 32 7

Longitude: 122 18 52

Ecology Site Status relative to the MTCA cleanup process:

Independent Remedial Action

Independent Site Status - those sites undergoing an independent cleanup:

Independent Site Assessment of Interim Remedial Action Report received

WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):

Not reported

Affected Media:

Soil

Media Status: C (Confirmed) - The presence of hazardous substances above MTCA cleanup levels has been confirmed by laboratory analysis (or field determination in the case of petroleum contamination)

Arsenic Code: Not reported

Base/Neutral/Acid Organics: Not reported

Halogenated Organic Compounds: Not reported

Horizontal Collection Method: 3

EPA Priority Pollutants - Metals and Cyanide: Confirmed above MTCA cleanup levels

Metals - Other non-priority pollutant metals: Not reported

Polychlorinated biPhenyls (PCBs): Not reported

Pesticides: Not reported

Petroleum Products: Suspected to be present

Phenolic Compounds: Not reported

Non-Halogenated Solvents: Not reported

Dioxin: Not reported

Polynuclear Aromatic Hydrocarbons (PAH): Not reported

Reactive Wastes: Not reported

Corrosive Wastes: Suspected to be present

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

BOC GASES 14TH AVE (Continued)

EDR ID Number
EPA ID Number

Database(s)

S104971576

Radioactive Wastes: Suspected to be present
Asbestos: Not reported
Conventional Contaminants, Organic: Not reported
Conventional Contaminants, Inorganic: Not reported

Facility ID: 2081
Responsible Unit: NW
Latitude: 47 32 7
Longitude: 122 18 52

Ecology Site Status relative to the MTCA cleanup process:
Independent Remedial Action

Independent Site Status - those sites undergoing an independent cleanup:
Independent Site Assessment of Interim Remedial Action Report received

WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):
Not reported

Affected Media: Surface Water

Media Status: S (Suspected) - Due to preliminary investigations or the nature of business operations or manufacturing processes, certain contaminants are suspected to be present at the site

Arsenic Code: Not reported
Base/Neutral/Acid Organics: Not reported
Halogenated Organic Compounds: Not reported
Horizontal Collection Method: 3
EPA Priority Pollutants - Metals and Cyanide: Suspected to be present
Metals - Other non-priority pollutant metals: Not reported
Polychlorinated biPhenyls (PCBs): Not reported
Pesticides: Not reported
Petroleum Products: Suspected to be present
Phenolic Compounds: Not reported
Non-Halogenated Solvents: Not reported
Dioxin: Not reported
Polynuclear Aromatic Hydrocarbons (PAH): Not reported
Reactive Wastes: Not reported
Corrosive Wastes: Suspected to be present
Radioactive Wastes: Suspected to be present
Asbestos: Not reported
Conventional Contaminants, Organic: Not reported
Conventional Contaminants, Inorganic: Not reported

Facility ID: 2081
Responsible Unit: NW
Latitude: 47 32 7
Longitude: 122 18 52

Ecology Site Status relative to the MTCA cleanup process:
Independent Remedial Action

Independent Site Status - those sites undergoing an independent cleanup:
Independent Site Assessment of Interim Remedial Action Report received

WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):
Not reported

Affected Media: Air

Media Status: S (Suspected) - Due to preliminary investigations or the nature of business operations or manufacturing processes, certain contaminants are suspected to be present at the site

Arsenic Code: Not reported
Base/Neutral/Acid Organics: Not reported
Halogenated Organic Compounds: Not reported
Horizontal Collection Method: 3

Map ID
Direction
Distance
Distance (ft.)
Elevation

Site

MAP FINDINGS

Database(s)

EDR ID Number

EPA ID Number

BOC GASES 14TH AVE (Continued)

S104971576

EPA Priority Pollutants - Metals and Cyanide:	Suspected to be present
Metals - Other non-priority pollutant metals:	Not reported
Polychlorinated biPhenyls (PCBs):	Not reported
Pesticides:	Not reported
Petroleum Products:	Suspected to be present
Phenolic Compounds:	Not reported
Non-Halogenated Solvents:	Not reported
Dioxin:	Not reported
Polynuclear Aromatic Hydrocarbons (PAH):	Not reported
Reactive Wastes:	Not reported
Corrosive Wastes:	Suspected to be present
Radioactive Wastes:	Suspected to be present
Asbestos:	Not reported
Conventional Contaminants, Organic:	Not reported
Conventional Contaminants, Inorganic:	Not reported

Facility ID: 2081

Responsible Unit: NW

Latitude: 47 32 7

Longitude: 122 18 52

Ecology Site Status relative to the MTCA cleanup process:

Independent Remedial Action

Independent Site Status - those sites undergoing an independent cleanup:

Independent Site Assessment of Interim Remedial Action Report received

WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):

Not reported

Affected Media: Sediments

Media Status: S (Suspected) - Due to preliminary investigations or the nature of business operations or manufacturing processes, certain contaminants are suspected to be present at the site

Arsenic Code: Not reported

Base/Neutral/Acid Organics: Not reported

Halogenated Organic Compounds: Not reported

Horizontal Collection Method: 3

EPA Priority Pollutants - Metals and Cyanide: Suspected to be present

Metals - Other non-priority pollutant metals: Not reported

Polychlorinated biPhenyls (PCBs): Not reported

Pesticides: Not reported

Petroleum Products: Suspected to be present

Phenolic Compounds: Not reported

Non-Halogenated Solvents: Not reported

Dioxin: Not reported

Polynuclear Aromatic Hydrocarbons (PAH): Not reported

Reactive Wastes: Not reported

Corrosive Wastes: Suspected to be present

Radioactive Wastes: Suspected to be present

Asbestos: Not reported

Conventional Contaminants, Organic: Not reported

Conventional Contaminants, Inorganic: Not reported

WA SPILL:

Facility ID: 525690

Date Received: 04/10/2002

Business Name: BOC GASES

Material Desc : OTHER HAZARDOUS

Medium: INDUSTRIAL PROPERTY

Material Qty: 300

Material Units: GALLON

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

BOC GASES 14TH AVE (Continued)

EDR ID Number
EPA ID Number

Database(s)

S104971576

WA NFA:

Facility/Site Id : 2081
Ecology Status : Independent Remedial Action
Independent Status Code : Independant Site Assesment or Interim RA recvd
WARM Bin Number : Not reported
NFA Code : NFA after Assesment IRAP or VCP
NFA Date : 12/20/1996 00:00:00

O71
North
1/4-1/2
2384 ft.
Lower

AIRCO WELDING PRODUCTS
7700 14TH AV S
SEATTLE, WA 98108

RCRIS-SQG 1000178275
FINDS WAD097818983
TSCA
CERC-NFRAP
WA ICR

Site 2 of 4 in cluster O

CERCLIS-NFRAP Classification Data:

Site Incident Category: Not reported
Non NPL Code: NFRAP
Ownership Status: Other

Federal Facility: Not a Federal Facility

NPL Status: Not on the NPL

CERCLIS-NFRAP Assessment History:

Assessment: DISCOVERY
Assessment: PRELIMINARY ASSESSMENT

Completed: 12/13/1979
Completed: 05/08/1985

RCRIS:

Owner: BOC GASES 14TH AVE
EPA ID: WAD097818983
Contact: BRIAN FERGUSON
(206) 767-3888

Classification: Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)
Toxic Chemical Release Inventory System (TRIS)

WA ICR:

Date Ecology Received Report: 03/11/1998
Contaminants Found at Site: Metals
Media Contaminated: Groundwater, Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Not reported
Site Register Issue: 98-01
County Code: 17
Contact: Not reported
Report Title: Not reported

O72
North
1/4-1/2
2384 ft.
Lower

BOC GASES, DIV OF BOC GROUP, INC.
7700 14TH S
SEATTLE, WA 98108
Site 3 of 4 in cluster O

UST U003026040
N/A

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

BOC GASES, DIV OF BOC GROUP, INC. (Continued)

EDR ID Number
EPA ID Number

Database(s)

U003026040

UST:

Facility ID: 1587
Install Date: 7/17/1968 0:00
Capacity: 1,101 TO 2,000 GALLONS
Status: Not reported
Tank Name: HAZARDOUS SUBSTANCE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

O73
North
1/4-1/2
2384 ft.
Lower

7700 14TH AVENUE SOUTH, SEATTLE, WA 9810
SEATTLE, WA

SPILLS S105397974
N/A

Site 4 of 4 in cluster O

WA SPILL:

Facility ID: 519560
Date Received: 07/12/2001
Business Name: ACETYLENE PLANT
Material Desc : CHEMICAL
Medium: OTHER
Material Qty: Not reported
Material Units: Not reported

P74
WNW
1/4-1/2
2385 ft.
Lower

S KENYON ST
832 S KENYON ST
SEATTLE, WA 98108

RCRIS-SQG 1000199626
FINDS WAD981766181

Site 1 of 6 in cluster P

RCRIS:

Owner: WA ECY
(360) 555-1212
EPA ID: WAD981766181
Contact: LAURENCE ASHLEY
(425) 885-1900
Classification: Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

P75
WNW
1/4-1/2
2416 ft.
Lower

REAMCO ELECTRONICS
817 S KENYON
SEATTLE, WA 98108
Site 2 of 6 in cluster P

RCRIS-SQG 1000297046
FINDS WAD092880095

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

REAMCO ELECTRONICS (Continued)

EDR ID Number
EPA ID Number

Database(s)

1000297046

RCRIS:

Owner: REAMCO ELECTRONICS
(360) 555-1212
EPA ID: WAD092880095
Contact: TEE SQUANT NEE JACK
(425) 234-5239

Classification: Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

P76
WNW
1/4-1/2
2424 ft.
Lower

WEST FORK NELSON
7918 8TH AVE S
SEATTLE, WA 98108

UST U001128233
N/A

Site 3 of 6 in cluster P

UST:

Facility ID: 101151
Install Date: 12/31/1964 0:00
Capacity: 111 TO 1,000 GALLONS
Status: Not reported
Tank Name: LEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

P77
WNW
1/4-1/2
2426 ft.
Lower

WESTFORK NELSON INCORPORATED
7916 8TH AVE S
SEATTLE, WA 98108

UST U001128423
N/A

Site 4 of 6 in cluster P

UST:

Facility ID: 101576
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: LEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

P78
WNW
1/4-1/2
2447 ft.
Lower

WFI
800 S KENYON
SEATTLE, WA 98108

UST U000591516
N/A

Site 5 of 6 in cluster P

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

WFI (Continued)

U000591516

UST:

Facility ID: 6933
Install Date: 12/31/1964 0:00
Capacity: 111 to 1,100 Gallons
Status: Not reported
Tank Name: LEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 6933
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: Not reported
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 6933
Install Date: 12/31/1964 0:00
Capacity: 111 to 1,100 Gallons
Status: Not reported
Tank Name: LEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 6933
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: Not reported
Substance: NW
Compartment #: Not reported
Ecology Region: 1

P79
WNW
1/4-1/2
2447 ft.
Lower

SERVICE SPECIALTIES INC
800 S KENYON ST
SEATTLE, WA 98108

Site 6 of 6 in cluster P

RCRIS-SQG 1000432886
FINDS WAD981764467

RCRIS:

Owner: SERVICE SPECIALTIES INC
(360) 555-1212
EPA ID: WAD981764467
Contact: DEAN BERTO
(206) 632-1441

Classification: Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

SERVICE SPECIALTIES INC (Continued)

1000432886

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:

Facility Registry System (FRS)

Resource Conservation and Recovery Act Information system (RCRAINFO)

80
East
1/4-1/2
2459 ft.
Higher

BOEING D&SG / MFC SITE
1008 E MARGINAL WAY S
SEATTLE, WA 98108

RCRIS-SQG 1000455948
FINDS WAD988475943
CORRACTS

CORRACTS Data:

EPA Id: WAD988475943
Region: 10
State: Not reported
Area Name: ENTIRE FACILITY
Original Scheduled Date: Not reported
New Scheduled Date: Not reported
Actual Date: 05/21/1997
Corrective Action: CA070YE - RFA Determination Of Need For An RFI, RFI is Necessary

EPA Id: WAD988475943
Region: 10
State: Not reported
Area Name: ENTIRE FACILITY
Original Scheduled Date: Not reported
New Scheduled Date: Not reported
Actual Date: 01/13/1993
Corrective Action: CA075LO - CA Prioritization, Facility or area was assigned a low corrective action priority

EPA Id: WAD988475943
Region: 10
State: Not reported
Area Name: ENTIRE FACILITY
Original Scheduled Date: Not reported
New Scheduled Date: Not reported
Actual Date: 05/21/1997
Corrective Action: CA075ME - CA Prioritization, Facility or area was assigned a medium corrective action priority

EPA Id: WAD988475943
Region: 10
State: Not reported
Area Name: ENTIRE FACILITY
Original Scheduled Date: Not reported
New Scheduled Date: Not reported
Actual Date: 09/21/1994
Corrective Action: CA225NR - Stabilization Measures Evaluation, This facility is , not amenable to stabilization activity at the, present time for reasons other than (1) it appears to be technically, infeasible or inappropriate (NF) or (2) there is a lack of technical, information (IN). Reasons for this conclusion may be the status of, closure at the facility, the degree of risk, timing considerations, the status of corrective action work at the facility, or other, administrative considerations

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

BOEING D&SG / MFC SITE (Continued)

EDR ID Number
EPA ID Number

Database(s)

1000455948

RCRIS Corrective Action Summary:

Event: RFA Determination Of Need For An RFI, RFI is Necessary;
Event Date: 05/21/1997
Event: CA Prioritization, Facility or area was assigned a medium corrective action priority.
Event Date: 05/21/1997
Event: Stabilization Measures Evaluation, This facility is not amenable to stabilization activity at the present time for reasons other than 1) it appears to be technically infeasible or inappropriate (NF) or 2) there is a lack of technical information (IN). Reasons for this conclusion may be the status of closure at the facility, the degree of risk, timing considerations, the status of corrective action work at the facility, or other administrative considerations.
Event Date: 09/21/1994
Event: CA Prioritization, Facility or area was assigned a low corrective action priority.
Event Date: 01/13/1993

RCRIS:

Owner: BOEING CO
(206) 655-7431
EPA ID: WAD988475943
Contact: ANDRO WIPPLINGER
(206) 544-6167
Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Biennial Reporting System (BRS)
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

Q81
North
1/4-1/2
2519 ft.
Lower

BOEING CO N BOEING FIELD
7500 E MARGINAL WY
SEATTLE, WA 98108
Site 1 of 6 in cluster Q

HAZNET S104584307
N/A

HAZNET:

Gepaid: WAD980982037
Tepaid: CAD009452657
Gen County: 99
Tsd County: San Mateo
Tons: 1.0275
Category: Solids or sludges with halogenated organic compounds > 1000mg/kg
Disposal Method: Treatment, Incineration
Contact: THE BOEING COMPANY
Telephone: (206) 655-7431
Mailing Address: PO BOX 3707 M/S 63-41
SEATTLE, WA 98124 - 2207
County: 99

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BOEING CO N BOEING FIELD (Continued)

S104584307

Gepaid: WAD980982037
Tepaid: CAD009452657
Gen County: 99
Tsd County: San Mateo
Tons: 5.0950
Category: Liquids with halogenated organic compounds > 1000 mg/l
Disposal Method: Recycler
Contact: THE BOEING COMPANY
Telephone: (206) 655-7431
Mailing Address: PO BOX 3707 M/S 63-41
SEATTLE, WA 98124 - 2207
County 99

Gepaid: WAD980982037
Tepaid: CAD009452657
Gen County: 99
Tsd County: San Mateo
Tons: .0825
Category: Liquids with halogenated organic compounds > 1000 mg/l
Disposal Method: Treatment, Incineration
Contact: THE BOEING COMPANY
Telephone: (206) 655-7431
Mailing Address: PO BOX 3707 M/S 63-41
SEATTLE, WA 98124 - 2207
County 99

Gepaid: WAD980982037
Tepaid: CAD009452657
Gen County: 99
Tsd County: San Mateo
Tons: .2000
Category: Liquids with chromium (VI) > 500 mg/l
Disposal Method: Treatment, Incineration
Contact: THE BOEING COMPANY
Telephone: (206) 655-7431
Mailing Address: PO BOX 3707 M/S 63-41
SEATTLE, WA 98124 - 2207
County 99

Gepaid: WAD980982037
Tepaid: CAD009452657
Gen County: 99
Tsd County: San Mateo
Tons: 1.2000
Category: Off-specification, aged, or surplus organics
Disposal Method: Recycler
Contact: THE BOEING COMPANY
Telephone: (206) 655-7431
Mailing Address: PO BOX 3707 M/S 63-41
SEATTLE, WA 98124 - 2207
County 99

The CA HAZNET database contains 74 additional records for this site.
Please contact your EDR Account Executive for more information.

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

Q82
North
1/4-1/2
2519 ft.
Lower
7500 EAST MARGINAL LANE SOUTH
7500 EAST MARGINAL LANE SOUTH
SEATTLE, WA
Site 2 of 6 in cluster Q

ERNS **90161025**
N/A

Q83
North
1/4-1/2
2519 ft.
Lower
NORTH BOEING FIELD
7500 E MARGINAL WAY S
SEATTLE, WA 98108
Site 3 of 6 in cluster Q

UST **U003028460**
LUST **N/A**

LUST:

Facility ID: 8338 Ecology Region: North Western
Release ID: 2558 Release Date: 9/14/1989 00:00:00
Release Status: Cleanup Started Status Date: Not reported
Alternate Name: BOEING NORTH FIELD DELIVERY
Affected Media: Soil

Facility ID: 8338 Ecology Region: North Western
Release ID: 2558 Release Date: 9/14/1989 00:00:00
Release Status: Cleanup Started Status Date: Not reported
Alternate Name: BOEING NORTH FIELD DELIVERY
Affected Media: Ground Water

Facility ID: 8338 Ecology Region: North Western
Release ID: 2558 Release Date: 9/14/1989 00:00:00
Release Status: Reported Cleaned Up Status Date: 5/10/1993 00:00:00
Alternate Name: BOEING NORTH FIELD DELIVERY
Affected Media: Soil

Facility ID: 8338 Ecology Region: North Western
Release ID: 2558 Release Date: 9/14/1989 00:00:00
Release Status: Reported Cleaned Up Status Date: 5/10/1993 00:00:00
Alternate Name: BOEING NORTH FIELD DELIVERY
Affected Media: Ground Water

Facility ID: 8338 Ecology Region: North Western
Release ID: 5290 Release Date: 5/17/1994 00:00:00
Release Status: Cleanup Started Status Date: 5/17/1994 00:00:00
Alternate Name: BOEING N FIELD F & G FACILITY
Affected Media: Soil

Facility ID: 8338 Ecology Region: North Western
Release ID: 5290 Release Date: 5/17/1994 00:00:00
Release Status: Cleanup Started Status Date: 5/17/1994 00:00:00
Alternate Name: BOEING N FIELD F & G FACILITY
Affected Media: Ground Water

Facility ID: 8338 Ecology Region: North Western
Release ID: 5290 Release Date: 5/17/1994 00:00:00
Release Status: Reported Cleaned Up Status Date: 10/24/1994 00:00:00
Alternate Name: BOEING N FIELD F & G FACILITY
Affected Media: Soil

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

NORTH BOEING FIELD (Continued)

EDR ID Number
EPA ID Number

Database(s)

U003028460

Facility ID: 8338 Ecology Region: North Western
Release ID: 5290 Release Date: 5/17/1994 00:00:00
Release Status: Reported Cleaned Up Status Date: 10/24/1994 00:00:00
Alternate Name: BOEING N FIELD F & G FACILITY
Affected Media: Ground Water

Facility ID: 8338 Ecology Region: North Western
Release ID: 5290 Release Date: 5/17/1994 00:00:00
Release Status: Reported Cleaned Up Status Date: 6/1/1995 00:00:00
Alternate Name: BOEING N FIELD F & G FACILITY
Affected Media: Soil

Facility ID: 8338 Ecology Region: North Western
Release ID: 5290 Release Date: 5/17/1994 00:00:00
Release Status: Reported Cleaned Up Status Date: 6/1/1995 00:00:00
Alternate Name: BOEING N FIELD F & G FACILITY
Affected Media: Ground Water

Facility ID: 8338 Ecology Region: North Western
Release ID: 5292 Release Date: 5/17/1994 00:00:00
Release Status: Cleanup Started Status Date: 6/1/1995 00:00:00
Alternate Name: BOEING N FIELD GREEN HORNET AREA
Affected Media: Soil

Facility ID: 8338 Ecology Region: North Western
Release ID: 5292 Release Date: 5/17/1994 00:00:00
Release Status: Cleanup Started Status Date: 6/1/1995 00:00:00
Alternate Name: BOEING N FIELD GREEN HORNET AREA
Affected Media: Ground Water

Facility ID: 8338 Ecology Region: North Western
Release ID: 5292 Release Date: 5/17/1994 00:00:00
Release Status: Reported Cleaned Up Status Date: 4/15/1994 00:00:00
Alternate Name: BOEING N FIELD GREEN HORNET AREA
Affected Media: Soil

Facility ID: 8338 Ecology Region: North Western
Release ID: 5292 Release Date: 5/17/1994 00:00:00
Release Status: Reported Cleaned Up Status Date: 4/15/1994 00:00:00
Alternate Name: BOEING N FIELD GREEN HORNET AREA
Affected Media: Ground Water

Facility ID: 8338 Ecology Region: North Western
Release ID: 5628 Release Date: 2/1/1995 00:00:00
Release Status: Cleanup Started Status Date: 2/1/1995 00:00:00
Alternate Name: BOEING NORTH FIELD BLDG 3-374
Affected Media: Soil

Facility ID: 8338 Ecology Region: North Western
Release ID: 5628 Release Date: 2/1/1995 00:00:00
Release Status: Reported Cleaned Up Status Date: 1/30/1995 00:00:00
Alternate Name: BOEING NORTH FIELD BLDG 3-374
Affected Media: Soil

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NORTH BOEING FIELD (Continued)

U003028460

UST:

Facility ID: 8338
Install Date: 11/30/1951 0:00
Capacity: 10,000 TO 19,999 GALLONS
Status: Not reported
Tank Name: AVIATION FUEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 8338
Install Date: 12/31/1964 0:00
Capacity: 1,101 TO 2,000 GALLONS
Status: Not reported
Tank Name: HEATING FUEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 8338
Install Date: 12/31/1964 0:00
Capacity: 5,000 TO 9,999 GALLONS
Status: Not reported
Tank Name: HAZARDOUS SUBSTANCE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 8338
Install Date: 11/30/1953 0:00
Capacity: 30,000 TO 49,999 GALLONS
Status: Not reported
Tank Name: AVIATION FUEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 8338
Install Date: 12/31/1964 0:00
Capacity: 10,000 TO 19,999 GALLONS
Status: Not reported
Tank Name: AVIATION FUEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 8338
Install Date: 12/31/1964 0:00
Capacity: 10,000 TO 19,999 GALLONS
Status: Not reported
Tank Name: AVIATION FUEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

NORTH BOEING FIELD (Continued)

U003028460

Facility ID: 8338
Install Date: 11/30/1951 0:00
Capacity: 10,000 TO 19,999 GALLONS
Status: Not reported
Tank Name: AVIATION FUEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 8338
Install Date: 11/30/1967 0:00
Capacity: 20,000 TO 29,999 GALLONS
Status: Not reported
Tank Name: HEATING FUEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 8338
Install Date: 1/1/1988 0:00
Capacity: 1,101 TO 2,000 GALLONS
Status: Not reported
Tank Name: AVIATION FUEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 8338
Install Date: 12/31/1964 0:00
Capacity: 1,101 TO 2,000 GALLONS
Status: Not reported
Tank Name: Not reported
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 8338
Install Date: 12/31/1964 0:00
Capacity: 111 to 1,100 Gallons
Status: Not reported
Tank Name: LEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 8338
Install Date: 10/30/1950 0:00
Capacity: 10,000 TO 19,999 GALLONS
Status: Not reported
Tank Name: AVIATION FUEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NORTH BOEING FIELD (Continued)

U003028460

Facility ID: 8338
Install Date: 11/30/1950 0:00
Capacity: 10,000 TO 19,999 GALLONS
Status: Not reported
Tank Name: AVIATION FUEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 8338
Install Date: 11/30/1951 0:00
Capacity: 10,000 TO 19,999 GALLONS
Status: Not reported
Tank Name: AVIATION FUEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 8338
Install Date: 11/30/1953 0:00
Capacity: 30,000 TO 49,999 GALLONS
Status: Not reported
Tank Name: AVIATION FUEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 8338
Install Date: 11/30/1953 0:00
Capacity: 30,000 TO 49,999 GALLONS
Status: Not reported
Tank Name: AVIATION FUEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 8338
Install Date: 12/31/1964 0:00
Capacity: 10,000 TO 19,999 GALLONS
Status: Not reported
Tank Name: AVIATION FUEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 8338
Install Date: 12/31/1964 0:00
Capacity: 1,101 TO 2,000 GALLONS
Status: Not reported
Tank Name: LEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

NORTH BOEING FIELD (Continued)

EDR ID Number
EPA ID Number

Database(s)

U003028460

Facility ID: 8338
Install Date: 11/30/1950 0:00
Capacity: 10,000 TO 19,999 GALLONS
Status: Not reported
Tank Name: AVIATION FUEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 8338
Install Date: 11/30/1950 0:00
Capacity: 10,000 TO 19,999 GALLONS
Status: Not reported
Tank Name: AVIATION FUEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 8338
Install Date: 11/30/1951 0:00
Capacity: 10,000 TO 19,999 GALLONS
Status: Not reported
Tank Name: AVIATION FUEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 8338
Install Date: 11/30/1967 0:00
Capacity: 20,000 TO 29,999 GALLONS
Status: Not reported
Tank Name: HEATING FUEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 8338
Install Date: 12/31/1964 0:00
Capacity: 5,000 TO 9,999 GALLONS
Status: Not reported
Tank Name: HAZARDOUS SUBSTANCE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 8338
Install Date: 12/31/1964 0:00
Capacity: 111 to 1,100 Gallons
Status: Not reported
Tank Name: HEATING FUEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

NORTH BOEING FIELD (Continued)

Database(s) EDR ID Number
EPA ID Number

U003028460

Facility ID: 8338
Install Date: 12/31/1964 0:00
Capacity: 111 to 1,100 Gallons
Status: Not reported
Tank Name: AVIATION FUEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 8338
Install Date: 12/31/1964 0:00
Capacity: 111 to 1,100 Gallons
Status: Not reported
Tank Name: AVIATION FUEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 8338
Install Date: 1/1/1989 0:00
Capacity: 2,001 TO 4,999 GALLONS
Status: Not reported
Tank Name: UNLEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 8338
Install Date: 11/30/1986 0:00
Capacity: 5,000 TO 9,999 GALLONS
Status: Not reported
Tank Name: AVIATION FUEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 8338
Install Date: 11/30/1986 0:00
Capacity: 10,000 TO 19,999 GALLONS
Status: Not reported
Tank Name: USED OIL/WASTE OIL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 8338
Install Date: 11/30/1986 0:00
Capacity: 5,000 TO 9,999 GALLONS
Status: Not reported
Tank Name: AVIATION FUEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

NORTH BOEING FIELD (Continued)

U003028460

Facility ID: 8338
Install Date: 1/31/1986 0:00
Capacity: 111 to 1,100 Gallons
Status: Not reported
Tank Name: DIESEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Q84
North
1/4-1/2
2519 ft.
Lower

BOEING NORTH BOEING FIELD
7500 E MARGINAL WAY
SEATTLE, WA 98108

Site 4 of 6 in cluster Q

FINDS 1000257086
RCRIS-LQG 98108THBNG75
TRIS
WA ICR

RCRIS:

Owner: BOEING CO
(425) 865-2400
EPA ID: WAD980982037
Contact: LOUIS BABICH III
(425) 234-1766

Classification: N, Large Quantity Generator
Used Oil Recyc: No
TSD Activities: Not reported

BIENNIAL REPORTS:

Last Biennial Reporting Year: 1999

<u>Waste</u>	<u>Quantity (Lbs)</u>	<u>Waste</u>	<u>Quantity (Lbs)</u>
D001	255244.09	D004	130.00
D005	380032.66	D006	442042.13
D007	477493.88	D008	566249.13
D009	5370.00	D010	380017.38
D011	5240.00	D018	86257.39
D027	47.59	D035	1265.00
D039	47.59	D040	50.00
F002	339228.90	F003	35529.25
F005	296923.90	F019	138482.65

Violation Status: Violations exist

Regulation Violated: 200(1)(B)/630(5)(A)
Area of Violation: GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined: 08/26/1999
Enforcement Action: WRITTEN INFORMAL
Enforcement Action Date: 10/18/1999
Penalty Type: Not reported

Regulation Violated: 07(3)(6)/170(1)(A)
Area of Violation: GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined: 08/26/1999
Enforcement Action: WRITTEN INFORMAL
Enforcement Action Date: 10/18/1999
Penalty Type: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

BOEING NORTH BOEING FIELD (Continued)

EDR ID Number
EPA ID Number

Database(s)

1000257086

There are 2 violation record(s) reported at this site:

<u>Evaluation</u>	<u>Area of Violation</u>
Compliance Evaluation Inspection	GENERATOR-GENERAL REQUIREMENTS
	GENERATOR-GENERAL REQUIREMENTS

Date of
Compliance
08/26/199
01/07/200

FINDS:

Other Pertinent Environmental Activity Identified at Site:

Biennial Reporting System (BRS)
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)
Toxic Chemical Release Inventory System (TRIS)

WA ICR:

Date Ecology Received Report: 08/07/1992
Contaminants Found at Site: Petroleum products
Media Contaminated: Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Final cleanup report
Site Register Issue: 92-30
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 02/28/1992
Contaminants Found at Site: Petroleum products
Media Contaminated: Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 92-23
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 06/23/1992
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 92-27
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 06/25/1992
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 92-27
County Code: 17
Contact: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

BOEING NORTH BOEING FIELD (Continued)

EDR ID Number
EPA ID Number

Database(s)

1000257086

Report Title: Not reported
Date Ecology Received Report: 11/02/1992
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 92-36
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 12/12/1994
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Final cleanup report
Site Register Issue: 93-43
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 05/17/1994
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 93-27
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 02/01/1995
Contaminants Found at Site: Petroleum products
Media Contaminated: Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Final cleanup report
Site Register Issue: 93-44
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 05/17/1994
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 93-27
County Code: 17
Contact: Not reported
Report Title: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

Q85
North
1/4-1/2
2519 ft.
Lower

BOEING/NORTH BOEING FIELD BUILDING 3-333 SITE
7500 E. MARGINAL WAY S.
SEATTLE, WA 98104

WA ICR **S104484975**
N/A

Site 5 of 6 in cluster Q

WA ICR:

Date Ecology Received Report: 02/25/1997
Contaminants Found at Site: PCB's
Solvents
Media Contaminated: Soil
Cause of Contamination: Not reported
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 98-04
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 01/23/1998
Contaminants Found at Site: PCB's
Solvents
Media Contaminated: Soil
Cause of Contamination: Not reported
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 98-04
County Code: 17
Contact: Not reported
Report Title: Not reported

Q86
North
1/4-1/2
2519 ft.
Lower

7500 E MARGINAL WAY S
7500 E MARGINAL WAY S
SEATTLE, WA

ERNS **873093**
N/A

Site 6 of 6 in cluster Q

R87
NW
1/4-1/2
2565 ft.
Lower

WORKBOATS NORTHWEST INC
7814 8TH AVE S
SEATTLE, WA 98108

RCRIS-SQG **1000268099**
FINDS **WAD980975700**

Site 1 of 2 in cluster R

RCRIS:

Owner: RONALD BROWN
(206) 583-2714
EPA ID: WAD980975700
Contact: BRUCE REAGAN
(206) 767-4497

Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

WORKBOATS NORTHWEST INC (Continued)

1000268099

Violation Status: Violations exist

Regulation Violated:	200(1)(a)
Area of Violation:	GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined:	09/14/1995
Regulation Violated:	200(1)(c)
Area of Violation:	GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined:	09/14/1995
Regulation Violated:	200(1)(d)
Area of Violation:	GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined:	09/14/1995

There are 3 violation record(s) reported at this site:

<u>Evaluation</u>	<u>Area of Violation</u>	<u>Date of Compliance</u>
Compliance Evaluation Inspection	GENERATOR-GENERAL REQUIREMENTS	01/05/199
	GENERATOR-GENERAL REQUIREMENTS	01/05/199
	GENERATOR-GENERAL REQUIREMENTS	01/05/199

FINDS:

Other Pertinent Environmental Activity Identified at Site:

Facility Registry System (FRS)

Resource Conservation and Recovery Act Information system (RCRAINFO)

R88 E M MATSON JR CO INC
NW 7808 8TH AVE S
1/4-1/2 SEATTLE, WA 98108
2572 ft.
Lower Site 2 of 2 in cluster R

FINDS 1004613363
FTTS C10#10-91324

FTTS Insp:

Region:	10
Inspected Date:	11/20/91
Insp Number:	11/20/91
Violation occurred:	Yes
Inspector:	CREGER
Investigation Type:	General Product Review
Facility Function:	Producer
Investig Reason:	Neutral Scheme, Region
Legislation Code:	FIFRA

Region:	10
Inspected Date:	03/15/95
Insp Number:	03/15/95
Violation occurred:	No
Inspector:	DAVIS
Investigation Type:	General Product Review
Facility Function:	Producer
Investig Reason:	Neutral Scheme, Region
Legislation Code:	FIFRA

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

E M MATSON JR CO INC (Continued)

EDR ID Number
EPA ID Number

Database(s)

1004613363

FINDS:

Other Pertinent Environmental Activity Identified at Site:
National Compliance Database (NCDB)

S89
North
1/2-1
2714 ft.
Lower

HUSSMAN REFRIGERATION INC
7440 W MARGINAL WAY S
SEATTLE, WA 98108

RCRIS-SQG
FINDS

1000383415
WAD053816450

Site 1 of 2 in cluster S

RCRIS:

Owner: HUSSMAN REFRIGERATION INC
(360) 555-1212
EPA ID: WAD053816450
Contact: WIRT DORMAN
(206) 763-9050

Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

S90
North
1/2-1
2714 ft.
Lower

FOSS ENVIRONMENTAL SERVICES CO
7440 W MARGINAL WAY S
SEATTLE, WA 98108

PADS
RCRIS-SQG
FINDS

1000486140
WAD988482352

Site 2 of 2 in cluster S

RCRIS:

Owner: PIONEER HUMAN SERVICES
(206) 322-6645
EPA ID: WAD988482352
Contact: MICHAEL POE
(206) 768-1408

Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
PCB Handler Activity Data System (PADS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

91
NNW
1/2-1
2717 ft.
Lower

DUWAMISH RIVER SLIP 4
SLIP 4 DUWAMISH RIVER
SEATTLE, WA 98108

RCRIS-SQG
FINDS
CSCSL

1000199782
WAD980977029

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

DUWAMISH RIVER SLIP 4 (Continued)

Database(s)
EDR ID Number
EPA ID Number

1000199782

RCRIS:

Owner: WA ECY
(360) 555-1212
EPA ID: WAD980977029
Contact: GARY BRUGGER
(425) 885-1900
Classification: Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

SHWS:

Facility ID: 29959714
Responsible Unit: NW
Latitude: 47 32 51
Longitude: 122 20 18
Ecology Site Status relative to the MTCA cleanup process:
Awaiting Site Hazard Assessment (SHA)
Independent Site Status* - those sites undergoing an independent cleanup:
Not reported
WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):
Not reported
Affected Media: Sediments
Media Status: C (Confirmed) - The presence of hazardous substances above MTCA cleanup levels has been confirmed by laboratory analysis (or field determination in the case of petroleum contamination)
Arsenic Code: Not reported
Base/Neutral/Acid Organics: Confirmed above MTCA cleanup levels
Halogenated Organic Compounds: Not reported
Horizontal Collection Method: 99
EPA Priority Pollutants - Metals and Cyanide: Not reported
Metals - Other non-priority pollutant metals: Not reported
Polychlorinated biPhenyls (PCBs): Confirmed above MTCA cleanup levels
Pesticides: Not reported
Petroleum Products: Not reported
Phenolic Compounds: Not reported
Non-Halogenated Solvents: Not reported
Dioxin: Not reported
Polynuclear Aromatic Hydrocarbons (PAH): Confirmed above MTCA cleanup levels
Reactive Wastes: Not reported
Corrosive Wastes: Not reported
Radioactive Wastes: Not reported
Asbestos: Not reported
Conventional Contaminants, Organic: Not reported
Conventional Contaminants, Inorganic: Not reported

T92
South
1/2-1
2822 ft.
Higher
INDUSTRIAL AUTOMATION INC
1421 S 93RD ST
SEATTLE, WA 98108
Site 1 of 2 in cluster T

RCRIS-SQG 1001114274
FINDS WAR000009068

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

INDUSTRIAL AUTOMATION INC (Continued)

1001114274

RCRIS:

Owner: INDUSTRIAL AUTOMATION INC
EPA ID: WAR000009068
Contact: JEFF FISCHER
(206) 763-1025

Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported

Violation Status: Violations exist

Regulation Violated: 200(2),200(1)(D),630(5)(A)
Area of Violation: GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined: 02/16/1999
Regulation Violated: 200(1)(C)
Area of Violation: GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined: 02/16/1999
Regulation Violated: 200, 200(1)(B), 630(6)
Area of Violation: GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined: 02/16/1999

There are 3 violation record(s) reported at this site:

Evaluation	Area of Violation	Date of Compliance
Compliance Evaluation Inspection	GENERATOR-GENERAL REQUIREMENTS	04/01/199
	GENERATOR-GENERAL REQUIREMENTS	04/01/199
	GENERATOR-GENERAL REQUIREMENTS	04/01/199

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

93
WSW
1/2-1
2822 ft.
Higher

7TH AVE S / S CLOVERDALE
SEATTLE, WA

SPILLS S105390794
N/A

WA SPILL:

Facility ID: 507333
Date Received: 10/19/1999
Business Name: UNKNOWN
Material Desc : OTHER HAZARDOUS
Medium: SOIL
Material Qty: 5
Material Units: CYLINDER

U94
WNW
1/2-1
2835 ft.
Lower

INTERSTATE COATINGS
754 S CHICAGO
SEATTLE, WA 98108

RCRIS-SQG 1000697065
FINDS WAD988507430
CSCSL
WA ICR

Site 1 of 2 in cluster U

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

INTERSTATE COATINGS (Continued)

EDR ID Number
EPA ID Number

Database(s)

1000697065

RCRIS:

Owner: INTERSTATE COATINGS
EPA ID: WAD988507430
Contact: MARK WILK
(206) 762-1320

Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSD Activities: Not reported

Violation Status: Violations exist

Regulation Violated:	200(1)(c)&(d)
Area of Violation:	GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined:	12/07/1998
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	12/17/1998
Penalty Type:	Not reported
Regulation Violated:	200(1)(b)&630(5)(a)
Area of Violation:	GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined:	12/07/1998
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	12/17/1998
Penalty Type:	Not reported
Regulation Violated:	200(1)(b)&630(7)
Area of Violation:	GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined:	12/07/1998
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	12/17/1998
Penalty Type:	Not reported
Regulation Violated:	180(1)
Area of Violation:	GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined:	12/07/1998
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	12/17/1998
Penalty Type:	Not reported

There are 4 violation record(s) reported at this site:

<u>Evaluation</u>	<u>Area of Violation</u>	<u>Date of Compliance</u>
Compliance Evaluation Inspection	GENERATOR-GENERAL REQUIREMENTS	12/08/199
	GENERATOR-GENERAL REQUIREMENTS	12/08/199
	GENERATOR-GENERAL REQUIREMENTS	12/08/199
	GENERATOR-GENERAL REQUIREMENTS	01/19/199

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Biennial Reporting System (BRS)
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

SHWS:

Facility ID: 2335
Responsible Unit: NW

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

INTERSTATE COATINGS (Continued)

EDR ID Number
EPA ID Number

Database(s)

1000697065

Latitude: 47 31 58
Longitude: 122 19 26
Ecology Site Status relative to the MTCA cleanup process:
Ranked, Awaiting Remedial Action (RA)
Independent Site Status - those sites undergoing an independent cleanup:
Not reported
WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):
3 - Moderate assessed risk to human health and to the environment
Affected Media: Soil
Media Status: C (Confirmed) - The presence of hazardous substances above MTCA cleanup levels has been confirmed by laboratory analysis (or field determination in the case of petroleum contamination)
Arsenic Code: Not reported
Base/Neutral/Acid Organics: Not reported
Halogenated Organic Compounds: Suspected to be present
Horizontal Collection Method: 3
EPA Priority Pollutants - Metals and Cyanide: Confirmed above MTCA cleanup levels
Metals - Other non-priority pollutant metals: Not reported
Polychlorinated biPhenyls (PCBs): Not reported
Pesticides: Not reported
Petroleum Products: Confirmed above MTCA cleanup levels
Phenolic Compounds: Not reported
Non-Halogenated Solvents: Suspected to be present
Dioxin: Not reported
Polynuclear Aromatic Hydrocarbons (PAH): Not reported
Reactive Wastes: Not reported
Corrosive Wastes: Not reported
Radioactive Wastes: Not reported
Asbestos: Not reported
Conventional Contaminants, Organic: Not reported
Conventional Contaminants, Inorganic: Not reported
Facility ID: 2335
Responsible Unit: NW
Latitude: 47 31 58
Longitude: 122 19 26
Ecology Site Status relative to the MTCA cleanup process:
Ranked, Awaiting Remedial Action (RA)
Independent Site Status - those sites undergoing an independent cleanup:
Not reported
WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):
3 - Moderate assessed risk to human health and to the environment
Affected Media: Ground Water
Media Status: S (Suspected) - Due to preliminary investigations or the nature of business operations or manufacturing processes, certain contaminants are suspected to be present at the site
Arsenic Code: Not reported
Base/Neutral/Acid Organics: Not reported
Halogenated Organic Compounds: Suspected to be present
Horizontal Collection Method: 3
EPA Priority Pollutants - Metals and Cyanide: Suspected to be present
Metals - Other non-priority pollutant metals: Not reported
Polychlorinated biPhenyls (PCBs): Not reported
Pesticides: Not reported
Petroleum Products: Suspected to be present
Phenolic Compounds: Not reported
Non-Halogenated Solvents: Suspected to be present

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

EDR ID Number
EPA ID Number
Database(s)

INTERSTATE COATINGS (Continued)

1000697065

Dioxin:	Not reported
Polynuclear Aromatic Hydrocarbons (PAH):	Not reported
Reactive Wastes:	Not reported
Corrosive Wastes:	Not reported
Radioactive Wastes:	Not reported
Asbestos:	Not reported
Conventional Contaminants, Organic:	Not reported
Conventional Contaminants, Inorganic:	Not reported

Facility ID: 2335
Responsible Unit: NW
Latitude: 47 31 58
Longitude: 122 19 26

Ecology Site Status relative to the MTCA cleanup process:

Ranked, Awaiting Remedial Action (RA)

Independent Site Status - those sites undergoing an independent cleanup:

Not reported

WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):

3 - Moderate assessed risk to human health and to the environment

Affected Media: Surface Water

Media Status: S (Suspected) - Due to preliminary investigations or the nature of business operations or manufacturing processes, certain contaminants are suspected to be present at the site

Arsenic Code: Not reported

Base/Neutral/Acid Organics:

Not reported

Halogenated Organic Compounds: Suspected to be present

Horizontal Collection Method:

3

EPA Priority Pollutants - Metals and Cyanide: Suspected to be present

Metals - Other non-priority pollutant metals: Not reported

Polychlorinated biPhenyls (PCBs): Not reported

Pesticides: Not reported

Petroleum Products: Suspected to be present

Phenolic Compounds: Not reported

Non-Halogenated Solvents: Suspected to be present

Dioxin: Not reported

Polynuclear Aromatic Hydrocarbons (PAH): Not reported

Reactive Wastes: Not reported

Corrosive Wastes: Not reported

Radioactive Wastes: Not reported

Asbestos: Not reported

Conventional Contaminants, Organic: Not reported

Conventional Contaminants, Inorganic: Not reported

Facility ID: 2335
Responsible Unit: NW
Latitude: 47 31 58
Longitude: 122 19 26

Ecology Site Status relative to the MTCA cleanup process:

Ranked, Awaiting Remedial Action (RA)

Independent Site Status - those sites undergoing an independent cleanup:

Not reported

WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):

3 - Moderate assessed risk to human health and to the environment

Affected Media: Air

Media Status: S (Suspected) - Due to preliminary investigations or the nature of business operations or manufacturing processes, certain contaminants are suspected to be present at the site

Arsenic Code: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

INTERSTATE COATINGS (Continued)

EDR ID Number
EPA ID Number

Database(s)

1000697065

Base/Neutral/Acid Organics:	Not reported
Halogenated Organic Compounds:	Suspected to be present
Horizontal Collection Method:	3
EPA Priority Pollutants - Metals and Cyanide:	Suspected to be present
Metals - Other non-priority pollutant metals:	Not reported
Polychlorinated biPhenyls (PCBs):	Not reported
Pesticides:	Not reported
Petroleum Products:	Suspected to be present
Phenolic Compounds:	Not reported
Non-Halogenated Solvents:	Suspected to be present
Dioxin:	Not reported
Polynuclear Aromatic Hydrocarbons (PAH):	Not reported
Reactive Wastes:	Not reported
Corrosive Wastes:	Not reported
Radioactive Wastes:	Not reported
Asbestos:	Not reported
Conventional Contaminants, Organic:	Not reported
Conventional Contaminants, Inorganic:	Not reported

WA ICR:

Date Ecology Received Report:	12/04/1998
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Soil
Cause of Contamination:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	98-15
County Code:	17
Contact:	Not reported
Report Title:	Not reported

U95
WNW
1/2-1
2835 ft.
Lower

INTERSTATE COATINGS, INC.
754 S CHICAGO ST
SEATTLE, WA 98108

UST U003028790
LUST N/A

Site 2 of 2 in cluster U

LUST:

Facility ID:	9194	Ecology Region:	North Western
Release ID:	493842	Release Date:	12/4/1998 00:00:00
Release Status:	Cleanup Started	Status Date:	9/23/1998 00:00:00
Alternate Name:	INTERSTATE COATINGS INC		
Affected Media:	Soil		

UST:

Facility ID:	9194
Install Date:	4/15/1975 0:00
Capacity:	111 to 1,100 Gallons
Status:	Not reported
Tank Name:	UNLEADED GASOLINE
Substance:	NW
Compartment #:	Not reported
Ecology Region:	1

V96
South
1/2-1
2847 ft.
Higher

PROGRESSIVE MEDICAL CORP
1600 S 92ND AVE STE H
SEATTLE, WA 98108

RCRIS-SQG 1000236698
FINDS WAD981761497

Site 1 of 4 in cluster V

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

PROGRESSIVE MEDICAL CORP (Continued)

1000236698

RCRIS:

Owner: PROGRESSIVE MEDICAL CORP
 (360) 555-1212
EPA ID: WAD981761497
Contact: STEVE DILLINGHAM
 (206) 762-6910

Classification: Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

V97
South
1/2-1
2852 ft.
Higher

**KRS MARINE
1621 S. 92ND PL.
SEATTLE, WA 98108**

WA ICR S104586222
 N/A

Site 2 of 4 in cluster V

WA ICR:

Date Ecology Received Report: 05/23/2000
Contaminants Found at Site: Petroleum products
Media Contaminated: Soil
Cause of Contamination: Improper Handling
Region: North Western
Type of Report Ecology Received: Final cleanup report
Site Register Issue: 98-26
County Code: 17
Contact: Not reported
Report Title: Not reported

V98
South
1/2-1
2852 ft.
Higher

**1621 S 92ND PL, SEA KING INDUSTRIAL PARK
SEATTLE, WA**

SPILLS S105392837
 N/A

Site 3 of 4 in cluster V

WA SPILL:

Facility ID: 510843
Date Received: 05/08/2000
Business Name: KRS MARINE
Material Desc : PETROLEUM - HYDRAULIC OIL
Medium: SOIL
Material Qty: 30
Material Units: GALLON

V99
South
1/2-1
2852 ft.
Higher

**KRS MARINE
1621 S 92ND PLACE
SEATTLE, WA 98108**

CSCSL NFA S104780219
 N/A

Site 4 of 4 in cluster V

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

KRS MARINE (Continued)

EDR ID Number
EPA ID Number

Database(s)

S104780219

WA NFA:

Facility/Site Id : 90355185
Ecology Status : Independent Remedial Action
Independent Status Code : Final Independent RA Report received
WARM Bin Number : Not reported
NFA Code : NFA after Assessment IRAP or VCP
NFA Date : 8/17/2000 00:00:00

W100
WNW
1/2-1
2853 ft.
Lower

WESTEC INDUSTRIES INC
8111 7TH AVE S
SEATTLE, WA 98108
Site 1 of 2 in cluster W

FINDS 1005106665
000009111814

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)

T101
South
1/2-1
2860 ft.
Higher

AHRENIUS MANUFACTURING INC
1425 S 93RD
SEATTLE, WA 98108

FINDS 1005106681
000009112010

Site 2 of 2 in cluster T

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)

W102
WNW
1/2-1
2861 ft.
Lower

YALE MATERIALS HANDLING NW INC
8101 7TH AVE S
SEATTLE, WA 98108

RCRIS-SQG 1001491421
FINDS WA0000866947

Site 2 of 2 in cluster W

RCRIS:

Owner: YALE MATERIAL HANDLING NW INC
(360) 555-1212
EPA ID: WA0000866947
Contact: CURTIS ORR
(425) 251-5050

Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

103
South
1/2-1
2861 ft.
Higher

1641 S 92ND PL 98108 KRS MARINE
SEATTLE, WA

SPILLS S105391205
N/A

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

(Continued)

S105391205

WA SPILL:
Facility ID: 507987
Date Received: 12/01/1999
Business Name: KRS MARINE
Material Desc : PETROLEUM - HYDRAULIC OIL
Medium: SOIL
Material Qty: 2
Material Units: GALLON

104
WNW
1/2-1
2874 ft.
Lower

EVERGREEN REFRIGERATION
727 S. KENYON STREET
SEATTLE, WA 98108

FINDS 1005186356
000010195886

FINDS:
Other Pertinent Environmental Activity Identified at Site:
AIRS Facility System (AIRS/AFS)
Facility Registry System (FRS)

105
WNW
1/2-1
2926 ft.
Lower

SEIDELHUBER IRON & BRONZE WORKS, INC.
8009 7TH AVE S
SEATTLE, WA 98108

UST U003027936
N/A

UST:
Facility ID: 687
Install Date: 12/31/1964 0:00
Capacity: 111 to 1,100 Gallons
Status: Not reported
Tank Name: LEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 687
Install Date: 10/1/1991 0:00
Capacity: 111 to 1,100 Gallons
Status: Not reported
Tank Name: UNLEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

X106
SSW
1/2-1
2933 ft.
Higher

GARY MERLINO CONSTRUCTION CO., INC.
9125 10TH AVE S
SEATTLE, WA 98108
Site 1 of 2 in cluster X

UST U003025332
LUST N/A

LUST:
Facility ID: 10284
Release ID: 519639
Release Status: Cleanup Started
Alternate Name: Not reported
Affected Media: Soil
Ecology Region: North Western
Release Date: 8/31/1999 00:00:00
Status Date: 7/23/1999 00:00:00

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

GARY MERLINO CONSTRUCTION CO., INC. (Continued)

EDR ID Number
EPA ID Number

Database(s)

U003025332

Facility ID: 10284 Ecology Region: North Western
Release ID: 519639 Release Date: 8/31/1999 00:00:00
Release Status: Reported Cleaned Up Status Date: 8/31/1999 00:00:00
Alternate Name: Not reported
Affected Media: Soil

UST:

Facility ID: 10284
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: Not reported
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 10284
Install Date: 10/1/1975 0:00
Capacity: 10,000 TO 19,999 GALLONS
Status: Not reported
Tank Name: UNLEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 10284
Install Date: 10/1/1975 0:00
Capacity: 10,000 TO 19,999 GALLONS
Status: Not reported
Tank Name: UNLEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

X107
SSW
1/2-1
2933 ft.
Higher

GARY MERLINO CONSTRUCTION CO
9125 10TH AVE S
SEATTLE, WA 98108

RCRIS-SQG 1000660229
FINDS WAD988499125
WA ICR

Site 2 of 2 in cluster X

RCRIS:

Owner: GARY MERLINO CONSTRUCTION CO
(206) 762-9125
EPA ID: WAD988499125
Contact: LIANN MERLINO
(206) 762-2566

Classification: N, Conditionally Exempt Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

GARY MERLINO CONSTRUCTION CO (Continued)

EDR ID Number
EPA ID Number

Database(s)

1000660229

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:

Facility Registry System (FRS)

Resource Conservation and Recovery Act Information system (RCRAINFO)

WA ICR:

Date Ecology Received Report: 11/15/1999
Contaminants Found at Site: Petroleum products
Media Contaminated: Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Final cleanup report
Site Register Issue: 98-21
County Code: 17
Contact: Not reported
Report Title: Not reported

Y108
WNW
1/2-1
2974 ft.
Lower

**NORTHERN FREIGHT LINES INC
730 SO. CHICAGO STREET
SEATTLE, WA 98108**

UST U003028740
N/A

Site 1 of 2 in cluster Y

UST:

Facility ID: 905
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: Not reported
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Z109
North
1/2-1
2975 ft.
Lower

**BOEING NORTH FIELD
7370 E MARGINAL WAY S
SEATTLE, WA 98108**

CSCSL S102363853
N/A

Site 1 of 2 in cluster Z

SHWS:

Facility ID: 2050
Responsible Unit: NW
Latitude: 47 32 20
Longitude: 122 19 14
Ecology Site Status relative to the MTCA cleanup process:
Independent Remedial Action
Independent Site Status - those sites undergoing an independent cleanup:
Independent Site Assessment of Interim Remedial Action Report received
WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):
5 - Lowest assessed risk to human health and to the environment
Affected Media: Ground Water
Media Status: C (Confirmed) - The presence of hazardous substances above MTCA cleanup levels has
been confirmed by laboratory analysis (or field determination in the case of petroleum
contamination)
Arsenic Code: Not reported
Base/Neutral/Acid Organics: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

BOEING NORTH FIELD (Continued)

EDR ID Number
EPA ID Number

Database(s)

S102363853

Halogenated Organic Compounds:	Confirmed above MTCA cleanup levels
Horizontal Collection Method:	3
EPA Priority Pollutants - Metals and Cyanide:	Confirmed above MTCA cleanup levels
Metals - Other non-priority pollutant medals:	Suspected to be present
Polychlorinated biPhenyls (PCBs):	Confirmed above MTCA cleanup levels
Pesticides:	Not reported
Petroleum Products:	Confirmed above MTCA cleanup levels
Phenolic Compounds:	Not reported
Non-Halogenated Solvents:	Confirmed above MTCA cleanup levels
Dioxin:	Suspected to be present
Polynuclear Aromatic Hydrocarbons (PAH):	Not reported
Reactive Wastes:	Not reported
Corrosive Wastes:	Confirmed above MTCA cleanup levels
Radioactive Wastes:	Not reported
Asbestos:	Not reported
Conventional Contaminants, Organic:	Not reported
Conventional Contaminants, Inorganic:	Confirmed above MTCA cleanup levels

Facility ID: 2050
Responsible Unit: NW
Latitude: 47 32 20
Longitude: 122 19 14

Ecology Site Status relative to the MTCA cleanup process:

Independent Remedial Action

Independent Site Status - those sites undergoing an independent cleanup:

Independent Site Assessment of Interim Remedial Action Report received

WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):

5 - Lowest assessed risk to human health and to the environment

Affected Media: Sediments

Media Status: C (Confirmed) - The presence of hazardous substances above MTCA cleanup levels has been confirmed by laboratory analysis (or field determination in the case of petroleum contamination)

Arsenic Code: Not reported

Base/Neutral/Acid Organics:	Not reported
Halogenated Organic Compounds:	Confirmed above MTCA cleanup levels
Horizontal Collection Method:	3
EPA Priority Pollutants - Metals and Cyanide:	Confirmed above MTCA cleanup levels
Metals - Other non-priority pollutant medals:	Suspected to be present
Polychlorinated biPhenyls (PCBs):	Confirmed above MTCA cleanup levels
Pesticides:	Not reported
Petroleum Products:	Confirmed above MTCA cleanup levels
Phenolic Compounds:	Not reported
Non-Halogenated Solvents:	Confirmed above MTCA cleanup levels
Dioxin:	Suspected to be present
Polynuclear Aromatic Hydrocarbons (PAH):	Not reported
Reactive Wastes:	Not reported
Corrosive Wastes:	Confirmed above MTCA cleanup levels
Radioactive Wastes:	Not reported
Asbestos:	Not reported
Conventional Contaminants, Organic:	Not reported
Conventional Contaminants, Inorganic:	Confirmed above MTCA cleanup levels

Facility ID: 2050
Responsible Unit: NW
Latitude: 47 32 20
Longitude: 122 19 14

Ecology Site Status relative to the MTCA cleanup process:

Independent Remedial Action

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

BOEING NORTH FIELD (Continued)

S102363853

Independent Site Status - those sites undergoing an independent cleanup:
Independent Site Assessment of Interim Remedial Action Report received
WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):
5 - Lowest assessed risk to human health and to the environment
Affected Media: Soil
Media Status: C (Confirmed) - The presence of hazardous substances above MTCA cleanup levels has been confirmed by laboratory analysis (or field determination in the case of petroleum contamination)
Arsenic Code: Not reported
Base/Neutral/Acid Organics: Not reported
Halogenated Organic Compounds: Confirmed above MTCA cleanup levels
Horizontal Collection Method: 3
EPA Priority Pollutants - Metals and Cyanide: Confirmed above MTCA cleanup levels
Metals - Other non-priority pollutant metals: Suspected to be present
Polychlorinated biPhenyls (PCBs): Suspected to be present
Pesticides: Not reported
Petroleum Products: Confirmed above MTCA cleanup levels
Phenolic Compounds: Not reported
Non-Halogenated Solvents: Confirmed above MTCA cleanup levels
Dioxin: Suspected to be present
Polynuclear Aromatic Hydrocarbons (PAH): Not reported
Reactive Wastes: Not reported
Corrosive Wastes: Confirmed above MTCA cleanup levels
Radioactive Wastes: Not reported
Asbestos: Not reported
Conventional Contaminants, Organic: Not reported
Conventional Contaminants, Inorganic: Confirmed above MTCA cleanup levels

Facility ID: 2050
Responsible Unit: NW
Latitude: 47 32 20
Longitude: 122 19 14

Ecology Site Status relative to the MTCA cleanup process:
Independent Remedial Action

Independent Site Status - those sites undergoing an independent cleanup:
Independent Site Assessment of Interim Remedial Action Report received
WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):
5 - Lowest assessed risk to human health and to the environment

Affected Media: Surface Water
Media Status: S (Suspected) - Due to preliminary investigations or the nature of business operations or manufacturing processes, certain contaminants are suspected to be present at the site

Arsenic Code: Not reported
Base/Neutral/Acid Organics: Not reported
Halogenated Organic Compounds: Suspected to be present
Horizontal Collection Method: 3
EPA Priority Pollutants - Metals and Cyanide: Suspected to be present
Metals - Other non-priority pollutant metals: Suspected to be present
Polychlorinated biPhenyls (PCBs): Suspected to be present
Pesticides: Not reported
Petroleum Products: Suspected to be present
Phenolic Compounds: Not reported
Non-Halogenated Solvents: Suspected to be present
Dioxin: Suspected to be present
Polynuclear Aromatic Hydrocarbons (PAH): Not reported
Reactive Wastes: Not reported
Corrosive Wastes: Suspected to be present

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

THOMAS EQUIPMENT RENTAL (Continued)

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:

Facility Registry System (FRS)

Resource Conservation and Recovery Act Information system (RCRAINFO)

Database(s)

EDR ID Number

EPA ID Number

1000878467

AB113
WNW
1/2-1
3019 ft.
Lower

7912 7TH AVE SO AAA TRACTOR SALES
SEATTLE, WA

Site 1 of 2 in cluster AB

WA SPILL:

Facility ID: 510430
Date Received: 04/18/2000
Business Name: HEAVY EQUIPMENT RENTAL/REFURBISH
Material Desc : PETROLEUM - OIL OTHER
Medium: SURFACE WATER-FRESH
Material Qty: Not reported
Material Units: Not reported

SPILLS

S105392606

N/A

Y114
WNW
1/2-1
3023 ft.
Lower

SOUTH PARK TRUCK & TRAILER REPAIR
722 S CHICAGO ST
SEATTLE, WA 98108

Site 2 of 2 in cluster Y

RCRIS:

Owner: SOUTH PARK TRUCK TRAILER REPAIR
(360) 555-1212
EPA ID: WA0000360198
Contact: WENDY CULVER
(206) 767-2974

Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:

Facility Registry System (FRS)

Resource Conservation and Recovery Act Information system (RCRAINFO)

RCRIS-SQG

1001491395

FINDS

WA0000360198

AA115
South
1/2-1
3027 ft.
Higher

PSF INDUSTRIES INC FIELD YARD
9332 14TH AVE S
SEATTLE, WA 98108

Site 2 of 2 in cluster AA

FINDS

1005106605

000009111128

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

Site Database(s) EDR ID Number
EPA ID Number

PSF INDUSTRIES INC FIELD YARD (Continued)

1005106605

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)

AB116
WNW
1/2-1
3032 ft.
Lower

TIERNEY ELECTRICAL MFG CO
7901 7TH AVE S
SEATTLE, WA 98108

FINDS 1005106824
000009113716

Site 2 of 2 in cluster AB

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)

AC117
South
1/2-1
3080 ft.
Higher

DUWAMISH MANOR
15TH AVE S & S 93RD ST
SEATTLE, WA 98108

RCRIS-SQG 1000838300
FINDS WAD988510673

Site 1 of 3 in cluster AC

RCRIS:

Owner: DUWAMISH MANOR & ASSOC
(360) 555-1212
EPA ID: WAD988510673
Contact: BIRNEY DEMPCY
(425) 453-6371

Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSD Activities: Not reported
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

AD118
NNW
1/2-1
3084 ft.
Lower

LE TRACON ENVIROMENTAL INC
7343 E MARGINAL WAY S
SEATTLE, WA 98108

RCRIS-SQG 1000418406
FINDS WAD980723324

Site 1 of 3 in cluster AD

RCRIS:

Owner: CONNIE VALADEZ
(206) 832-3027
EPA ID: WAD980723324
Contact: JIM MUWWELL
(206) 832-3032

Classification: Small Quantity Generator
Used Oil Recyc: No
TSD Activities: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

LE TRACON ENVIROMENTAL INC (Continued)

1000418406

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:

Facility Registry System (FRS)

Resource Conservation and Recovery Act Information system (RCRAINFO)

AD119
NNW
1/2-1
3084 ft.
Lower

EVERGREEN MARINE LEASING
7343 E MARGINAL WAY
SEATTLE, WA 98108

UST U003027782
CSCSL NFA N/A
WA ICR

Site 2 of 3 in cluster AD

WA NFA:

Facility/Site Id : 2462
Ecology Status : Independent Remedial Action
Independent Status Code : Final Independent RA Report received
WARM Bin Number : Not reported
NFA Code : NFA after Assesment IRAP or VCP
NFA Date : 10/21/1997 00:00:00

WA ICR:

Date Ecology Received Report: 10/24/1991
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 92-10
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 03/09/1998
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Final cleanup report
Site Register Issue: 98-03
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 03/09/1998
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Final cleanup report
Site Register Issue: 98-04
County Code: 17
Contact: Not reported
Report Title: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

EVERGREEN MARINE LEASING (Continued)

EDR ID Number
EPA ID Number

Database(s)

U003027782

UST:

Facility ID: 6485
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: Not reported
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 6485
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: Not reported
Substance: NW
Compartment #: Not reported
Ecology Region: 1

AD120
NNW
1/2-1
3084 ft.
Lower

EMERALD SERVICES
7343 E MARGINAL WAY S
SEATTLE, WA 98103

PADS 1001490301
RCRIS-SQG WAD058364647
FINDS

Site 3 of 3 in cluster AD

RCRIS:

Owner: EMERALD SERVICES
EPA ID: WAD058364647
Contact: JERRY BARTLETT
(206) 832-3000

Classification: Handler transports wastes for hire, Small Quantity Generator
Used Oil Recyc: Yes
TSDF Activities: Not reported
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

AE121
WSW
1/2-1
3103 ft.
Higher

SEATTLE SCHOOL DIST 1 CONCORD ELEMENTARY
723 S CONCORD ST
SEATTLE, WA 98108

FINDS 1005099160
000009024548

Site 1 of 2 in cluster AE

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)

AE122
WSW
1/2-1
3103 ft.
Higher

SEATTLE SCHOOL DIST 1 CONCORD ELEMENTARY
723 S CONCORD ST
SEATTLE, WA 98108

RCRIS-SQG 1001600562
WAH000008748

Site 2 of 2 in cluster AE

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

SEATTLE SCHOOL DIST 1 CONCORD ELEMENTARY (Continued)

EDR ID Number
EPA ID Number

Database(s)

1001600562

RCRIS:

Owner: SEATTLE SCHOOL DIST 1
(206) 298-7529
EPA ID: WAH000008748
Contact: DAVID WICK
(206) 298-7529

Classification: Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported
Violation Status: No violations found

AC123
South
1/2-1
3124 ft.
Higher

FEDERAL EXPRESS CORP BFI
9320 15TH AVE S
SEATTLE, WA 98108

Site 2 of 3 in cluster AC

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)

FINDS 1004612932
WAR000011718

AC124
South
1/2-1
3124 ft.
Higher

DESIGN DIRECT SOUND INC
9320 15TH AVE S UNITS C-E
SEATTLE, WA 98108

Site 3 of 3 in cluster AC

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)

FINDS 1005106412
000009108954

AF125
South
1/2-1
3145 ft.
Higher

US EPA TECHNICAL ASSISTANCE TEAM WHSE
1605 S 93RD BLDG E UNIT R
SEATTLE, WA 98108

Site 1 of 4 in cluster AF

RCRIS:

Owner: US EPA TECHNICAL ASSISTANCE TEAM WHSE
EPA ID: WAD981770977
Contact: CHRIS FIELD
(206) 553-1263

Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported

RCRIS-SQG 1000344874
FINDS WAD981770977

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

US EPA TECHNICAL ASSISTANCE TEAM WHSE (Continued)

EDR ID Number
EPA ID Number

Database(s)

Violation Status: No violations found

1000344874

FINDS:

Other Pertinent Environmental Activity Identified at Site:

Facility Registry System (FRS)

Resource Conservation and Recovery Act Information system (RCRAINFO)

AF126
South
1/2-1
3145 ft.
Higher

OLSEN RODNEY
1605 S 93RD ST BLDG E UNIT R
SEATTLE, WA 98108

RCRIS-SQG 1000314712
FINDS WAD980724462

Site 2 of 4 in cluster AF

RCRIS:

Owner: OLSEN RODNEY
(503) 555-1212

EPA ID: WAD980724462

Contact: RODNEY OLSEN
(206) 784-8391

Classification: Small Quantity Generator

Used Oil Recyc: No

TSDF Activities: Not reported

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:

Facility Registry System (FRS)

Resource Conservation and Recovery Act Information system (RCRAINFO)

AF127
South
1/2-1
3145 ft.
Higher

DEOX
1605 S 93RD ST BLDG EC
SEATTLE, WA 98108

RCRIS-SQG 1001491156
WAH000007484

Site 3 of 4 in cluster AF

RCRIS:

Owner: DEOX
(206) 762-8631

EPA ID: WAH000007484

Contact: RICHARD WEST
(206) 762-8631

Classification: N, Small Quantity Generator

Used Oil Recyc: No

TSDF Activities: Not reported

Violation Status: No violations found

AF128
South
1/2-1
3145 ft.
Higher

DEOX
1605 S 93RD ST BLDG EC
SEATTLE, WA 98108

FINDS 1005077091
000008732342

Site 4 of 4 in cluster AF

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

DEOX (Continued)

EDR ID Number
EPA ID Number

Database(s)

1005077091

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)

AG129
WNW
1/2-1
3153 ft.
Lower

7800 7TH AVE SO
SEATTLE, WA

Site 1 of 5 in cluster AG

WA SPILL:

Facility ID: 507470
Date Received: 11/01/1999
Business Name: OLYMPIC STEEL DOOR
Material Desc : PETROLEUM - GASOLINE
Medium: SOIL
Material Qty: Not reported
Material Units: Not reported

SPILLS S105390910
N/A

AG130
WNW
1/2-1
3153 ft.
Lower

OLYMPIC STEEL DOOR
7800 7TH AVE S
SEATTLE, WA 98108

Site 2 of 5 in cluster AG

LUST:

Facility ID: 516774 Ecology Region: North Western
Release ID: 516776 Release Date: 11/1/1999 00:00:00
Release Status: Awaiting Cleanup Status Date: 11/29/1999 00:00:00
Alternate Name: OLYMPIC STEEL DOOR (FORMERLY NW CONTRACT PKG)
Affected Media: Soil

Facility ID: 516774 Ecology Region: North Western
Release ID: 516776 Release Date: 11/1/1999 00:00:00
Release Status: Awaiting Cleanup Status Date: 11/29/1999 00:00:00
Alternate Name: OLYMPIC STEEL DOOR (FORMERLY NW CONTRACT PKG)
Affected Media: Ground Water

UST:

Facility ID: 516774
Install Date: Not reported
Capacity: 2,001 TO 4,999 GALLONS
Status: Not reported
Tank Name: OTHER PETROLEUM SUBSTANCE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

UST U003710143
LUST N/A

AG131
WNW
1/2-1
3153 ft.
Lower

7TH S / CHICAGO S
SEATTLE, WA

Site 3 of 5 in cluster AG

WA SPILL:

Facility ID: 524155
Date Received: 02/06/2002
Business Name: Not reported

SPILLS S105400312
N/A

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

(Continued)

Material Desc : CHEMICAL
Medium: OTHER
Material Qty: Not reported
Material Units: Not reported

Database(s)

EDR ID Number
EPA ID Number

S105400312

AG132
WNW
1/2-1
3153 ft.
Lower

WASHINGTON LIFTRUCK INC
700 S CHICAGO ST
SEATTLE, WA 98108

RCRIS-SQG 1000891989
FINDS WA0000261735

Site 4 of 5 in cluster AG

RCRIS:

Owner: WASHINGTON LIFTRUCK INC
(206) 762-2040
EPA ID: WA0000261735
Contact: JOHN KURTTI
(206) 762-2040

Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

133
West
1/2-1
3165 ft.
Lower

SNYDER INDUSTRIES INC
524 S SOUTHERN
SEATTLE, WA 98108

RCRIS-SQG 1001203878
FINDS WAH000000125

RCRIS:

Owner: SNYDER INDUSTRIES INC
EPA ID: WAH000000125
Contact: LYLE SNYDER
(206) 762-6363

Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

134
South
1/2-1
3171 ft.
Higher

DUWAMISH MANOR INDUSTRIAL PARK
1505 S 93RD
SEATTLE, WA 98018

RCRIS-SQG 1001031740
FINDS WAR000004523

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

DUWAMISH MANOR INDUSTRIAL PARK (Continued)

1001031740

RCRIS:

Owner: WA STATE
(360) 555-1212
EPA ID: WAR000004523
Contact: SUSANNE WINTER
(425) 649-7141
Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Resource Conservation and Recovery Act Information system (RCRAINFO)

AH135
NW
1/2-1
3203 ft.
Lower

**LUKAS MACHINE INC
707 S RIVERSIDE DR
SEATTLE, WA 98108**

Site 1 of 3 in cluster AH

RCRIS-SQG 1000157559
FINDS WAD045331063

RCRIS:

Owner: LUKAS MACHINE INC
(206) 763-9282
EPA ID: WAD045331063
Contact: BRENDA LUKAS
(206) 763-9282
Classification: Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

AG136
WNW
1/2-1
3213 ft.
Lower

**WEST COAST WIRE ROPE RIGGING
7777 7TH AVE S
SEATTLE, WA 98108**

Site 5 of 5 in cluster AG

RCRIS-SQG 1000391701
FINDS WAD027483775

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

WEST COAST WIRE ROPE RIGGING (Continued)

EDR ID Number
EPA ID Number

Database(s)

1000391701

RCRIS:

Owner: WEST COAST WIRE ROPE RIGGING

(206) 767-4144

EPA ID: WAD027483775

Contact: KEN BRISSETTE

(206) 767-4144

Classification: N, Conditionally Exempt Small Quantity Generator

Used Oil Recyc: No

TSDF Activities: Not reported

Violation Status: Violations exist

Regulation Violated: Not reported

Area of Violation: GENERATOR-ALL REQUIREMENTS (OVERSIGHT)

Date Violation Determined: 09/29/1989

There are 1 violation record(s) reported at this site:

<u>Evaluation</u>	<u>Area of Violation</u>
Non-Financial Record Review	GENERATOR-ALL REQUIREMENTS (OVERSIGHT)

Date of
Compliance
10/15/198

FINDS:

Other Pertinent Environmental Activity Identified at Site:

Facility Registry System (FRS)

Resource Conservation and Recovery Act Information system (RCRAINFO)

AH137
NW
1/2-1
3216 ft.
Lower

HURLEN CONSTRUCTION COMPANY
700 SO RIVERSIDE DR/PO BOX 90045
SEATTLE, WA 98108

UST U000595406
LUST N/A

Site 2 of 3 in cluster AH

LUST:

Facility ID: 11414

Release ID: 4756

Release Status: Cleanup Started

Alternate Name: HURLEN CONSTRUCTION

Affected Media: Soil

Ecology Region: North Western

Release Date: 4/30/1993 00:00:00

Status Date: 6/1/1995 00:00:00

Facility ID: 11414

Release ID: 4756

Release Status: Reported Cleaned Up

Alternate Name: HURLEN CONSTRUCTION

Affected Media: Soil

Ecology Region: North Western

Release Date: 4/30/1993 00:00:00

Status Date: 12/6/2000 00:00:00

UST:

Facility ID: 11414

Install Date: 2/1/1980 0:00

Capacity: Not reported

Status: Not reported

Tank Name: Not reported

Substance: NW

Compartment #: Not reported

Ecology Region: 1

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

HURLEN CONSTRUCTION COMPANY (Continued)

EDR ID Number
EPA ID Number

Database(s)

U000595406

Facility ID: 11414
Install Date: 2/1/1980 0:00
Capacity: Not reported
Status: Not reported
Tank Name: LEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

AH138
NW
1/2-1
3216 ft.
Lower

HURLEN CONSTRUCTION
700 S RIVERSIDE DR
SEATTLE, WA 98108

Site 3 of 3 in cluster AH

RCRIS-SQG
FINDS
WA ICR

1000839003
WAD988518239

RCRIS:

Owner: HURLEN CONSTRUCTION
(360) 555-1212
EPA ID: WAD988518239
Contact: SCOTT MCKELLAR
(206) 763-1230

Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSD Activities: Not reported
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

WA ICR:

Date Ecology Received Report: 04/30/1993
Contaminants Found at Site: Petroleum products
Media Contaminated: Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 93-11
County Code: 17
Contact: Not reported
Report Title: Not reported

139
NW
1/2-1
3220 ft.
Lower

HANSEN MACHINE CORP SEATTLE
712 S PORTLAND ST
SEATTLE, WA 98108

RCRIS-SQG
FINDS

1000379862
WAD063375380

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

HANSEN MACHINE CORP SEATTLE (Continued)

EDR ID Number
EPA ID Number

Database(s)

1000379862

RCRIS:

Owner: HANSEN MACHINE CORP
(360) 555-1212
EPA ID: WAD063375380
Contact: MICHAEL HANSEN
(206) 767-3775

Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

AI140
SSE
1/2-1
3226 ft.
Higher

PROPULSION CONTROLS ENGINEERIN
1705 S 93RD ST F10
SEATTLE, WA 98108

RCRIS-SQG 1000294758
FINDS WAD012061925

Site 1 of 4 in cluster AI

RCRIS:

Owner: PROPULSION CONTROLS ENGINEERING
(360) 555-1212
EPA ID: WAD012061925
Contact: THOMAS KOCIR
(206) 762-8562

Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Resource Conservation and Recovery Act Information system (RCRAINFO)

AI141
SSE
1/2-1
3226 ft.
Higher

PROFESSIONAL COATING INC
1705 S 93RD ST F-22
SEATTLE, WA 98108

EMI S104155877
N/A

Site 2 of 4 in cluster AI

WA AIR EMISSIONS:

Facility ID: 0263
SO2 Chemical: 0
VOC Chemical: 31
PM10 Chemical: 0

Local ID: C
NO2 Chemical: 0
CO Chemical: 0

Mailing Name: PROFESSIONAL COATING INC
1705 SOUTH 93RD F-22
SEATTLE, 53 98108

Year Of Info: 96
Mail Add Zip 2: Not reported
Point Num: Not reported

Point Desc: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

PROFESSIONAL COATING INC (Continued)

S104155877

Tot Suspended Particulate Tons/Yr: Not reported

AI142
SSE
1/2-1
3226 ft.
Higher

PROFESSIONAL COATING INC
1705 S 93RD F-22
SEATTLE, WA 98108

EMI S102456359
N/A

Site 3 of 4 in cluster AI

WA AIR EMISSIONS:

Facility ID:	0263	Local ID:	C
SO2 Chemical:	0.0000	NO2 Chemical:	0.0000
VOC Chemical:	30.7425	CO Chemical:	0.0000
PM10 Chemical:	0.0000		

Mailing Name: PROFESSIONAL COATING INC
1705 SOUTH 93RD F-22
SEATTLE, 53 98108

Year Of Info:	Not reported	Point Desc:	Not reported
Mail Add Zip 2:	Not reported		
Point Num:	Not reported		
Tot Suspended Particulate Tons/Yr:	Not reported		

Facility ID:	Not reported	Local ID:	Not reported
SO2 Chemical:	Not reported	NO2 Chemical:	Not reported
VOC Chemical:	Not reported	CO Chemical:	Not reported
PM10 Chemical:	Not reported		

Mailing Name: PROFESSIONAL COATING INC
1705 SOUTH 93RD F-22
SEATTLE, 53

Year Of Info:	Not reported	Point Desc:	Not reported
Mail Add Zip 2:	Not reported		
Point Num:	Not reported		
Tot Suspended Particulate Tons/Yr:	Not reported		

AI143
SSE
1/2-1
3226 ft.
Higher

PROFESSIONAL COATING INC
1705 S 93RD ST F22
SEATTLE, WA 98108

FINDS 1000228677
RCRIS-LQG WAD981772247

Site 4 of 4 in cluster AI

RCRIS:

Owner: RONALD MCNAUGHT JR
(425) 277-3097

EPA ID: WAD981772247

Contact: PAUL SPARKS
(206) 763-2880

Classification: N, Large Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported

BIENNIAL REPORTS:

Last Biennial Reporting Year: 1999

Waste	Quantity (Lbs)	Waste	Quantity (Lbs)
D001	33443.00	D035	29180.00
F003	33443.00	F005	33443.00

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

PROFESSIONAL COATING INC (Continued)

1000228677

Violation Status: Violations exist

Regulation Violated:	630(5)
Area of Violation:	GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined:	08/17/1999
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	09/08/1999
Penalty Type:	Not reported
Regulation Violated:	200(1)cd
Area of Violation:	GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined:	08/17/1999
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	09/08/1999
Penalty Type:	Not reported
Regulation Violated:	340(3)
Area of Violation:	GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined:	08/17/1999
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	09/08/1999
Penalty Type:	Not reported
Regulation Violated:	200(2)(c)
Area of Violation:	GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined:	08/12/1998
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	09/02/1998
Penalty Type:	Not reported
Regulation Violated:	200(1)(b) & 630(5)(a)
Area of Violation:	GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined:	08/12/1998
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	09/02/1998
Penalty Type:	Not reported
Regulation Violated:	200(1)(d)
Area of Violation:	GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined:	08/12/1998
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	09/02/1998
Penalty Type:	Not reported
Regulation Violated:	200(1)(c)
Area of Violation:	GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined:	08/12/1998
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	09/02/1998
Penalty Type:	Not reported
Regulation Violated:	200(1)(b) & 630(6)
Area of Violation:	GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined:	08/12/1998
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	09/02/1998
Penalty Type:	Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

PROFESSIONAL COATING INC (Continued)

EDR ID Number
EPA ID Number

Database(s)

1000228677

Regulation Violated: 200(1)(e) & 330
Area of Violation: GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined: 08/12/1998
Enforcement Action: WRITTEN INFORMAL
Enforcement Action Date: 09/02/1998
Penalty Type: Not reported
Regulation Violated: 200(1)(e) & 350, 360
Area of Violation: GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined: 08/12/1998
Enforcement Action: WRITTEN INFORMAL
Enforcement Action Date: 09/02/1998
Penalty Type: Not reported
Regulation Violated: 200(1)(b) & 630(5)(c)
Area of Violation: GENERATOR-ALL REQUIREMENTS (OVERSIGHT)
Date Violation Determined: 08/12/1998
Enforcement Action: WRITTEN INFORMAL
Enforcement Action Date: 09/02/1998
Penalty Type: Not reported

There are 11 violation record(s) reported at this site:

<u>Evaluation</u>	<u>Area of Violation</u>	<u>Date of Compliance</u>
Compliance Evaluation Inspection	GENERATOR-GENERAL REQUIREMENTS	08/20/199
	GENERATOR-GENERAL REQUIREMENTS	08/20/199
	GENERATOR-GENERAL REQUIREMENTS	08/20/199
Compliance Evaluation Inspection	GENERATOR-GENERAL REQUIREMENTS	10/06/199
	GENERATOR-GENERAL REQUIREMENTS	10/06/199
	GENERATOR-GENERAL REQUIREMENTS	10/06/199
	GENERATOR-GENERAL REQUIREMENTS	10/06/199
	GENERATOR-GENERAL REQUIREMENTS	10/06/199
	GENERATOR-GENERAL REQUIREMENTS	10/19/199
	GENERATOR-GENERAL REQUIREMENTS	11/10/199
	GENERATOR-GENERAL REQUIREMENTS	11/12/199
	GENERATOR-ALL REQUIREMENTS (OVERSIGHT)	11/09/199

FINDS:

Other Pertinent Environmental Activity Identified at Site:

AIRS Facility System (AIRS/AFS)
Biennial Reporting System (BRS)
Facility Registry System (FRS)
National Emissions Trends (NET)
Resource Conservation and Recovery Act Information system (RCRAINFO)

AJ144
NNW
1/2-1
3252 ft.
Lower

KING COUNTY AIRPORT OLD GAS STATION)
7300 E. MARGINAL WAY S.
SEATTLE, WA 98108

WA ICR S104486991
N/A

Site 1 of 2 in cluster AJ

WA ICR:

Date Ecology Received Report: 05/21/1993
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 93-07

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

KING COUNTY AIRPORT OLD GAS STATION) (Continued)

EDR ID Number
EPA ID Number

Database(s)

S104486991

County Code: 17
Contact: Not reported
Report Title: Not reported

AJ145
NNW
1/2-1
3252 ft.
Lower

VIC MARKOV TIRE CO.
7300 E MARGINAL WY SO
SEATTLE, WA 98108

Site 2 of 2 in cluster AJ

UST U003028463
LUST N/A

LUST:

Facility ID: 8342 Ecology Region: North Western
Release ID: 4431 Release Date: 5/19/1993 00:00:00
Release Status: Cleanup Started Status Date: 5/19/1993 00:00:00
Alternate Name: KING CO AIRPORT OLD GAS STATION
Affected Media: Ground Water

Facility ID: 8342 Ecology Region: North Western
Release ID: 4431 Release Date: 5/19/1993 00:00:00
Release Status: Monitoring Status Date: 6/1/1995 00:00:00
Alternate Name: KING CO AIRPORT OLD GAS STATION
Affected Media: Ground Water

UST:

Facility ID: 8342
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: LEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 8342
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: AVIATION FUEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 8342
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: Not reported
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

VIC MARKOV TIRE CO. (Continued)

EDR ID Number
EPA ID Number

Database(s)

U003028463

Facility ID: 8342
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: LEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 8342
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: LEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

AK146
SSW
1/2-1
3271 ft.
Higher

MORGAN TRUCKING INC SEATTLE
9228 10TH AVE S
SEATTLE, WA 98108

RCRIS-SQG 1000659947
FINDS WAD988496261

Site 1 of 3 in cluster AK

RCRIS:

Owner: K2 CORP
(360) 555-1212
EPA ID: WAD988496261
Contact: STEVE SUNDE
(360) 463-3631

Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSD Activities: Not reported
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

AK147
SSW
1/2-1
3271 ft.
Higher

MORGAN TRUCKING, INC.
9228 10TH AVE S
SEATTLE, WA 98108

UST U003028495
N/A

Site 2 of 3 in cluster AK

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

MORGAN TRUCKING, INC. (Continued)

Database(s)

EDR ID Number
EPA ID Number

U003028495

UST:

Facility ID: 844
Install Date: 12/5/1979 0:00
Capacity: 10,000 TO 19,999 GALLONS
Status: Not reported
Tank Name: DIESEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 844
Install Date: 12/5/1979 0:00
Capacity: 2,001 TO 4,999 GALLONS
Status: Not reported
Tank Name: UNLEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

AK148 9228 10TH AVE. SO.
SSW 9228 10TH AVE. SO.
1/2-1 SEATTLE, WA 98198
3271 ft.
Higher Site 3 of 3 in cluster AK

ERNS 93305890
N/A

149 MCKINSTRY CO S BARTON ST
SSW 855 S BARTON ST
1/2-1 SEATTLE, WA 98108
3315 ft.
Higher

RCRIS-SQG 1000270974
FINDS WAD055496004
UST

RCRIS:

Owner: GEORGE ALLEN
(206) 762-3311
EPA ID: WAD055496004
Contact: GARY FADDEN SR
(206) 762-3311
Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Biennial Reporting System (BRS)
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

MCKINSTRY CO S BARTON ST (Continued)

1000270974

UST:

Facility ID: 8958
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: LEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 8958
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: UNLEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

AL150 1801 S. 93RD
SSE 1801 S. 93RD
1/2-1 SEATTLE, WA
3328 ft.
Higher Site 1 of 3 in cluster AL

ERNS 91215520
N/A

AL151 1801 SOUTH 93RD ST IN THE DUWAMISH RIVER NEAR THE DUWAMISH Y
SSE 1801 SOUTH 93RD ST IN THE DUWAMISH RIVER NEAR THE DUWAMISH Y
1/2-1 SEATTLE, WA
3328 ft.
Higher Site 2 of 3 in cluster AL

ERNS 8855001
N/A

152 ABC METAL FINISHING
WNW 501 ELMGROVE S
1/2-1 SEATTLE, WA 98108
3329 ft.
Lower

RCRIS-SQG 1000421938
FINDS WAD981768435

RCRIS:

Owner: ABC METAL FINISHING INC
(360) 555-1212
EPA ID: WAD981768435
Contact: ALLEN CODLING
(206) 282-8762
Classification: Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ABC METAL FINISHING (Continued)

1000421938

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:

Facility Registry System (FRS)

Resource Conservation and Recovery Act Information system (RCRAINFO)

AL153
SSE
1/2-1
3350 ft.
Higher

GLOBAL INTERMODAL SYSTEMS
1818 S 93RD ST
SEATTLE, WA 98108

FINDS 1005106724
000009112550

Site 3 of 3 in cluster AL

FINDS:

Other Pertinent Environmental Activity Identified at Site:

Facility Registry System (FRS)

AM154
WNW
1/2-1
3383 ft.
Lower

BROWN ENGINEERING
550 S MONROE ST
SEATTLE, WA 98108

RCRIS-SQG 1001491121
WAH000007120

Site 1 of 7 in cluster AM

RCRIS:

Owner: BROWN ENGINEERING
(360) 555-1212

EPA ID: WAH000007120

Contact: LISA FARIN

Classification: N, Small Quantity Generator

Used Oil Recyc: No

TSD Activities: Not reported

Violation Status: No violations found

AM155
WNW
1/2-1
3383 ft.
Lower

BROWN ENGINEERING
550 S MONROE ST
SEATTLE, WA 98108

FINDS 1005077132
000008732774

Site 2 of 7 in cluster AM

FINDS:

Other Pertinent Environmental Activity Identified at Site:

Facility Registry System (FRS)

156
SSW
1/2-1
3385 ft.
Higher

ALL CITY AUTO WRECKING & SALES INC
9438 DES MOINES MEMORIAL DR
SEATTLE, WA 98108

RCRIS-SQG 1001491424
FINDS WA0000894238
CSCSL NFA

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

ALL CITY AUTO WRECKING & SALES INC (Continued)

1001491424

RCRIS:

Owner: ALL CITY AUTO WRECKING & SALES INC
EPA ID: WA0000894238
Contact: GARY HUMAN
(206) 767-9996

Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSD Activities: Not reported
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

WA NFA:

Facility/Site Id : 22342251
Ecology Status : Independent Remedial Action
Independent Status Code : Final Independent RA Report received
WARM Bin Number : Not reported
NFA Code : NFA after Assessment IRAP or VCP
NFA Date : 6/24/1999 00:00:00

AN157
SW
1/2-1
3391 ft.
Higher

WEST SEATTLE #28
9200 8TH AVE SO
SEATTLE, WA 98108
Site 1 of 7 in cluster AN

UST U001125219
LUST N/A

LUST:

Facility ID: 7932 Ecology Region: North Western
Release ID: 2872 Release Date: 7/11/1990 00:00:00
Release Status: Cleanup Started Status Date: 7/11/1990 00:00:00
Alternate Name: SEATTLE- W EST, MAINT HQ
Affected Media: Soil

Facility ID: 7932 Ecology Region: North Western
Release ID: 2872 Release Date: 7/11/1990 00:00:00
Release Status: Reported Cleaned Up Status Date: 9/27/1995 00:00:00
Alternate Name: SEATTLE- W EST, MAINT HQ
Affected Media: Soil

UST:

Facility ID: 7932
Install Date: 12/31/1956 0:00
Capacity: 111 TO 1,000 GALLONS
Status: Not reported
Tank Name: DIESEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

WEST SEATTLE #28 (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001125219

Facility ID: 7932
Install Date: 12/31/1956 0:00
Capacity: 2,001 TO 4,999 GALLONS
Status: Not reported
Tank Name: LEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

AN158
SW
1/2-1
3391 ft.
Higher

SEATTLE CITY TRANSMISSION W SEATTLE
9200 8TH AVE S
SEATTLE, WA 98108
Site 2 of 7 in cluster AN

RCRIS-SQG 1000421934
FINDS WAD981765183

RCRIS:

Owner: SEATTLE CITY ESD
(206) 684-0505
EPA ID: WAD981765183
Contact: STEVE FELLER
(206) 386-1203

Classification: Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

AM159
WNW
1/2-1
3405 ft.
Lower

KING AUTO & TRUCK WRECKING
543 S. MONROE ST
SEATTLE, WA 98108
Site 3 of 7 in cluster AM

FINDS 1005186366
000010195984

FINDS:

Other Pertinent Environmental Activity Identified at Site:
AIRS Facility System (AIRS/AFS)
Facility Registry System (FRS)

AM160
WNW
1/2-1
3405 ft.
Lower

KING AUTO TRUCK WRECKING
543 S MONROE
SEATTLE, WA 98108
Site 4 of 7 in cluster AM

CSCSL NFA S104971680
N/A

WA NFA:

Facility/Site Id : 2278
Ecology Status : Awaiting Site Hazard Assessment
Independent Status Code : Not reported
WARM Bin Number : Not reported
NFA Code : NFA after Assessment IRAP or VCP
NFA Date : 7/21/2000 00:00:00

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

AO161 MANITOWOC WESTERN COMPANY, INC.
West 8250 5TH AVE S
1/2-1 SEATTLE, WA 98108
3408 ft.
Lower Site 1 of 5 in cluster AO

UST U003152665
N/A

UST:

Facility ID: 11852
Install Date: 1/1/1973 0:00
Capacity: 111 to 1,100 Gallons
Status: Not reported
Tank Name: LEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 11852
Install Date: 1/1/1973 0:00
Capacity: 111 to 1,100 Gallons
Status: Not reported
Tank Name: UNLEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

AO162 MANITOWAK WESTERN
West 8250 5TH AVE S
1/2-1 SEATTLE, WA 98108
3408 ft.
Lower Site 2 of 5 in cluster AO

CSCSL S101856276
N/A

SHWS:

Facility ID: 2430
Responsible Unit: NW
Latitude: 47 31 44
Longitude: 122 19 41

Ecology Site Status relative to the MTCA cleanup process:
Awaiting Site Hazard Assessment (SHA)

Independent Site Status - those sites undergoing an independent cleanup:
Not reported

WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):
Not reported

Affected Media: Ground Water

Media Status: S (Suspected) - Due to preliminary investigations or the nature of business operations or manufacturing processes, certain contaminants are suspected to be present at the site

Arsenic Code: Not reported

Base/Neutral/Acid Organics: Not reported

Halogenated Organic Compounds: Not reported

Horizontal Collection Method: 3

EPA Priority Pollutants - Metals and Cyanide: Suspected to be present

Metals - Other non-priority pollutant metals: Not reported

Polychlorinated biPhenyls (PCBs): Not reported

Pesticides: Not reported

Petroleum Products: Suspected to be present

Phenolic Compounds: Not reported

Non-Halogenated Solvents: Not reported

Dioxin: Not reported

Polynuclear Aromatic Hydrocarbons (PAH): Not reported

Reactive Wastes: Not reported

Corrosive Wastes: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

MANITOWAK WESTERN (Continued)

EDR ID Number
EPA ID Number

Database(s)

S101856276

Radioactive Wastes: Not reported
Asbestos: Not reported
Conventional Contaminants, Organic: Not reported
Conventional Contaminants, Inorganic: Not reported

Facility ID: 2430
Responsible Unit: NW
Latitude: 47 31 44
Longitude: 122 19 41

Ecology Site Status relative to the MTCA cleanup process:

Awaiting Site Hazard Assessment (SHA)

Independent Site Status - those sites undergoing an independent cleanup:

Not reported

WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):

Not reported

Affected Media: Soil

Media Status: S (Suspected) - Due to preliminary investigations or the nature of business operations or manufacturing processes, certain contaminants are suspected to be present at the site

Arsenic Code: Not reported

Base/Neutral/Acid Organics: Not reported

Halogenated Organic Compounds: Not reported

Horizontal Collection Method: 3

EPA Priority Pollutants - Metals and Cyanide: Suspected to be present

Metals - Other non-priority pollutant metals: Not reported

Polychlorinated biPhenyls (PCBs): Not reported

Pesticides: Not reported

Petroleum Products: Suspected to be present

Phenolic Compounds: Not reported

Non-Halogenated Solvents: Not reported

Dioxin: Not reported

Polynuclear Aromatic Hydrocarbons (PAH): Not reported

Reactive Wastes: Not reported

Corrosive Wastes: Not reported

Radioactive Wastes: Not reported

Asbestos: Not reported

Conventional Contaminants, Organic: Not reported

Conventional Contaminants, Inorganic: Not reported

AO163
West
1/2-1
3408 ft.
Lower

MANITOWAK WESTERN
8250 5TH AVE S
SEATTLE, WA 98108

Site 3 of 5 in cluster AO

RCRIS-SQG 1001092048
FINDS WAR000006940
WA ICR

RCRIS:

Owner: MANITOWOC WESTERN
(360) 555-1212

EPA ID: WAR000006940

Contact: WAYNE CULVER
(206) 762-9011

Classification: Small Quantity Generator

Used Oil Recyc: No

TSDF Activities: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

MANITOWAK WESTERN (Continued)

1001092048

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

WA ICR:

Date Ecology Received Report: 12/08/1995
Contaminants Found at Site: Petroleum products
Media Contaminated: Soil
Cause of Contamination: Not reported
Region: North Western
Type of Report Ecology Received: Final cleanup report
Site Register Issue: 94-22
County Code: 17
Contact: Not reported
Report Title: Not reported

AP164
West
1/2-1
3412 ft.
Lower

5TH AVE S SULLIVAN
5TH AVE S & SULLIVAN
SEATTLE, WA 98108

RCRIS-SQG 1000199628
FINDS WAD981767288

Site 1 of 3 in cluster AP

RCRIS:

Owner: WA ECY
(360) 555-1212
EPA ID: WAD981767288
Contact: JEANNETTE BARRECA
(360) 459-6822

Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

AO165
West
1/2-1
3415 ft.
Lower

LONG PAINTING CO 5TH AVE
8230 5TH AVE S
SEATTLE, WA 98108

PADS 1000838306
RCRIS-SQG WAD988510731
FINDS

Site 4 of 5 in cluster AO

Map ID
Direction
Distance
Distance (ft.)
Elevation

Site

MAP FINDINGS

Database(s)

EDR ID Number
EPA ID Number

LONG PAINTING CO 5TH AVE (Continued)

1000838306

RCRIS:

Owner: LONG PAINTING CO
(206) 763-8050
EPA ID: WAD988510731
Contact: BRIAN VANCE
(206) 763-8050

Classification: Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
PCB Handler Activity Data System (PADS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

AP166
West
1/2-1
3415 ft.
Lower

RAZORE ENTERPRISES
500 SOUTH SULLIVAN
SEATTLE, WA 98108

UST U003028140
WA ICR N/A
LUST

Site 2 of 3 in cluster AP

LUST:

Facility ID: 7426 Ecology Region: North Western
Release ID: 2458 Release Date: 8/15/1991 00:00:00
Release Status: Cleanup Started Status Date: 8/15/1991 00:00:00
Alternate Name: RAZORE ENTERPRISES
Affected Media: Soil

Facility ID: 7426 Ecology Region: North Western
Release ID: 2458 Release Date: 8/15/1991 00:00:00
Release Status: Reported Cleaned Up Status Date: 6/1/1995 00:00:00
Alternate Name: RAZORE ENTERPRISES
Affected Media: Soil

WA ICR:

Date Ecology Received Report: 09/18/1991
Contaminants Found at Site: Petroleum products
Media Contaminated: Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 92-08
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 02/24/1993
Contaminants Found at Site: Petroleum products
Media Contaminated: Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Final cleanup report
Site Register Issue: 92-46
County Code: 17
Contact: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

RAZORE ENTERPRISES (Continued)

U003028140

Report Title: Not reported

Date Ecology Received Report: 09/16/1991
Contaminants Found at Site: Petroleum products
Media Contaminated: Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 92-07
County Code: 17
Contact: Not reported
Report Title: Not reported

UST:

Facility ID: 7426
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: Not reported
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 7426
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: Not reported
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 7426
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: Not reported
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 7426
Install Date: 12/31/1964 0:00
Capacity: 111 to 1,100 Gallons
Status: Not reported
Tank Name: USED OIL/WASTE OIL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

AP167 US DISPOSAL
West 500 S SULLIVAN ST
1/2-1 SEATTLE, WA 98108
3415 ft.
Lower Site 3 of 3 in cluster AP

FINDS 1004614209
 110005352518

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

US DISPOSAL (Continued)

Database(s)

EDR ID Number
EPA ID Number

1004614209

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)

AO168
West
1/2-1
3415 ft.
Lower

5TH AVE S SITE
8229 5TH AVE S
SEATTLE, WA 98108

RCRIS-SQG
FINDS

1000878864
WAD988521985

Site 5 of 5 in cluster AO

RCRIS:

Owner: WA ECY
(360) 555-1212
EPA ID: WAD988521985
Contact: DAVID MORA
(425) 649-7092

Classification: Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

169
WNW
1/2-1
3452 ft.
Lower

MARINE LUMBER SERVICE - SHOP
558 S KENYON ST
SEATTLE, WA 98108

UST
WA ICR
LUST

U002038025
N/A

LUST:

Facility ID: 102380 Ecology Region: North Western
Release ID: 5481 Release Date: 6/28/1994 00:00:00
Release Status: Cleanup Started Status Date: 6/1/1995 00:00:00
Alternate Name: MARINE LUMBER SERVICE S KENYON
Affected Media: Soil

Facility ID: 102380 Ecology Region: North Western
Release ID: 5481 Release Date: 6/28/1994 00:00:00
Release Status: Cleanup Started Status Date: 6/1/1995 00:00:00
Alternate Name: MARINE LUMBER SERVICE S KENYON
Affected Media: Ground Water

WA ICR:

Date Ecology Received Report: 06/28/1994
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 93-36
County Code: 17
Contact: Not reported
Report Title: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

MARINE LUMBER SERVICE - SHOP (Continued)

EDR ID Number
EPA ID Number

Database(s)

U002038025

UST:

Facility ID: 102380
Install Date: 7/15/1982 0:00
Capacity: Not reported
Status: Not reported
Tank Name: LEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 102380
Install Date: 7/15/1982 0:00
Capacity: Not reported
Status: Not reported
Tank Name: LEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

AN170
SW
1/2-1
3453 ft.
Higher

PUGET SOUND COATINGS INC
9400 8TH AVE S
SEATTLE, WA 98108

RCRIS-SQG 1000223624
UST WAD980975627
CSCSL NFA

Site 3 of 7 in cluster AN

RCRIS:

Owner: PUGET SOUND COATINGS INC
(360) 555-1212
EPA ID: WAD980975627
Contact: DONALD COLE
(206) 767-3800

Classification: Small Quantity Generator
Used Oil Recyc: No
TSD Activities: Not reported
Violation Status: No violations found

WA NFA:

Facility/Site Id : 13397378
Ecology Status : Independent Remedial Action
Independent Status Code : Final Independent RA Report received
WARM Bin Number : Not reported
NFA Code : NFA after Assessment IRAP or VCP
NFA Date : 3/30/1999 00:00:00

UST:

Facility ID: 3936
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: Not reported
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

AN171
SW
1/2-1
3453 ft.
Higher

PUGET SOUND COATINGS MACHINISTS DSR INC
9220 8TH AVE S
SEATTLE, WA 98108

Site 4 of 7 in cluster AN

WA AIR EMISSIONS:

Facility ID:	Not reported	Local ID:	Not reported
SO2 Chemical:	Not reported	NO2 Chemical:	Not reported
VOC Chemical:	Not reported	CO Chemical:	Not reported
PM10 Chemical:	Not reported		

Mailing Name: PUGET SOUND COATINGS (MACHINISTS DSR INC)
9220 8TH AVE S
SEATTLE, 53

Year Of Info:	Not reported		
Mail Add Zip 2:	Not reported		
Point Num:	Not reported	Point Desc:	Not reported
Tot Suspended Particulate Tons/Yr:	Not reported		

Facility ID:	0860	Local ID:	C
SO2 Chemical:	0	NO2 Chemical:	0
VOC Chemical:	45	CO Chemical:	0
PM10 Chemical:	3		

Mailing Name: PUGET SOUND COATINGS (MACHINISTS DSR INC)
9220 8TH AVE S
SEATTLE, 53 98108

Year Of Info:	96		
Mail Add Zip 2:	Not reported		
Point Num:	Not reported	Point Desc:	Not reported
Tot Suspended Particulate Tons/Yr:	Not reported		

AN172
SW
1/2-1
3453 ft.
Higher

PUGET SOUND COATINGS MACHINISTS INC
9220 8TH AV S
SEATTLE, WA 98108

Site 5 of 7 in cluster AN

RCRIS:

Owner: HUGH LABOSSIER
(425) 746-3832
EPA ID: WAD002838068
Contact: RICH TIEMAN
(206) 767-3800

Classification: N, Large Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported

BIENNIAL REPORTS:

Last Biennial Reporting Year: 1999

Waste	Quantity (Lbs)	Waste	Quantity (Lbs)
D001	26024.68	D035	26024.68
D039	326.61	F001	25698.07
F002	25698.07	F003	25698.07
F005	26024.68		

Database(s)
EDR ID Number
EPA ID Number

EMI S103531697
N/A

FINDS 1000223613
RCRIS-LQG 98020PGTSN92
TRIS
CSCSL NFA
WA ICR

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

PUGET SOUND COATINGS MACHINISTS INC (Continued)

1000223613

Violation Status: Violations exist

Regulation Violated:	-200(1)(b) / -630(6)
Area of Violation:	GENERATOR-RECORDKEEPING REQUIREMENTS
Date Violation Determined:	09/19/2001
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	09/25/2001
Penalty Type:	Not reported
Regulation Violated:	-515 / -630(7), -640(4)
Area of Violation:	GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined:	09/19/2001
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	09/25/2001
Penalty Type:	Not reported
Regulation Violated:	-200(1)(d)
Area of Violation:	GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined:	09/19/2001
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	09/25/2001
Penalty Type:	Not reported
Regulation Violated:	-170(1)(a) / -070(3)
Area of Violation:	GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined:	09/19/2001
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	09/25/2001
Penalty Type:	Not reported
Regulation Violated:	-200(1)(c)
Area of Violation:	GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined:	09/19/2001
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	09/25/2001
Penalty Type:	Not reported
Regulation Violated:	200(1)(c)(d)
Area of Violation:	GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined:	12/18/1997
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	01/07/1998
Penalty Type:	Not reported
Regulation Violated:	141
Area of Violation:	GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined:	12/18/1997
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	01/07/1998
Penalty Type:	Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation

Site

MAP FINDINGS

Database(s)

EDR ID Number
EPA ID Number

PUGET SOUND COATINGS MACHINISTS INC (Continued)

1000223613

There are 7 violation record(s) reported at this site:

<u>Evaluation</u>	<u>Area of Violation</u>	<u>Date of Compliance</u>
Compliance Evaluation Inspection	GENERATOR-RECORDKEEPING REQUIREMENTS	10/03/200
	GENERATOR-GENERAL REQUIREMENTS	10/29/200
	GENERATOR-GENERAL REQUIREMENTS	10/03/200
	GENERATOR-GENERAL REQUIREMENTS	10/03/200
	GENERATOR-GENERAL REQUIREMENTS	10/03/200
Compliance Evaluation Inspection	GENERATOR-GENERAL REQUIREMENTS	01/12/199
	GENERATOR-GENERAL REQUIREMENTS	01/23/199

FINDS:

Other Pertinent Environmental Activity Identified at Site:

AIRS Facility System (AIRS/AFS)
Biennial Reporting System (BRS)
Facility Registry System (FRS)
National Compliance Database (NCDB)
National Emissions Trends (NET)
National Toxics Inventory (NTI)
Resource Conservation and Recovery Act Information system (RCRAINFO)
Toxic Chemical Release Inventory System (TRIS)

WA NFA:

Facility/Site Id : 97263627
Ecology Status : Independent Remedial Action
Independent Status Code : Final Independent RA Report received
WARM Bin Number : Not reported
NFA Code : NFA after Assesment IRAP or VCP
NFA Date : 3/30/1999 00:00:00

WA ICR:

Date Ecology Received Report: 11/04/1992
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 92-37
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 02/01/1993
Contaminants Found at Site: Total petroleum hydrocarbons
Metals
Polynuclear aromatic hydrocarbons
Media Contaminated: Soil
Cause of Contamination: Not reported
Region: North Western
Type of Report Ecology Received: Not reported
Site Register Issue: 92-46
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 03/26/1999
Contaminants Found at Site: Petroleum products

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

PUGET SOUND COATINGS MACHINISTS INC (Continued)

1000223613

Media Contaminated: Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 98-14
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 02/03/1999
Contaminants Found at Site: Petroleum products
Media Contaminated: Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 98-14
County Code: 17
Contact: Not reported
Report Title: Not reported

AN173
SW
1/2-1
3453 ft.
Higher

PUGET SOUND COATINGS INC
9220 8TH AVE S
SEATTLE, WA 98108

FTTS 1004644363
N/A

Site 6 of 7 in cluster AN

FTTS:

Case Number: Not reported
Docket Number: 1091-10-02-325
Complaint Issued: 10/18/91
Complaint Closed: 03/18/92
Abatement Amount: 03/18/92
Proposed Penalty: 5000
Final Assessment: 5000
Final Order Date: 0
Close Date: 03/18/92
Violation: EPCRA, Nonreporting/Failure to RPT to EPA

FTTS Insp:

Region: 10
Inspected Date: 04/22/91
Insp Number: 04/22/91
Violation occurred: Yes
Inspector: ZILA
Investigation Type: EPCRA, Enforcement, SEE Conducted
Facility Function: Manufacturer
Investig Reason: Neutral Scheme, Region
Legislation Code: EPCRA

AN174
SW
1/2-1
3453 ft.
Higher

PUGET SOUND COATINGS MACHINISTS INC)
9220 8TH AVE S
SEATTLE, WA 98108

EMI S102456360
N/A

Site 7 of 7 in cluster AN

WA AIR EMISSIONS:

Facility ID: 0860
SO2 Chemical: 0.0000
VOC Chemical: 26.8935

Local ID: C
NO2 Chemical: 0.0000
CO Chemical: 0.0000

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

PUGET SOUND COATINGS MACHINISTS INC) (Continued)

EDR ID Number
EPA ID Number

Database(s)

PM10 Chemical: 2.9575
Mailing Name: PUGET SOUND COATINGS (MACHINISTS INC)
9220 8TH AVE S
SEATTLE, 53 98108
Year Of Info: Not reported
Mail Add Zip 2: Not reported
Point Num: Not reported
Tot Suspended Particulate Tons/Yr: Not reported

Point Desc: Not reported

S102456360

AM175
WNW
1/2-1
3456 ft.
Lower

VICTORY AUTO BUMPERS INC
526 S MONROE ST
SEATTLE, WA 98108

RCRIS-SQG 1000418004
FINDS WAD051236685

Site 5 of 7 in cluster AM

RCRIS:
Owner: VICTORY AUTO BUMPERS INC
(360) 555-1212
EPA ID: WAD051236685
Contact: BOYD COLEMAN
(206) 763-0962

Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Resource Conservation and Recovery Act Information system (RCRAINFO)

AM176
WNW
1/2-1
3456 ft.
Lower

AMERICAN PLASTICS
526 S. MONROE ST
SEATTLE, WA 98108

FINDS 1005186365
000010195974

Site 6 of 7 in cluster AM

FINDS:

Other Pertinent Environmental Activity Identified at Site:
AIRS Facility System (AIRS/AFS)
Facility Registry System (FRS)

AM177
WNW
1/2-1
3471 ft.
Lower

CHEMITRON
521 S. MONROE ST
SEATTLE, WA 98108

FINDS 1005186364
000010195964

Site 7 of 7 in cluster AM

FINDS:

Other Pertinent Environmental Activity Identified at Site:
AIRS Facility System (AIRS/AFS)
Facility Registry System (FRS)

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

AQ178
NW
1/2-1
3513 ft.
Lower

636 S RIVERSIDE DR
SEATTLE, WA

Site 1 of 4 in cluster AQ

WA SPILL:

Facility ID: 520282
Date Received: 08/14/2001
Business Name: MACHINE SHOP
Material Desc: PETROLEUM - OIL OTHER
Medium: OTHER
Material Qty: Not reported
Material Units: Not reported

SPILLS S105398435
N/A

179
WNW
1/2-1
3532 ft.
Lower

CUSTOM ROOFING, INC.
8001 5TH AVE S
SEATTLE, WA 98108

UST:

Facility ID: 4900
Install Date: 1/1/1980 0:00
Capacity: 1,101 TO 2,000 GALLONS
Status: Not reported
Tank Name: UNLEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 4900
Install Date: 1/1/1980 0:00
Capacity: 1,101 TO 2,000 GALLONS
Status: Not reported
Tank Name: UNLEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

UST U003027169
N/A

180
WSW
1/2-1
3576 ft.
Higher

RASMUSSEN EQUIP CO
8727 5TH AVE S
SEATTLE, WA 98108

RCRIS:

Owner: RASMUSSEN EQUIP CO
(360) 555-1212
EPA ID: WAR000006429
Contact: MICHAEL VAUGHN
(206) 762-3700

Classification: Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported

RCRIS-SQG 1001082076
FINDS WAR000006429

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

RASMUSSEN EQUIP CO (Continued)

EDR ID Number
EPA ID Number

Database(s)

1001082076

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:

Facility Registry System (FRS)

Resource Conservation and Recovery Act Information system (RCRAINFO)

181
SW
1/2-1
3578 ft.
Higher

**7TH AVE S / S DIRECTOR ST
SEATTLE, WA**

**SPILLS S105385660
N/A**

WA SPILL:

Facility ID: 429223
Date Received: 04/24/1998
Business Name: UNKNOWN
Material Desc : PETROLEUM - WASTE/USED OIL
Medium: SURFACE WATER-FRESH
Material Qty: Not reported
Material Units: Not reported

182
NW
1/2-1
3611 ft.
Lower

**S HOLDEN ABANDONED CONTAINER
750 BLK S HOLDEN ST AT DEADEND
SEATTLE, WA 98108**

**RCRIS-SQG 1000920559
FINDS WA0000463794**

RCRIS:

Owner: WA STATE
(360) 555-1212
EPA ID: WA0000463794
Contact: HATHOR WOODS
(425) 649-7141
Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:

Facility Registry System (FRS)

Resource Conservation and Recovery Act Information system (RCRAINFO)

AQ183
NW
1/2-1
3623 ft.
Lower

**605 SO RIVERSIDE DRIVE (MILLS MOVERS)
605 SO RIVERSIDE DRIVE
SEATTLE, WA 98108**

**UST U003025344
LUST N/A**

Site 2 of 4 in cluster AQ

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

605 SO RIVERSIDE DRIVE (MILLS MOVERS) (Continued)

EDR ID Number
EPA ID Number

Database(s)

U003025344

LUST:

Facility ID:	10341	Ecology Region:	North Western
Release ID:	510263	Release Date:	3/26/1999 00:00:00
Release Status:	Cleanup Started	Status Date:	2/26/1999 00:00:00
Alternate Name:	CROTHAMEL PROPERTY		
Affected Media:	Soil		

UST:

Facility ID:	10341
Install Date:	12/31/1964 0:00
Capacity:	111 TO 1,000 GALLONS
Status:	Not reported
Tank Name:	HEATING FUEL
Substance:	NW
Compartment #:	Not reported
Ecology Region:	1

AQ184
NW
1/2-1
3623 ft.
Lower

605 S RIVERSIDE DR, CROTHAMEL PROPERTY,
SEATTLE, WA

SPILLS S105388710
N/A

Site 3 of 4 in cluster AQ

WA SPILL:

Facility ID:	506822
Date Received:	03/26/1999
Business Name:	CROTHAMEL PROPERTY
Material Desc :	PETROLEUM - DIESEL FUEL
Medium:	SOIL
Material Qty:	Not reported
Material Units:	Not reported

AQ185
NW
1/2-1
3623 ft.
Lower

CROTHAMEL PROPERTY
605 S. RIVERSIDE DR.
SEATTLE, WA 98108

WA ICR S104485652
N/A

Site 4 of 4 in cluster AQ

WA ICR:

Date Ecology Received Report:	03/26/1999
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Soil
Cause of Contamination:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	98-17
County Code:	17
Contact:	Not reported
Report Title:	Not reported

AR186
WNW
1/2-1
3632 ft.
Lower

MARINE LUMBER SERVICE INC.
525 S CHICAGO ST /PO BOX 80964
SEATTLE, WA 98108

LUST S104155736
N/A

Site 1 of 3 in cluster AR

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

MARINE LUMBER SERVICE INC. (Continued)

EDR ID Number
EPA ID Number

Database(s)

S104155736

LUST:

Facility ID: 11327 Ecology Region: North Western
Release ID: 5286 Release Date: 6/3/1994 00:00:00
Release Status: Cleanup Started Status Date: 6/1/1995 00:00:00
Alternate Name: MARINE LUMBER SERVICE CHICAGO
Affected Media: Soil

**AS187
NNW
1/2-1
3632 ft.
Lower**

**SAMSON TUG & BARGE CO INC
7400 8TH AVE S
SEATTLE, WA 98108**

**PADS 1000385127
RCRIS-SQG WAD980981849
FINDS**

Site 1 of 6 in cluster AS

RCRIS:

Owner: CROWLEY MARITIME CORP
(800) 248-8632
EPA ID: WAD980981849
Contact: MICHAEL DROBKA
(206) 767-7820

Classification: Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
PCB Handler Activity Data System (PADS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

**AS188
NNW
1/2-1
3632 ft.
Lower**

**SERVICE SPECIALTIES INC 8TH AVE S
7400 8TH AVE S
SEATTLE, WA 98108**

**RCRIS-SQG 1000432888
FINDS WAD981768377**

Site 2 of 6 in cluster AS

RCRIS:

Owner: SERVICE SPECIALTIES INC
(360) 555-1212
EPA ID: WAD981768377
Contact: GREGG BISHOP
(206) 632-1441

Classification: Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported
Violation Status: No violations found

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

SERVICE SPECIALTIES INC 8TH AVE S (Continued)

EDR ID Number
EPA ID Number

Database(s)

1000432888

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Biennial Reporting System (BRS)
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

AS189
NNW
1/2-1
3632 ft.
Lower

**CROWLEY MARINE SERVICES INC 8TH AVE
7400 8TH AVE S
SEATTLE, WA 98108**

RCRIS-SQG

1001233933
WAD988470647

Site 3 of 6 in cluster AS

RCRIS:

Owner: 8TH AVE TERMINAL CO
(206) 443-8100

EPA ID: WAD988470647

Contact: GREG FERRIS
(206) 443-8100

Classification: N, Small Quantity Generator

Used Oil Recyc: No

TSDF Activities: Not reported

Violation Status: No violations found

AS190
NNW
1/2-1
3640 ft.
Lower

**7400 8TH AVE SOUTH
7400 8TH AVE SOUTH
SEATTLE, WA 98108**

ERNS

2000540655
N/A

Site 4 of 6 in cluster AS

AS191
NNW
1/2-1
3640 ft.
Lower

**NORTHLAND SERVICES INC TRANSFER FACILITY
7400 8TH AVE S TRANSFER FACILI
SEATTLE, WA 98108**

FINDS

1005238088
000010744758

Site 5 of 6 in cluster AS

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)

AS192
NNW
1/2-1
3640 ft.
Lower

**7400 8TH AVE S
SEATTLE, WA**

SPILLS

S105394145
N/A

Site 6 of 6 in cluster AS

WA SPILL:

Facility ID: 513189
Date Received: 08/31/2000
Business Name: BARGE LINES
Material Desc : OTHER HAZARDOUS
Medium: ROADWAY-PAVED
Material Qty: 1800
Material Units: GALLON

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

AT193
South
1/2-1
3649 ft.
Higher

DEVELOPMENTAL CENTER
9725 E MARGINAL WAY S
SEATTLE, WA 98108

Site 1 of 2 in cluster AT

UST **U000594520**
LUST **N/A**

LUST:

Facility ID: 10408 Ecology Region: North Western
Release ID: 1476 Release Date: 7/20/1989 00:00:00
Release Status: Cleanup Started Status Date: 6/1/1995 00:00:00
Alternate Name: BOEING DEVELOP CENTER BLDG 9-52
Affected Media: Soil

Facility ID: 10408 Ecology Region: North Western
Release ID: 1476 Release Date: 7/20/1989 00:00:00
Release Status: Cleanup Started Status Date: 6/1/1995 00:00:00
Alternate Name: BOEING DEVELOP CENTER BLDG 9-52
Affected Media: Ground Water

UST:

Facility ID: 10408
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: Not reported
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 10408
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: Not reported
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 10408
Install Date: 12/31/1964 0:00
Capacity: 111 to 1,100 Gallons
Status: Not reported
Tank Name: DIESEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 10408
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: USED OIL/WASTE OIL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

DEVELOPMENTAL CENTER (Continued)

U000594520

Facility ID: 10408
Install Date: 6/1/1984 0:00
Capacity: 111 to 1,100 Gallons
Status: Not reported
Tank Name: DIESEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 10408
Install Date: 12/1/1990 0:00
Capacity: 111 to 1,100 Gallons
Status: Not reported
Tank Name: DIESEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 10408
Install Date: 6/1/1985 0:00
Capacity: Not reported
Status: Not reported
Tank Name: Not reported
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 10408
Install Date: 12/1/1990 0:00
Capacity: 111 to 1,100 Gallons
Status: Not reported
Tank Name: UNLEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 10408
Install Date: 12/31/1964 0:00
Capacity: 111 to 1,100 Gallons
Status: Not reported
Tank Name: UNLEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 10408
Install Date: 12/31/1964 0:00
Capacity: 111 to 1,100 Gallons
Status: Not reported
Tank Name: USED OIL/WASTE OIL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

DEVELOPMENTAL CENTER (Continued)

EDR ID Number
EPA ID Number

Database(s)

U000594520

Facility ID: 10408
Install Date: 12/31/1964 0:00
Capacity: 111 to 1,100 Gallons
Status: Not reported
Tank Name: Not reported
Substance: NW
Compartment #: Not reported
Ecology Region: 1

AU194
NNW
1/2-1
3657 ft.
Lower

7200 EAST MARGINAL WAY SOUTH
SEATTLE, WA

SPILLS S105398795
N/A

Site 1 of 4 in cluster AU

WA SPILL:
Facility ID: 521009
Date Received: 09/13/2001
Business Name: GAS STATION
Material Desc : PETROLEUM - GASOLINE
Medium: OTHER
Material Qty: 5
Material Units: GALLON

AU195
NNW
1/2-1
3657 ft.
Lower

7201 EAST MARGINAL WAY SOUTH, SEATTLE
SEATTLE, WA

SPILLS S105388533
N/A

Site 2 of 4 in cluster AU

WA SPILL:
Facility ID: 505361
Date Received: 03/09/1999
Business Name: CURRENT OWNER
Material Desc : PETROLEUM - OIL OTHER
Medium: SOIL
Material Qty: Not reported
Material Units: Not reported

AU196
NNW
1/2-1
3657 ft.
Lower

ARCO 5218
7200 E. MARGINAL WAY S.
SEATTLE, WA 98108

WA ICR 1000838681
N/A

Site 3 of 4 in cluster AU

WA ICR:
Date Ecology Received Report: / /
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 95-13
County Code: 17
Contact: Not reported
Report Title: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

ARCO 5218 (Continued)

1000838681

Date Ecology Received Report: 01/08/1998
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 95-17
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 01/22/1996
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 94-27
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 02/28/1996
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 94-35
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 10/26/1998
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 98-13
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 04/30/1999
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 98-15
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 09/23/1999

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

ARCO 5218 (Continued)

EDR ID Number
EPA ID Number

Database(s)

1000838681

Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Cause of Contamination:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	98-19
County Code:	17
Contact:	Not reported
Report Title:	Not reported
Date Ecology Received Report:	08/19/1996
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Cause of Contamination:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	94-41
County Code:	17
Contact:	Not reported
Report Title:	Not reported
Date Ecology Received Report:	02/25/1997
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Cause of Contamination:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	94-53
County Code:	17
Contact:	Not reported
Report Title:	Not reported
Date Ecology Received Report:	06/09/2000
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Cause of Contamination:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	98-28
County Code:	17
Contact:	Not reported
Report Title:	First & Second Quarters Ground Water Monitoring
Date Ecology Received Report:	03/03/2000
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Cause of Contamination:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	98-28
County Code:	17
Contact:	Not reported
Report Title:	Third & Fourth Quarters Ground Water Monitoring 1999
Date Ecology Received Report:	10/26/1993
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Soil

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

ARCO 5218 (Continued)

1000838681

Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 93-20
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 02/18/1994
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 93-21
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 06/15/1994
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 94-03
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 06/08/1995
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 94-03
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 11/06/2000
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 98-32
County Code: 17
Contact: Not reported
Report Title: Third & Fourth Quarters Ground Water Monitoring

Date Ecology Received Report: 05/24/2001
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Cause of Contamination: Tank
Region: North Western

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

ARCO 5218 (Continued)

EDR ID Number
EPA ID Number

Database(s)

1000838681

Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 98-37
County Code: 17
Contact: Not reported
Report Title: First & Second Quarters 2001 Ground Water Monitoring

AU197
NNW
1/2-1
3657 ft.
Lower

ARCO FACILITY #05218
7200 E MARGINAL WAY S
SEATTLE, WA 98108

UST U001125619
LUST N/A

Site 4 of 4 in cluster AU

LUST:

Facility ID:	8788	Ecology Region:	North Western
Release ID:	4609	Release Date:	8/30/1993 00:00:00
Release Status:	Awaiting Cleanup	Status Date:	6/1/1995 00:00:00
Alternate Name:	ARCO STATION # 5218		
Affected Media:	Soil		

Facility ID:	8788	Ecology Region:	North Western
Release ID:	4609	Release Date:	8/30/1993 00:00:00
Release Status:	Awaiting Cleanup	Status Date:	6/1/1995 00:00:00
Alternate Name:	ARCO STATION # 5218		
Affected Media:	Ground Water		

Facility ID:	8788	Ecology Region:	North Western
Release ID:	4609	Release Date:	8/30/1993 00:00:00
Release Status:	Cleanup Started	Status Date:	2/8/1994 00:00:00
Alternate Name:	ARCO STATION # 5218		
Affected Media:	Soil		

Facility ID:	8788	Ecology Region:	North Western
Release ID:	4609	Release Date:	8/30/1993 00:00:00
Release Status:	Cleanup Started	Status Date:	2/8/1994 00:00:00
Alternate Name:	ARCO STATION # 5218		
Affected Media:	Ground Water		

Facility ID:	8788	Ecology Region:	North Western
Release ID:	4609	Release Date:	8/30/1993 00:00:00
Release Status:	Monitoring	Status Date:	9/6/1996 00:00:00
Alternate Name:	ARCO STATION # 5218		
Affected Media:	Soil		

Facility ID:	8788	Ecology Region:	North Western
Release ID:	4609	Release Date:	8/30/1993 00:00:00
Release Status:	Monitoring	Status Date:	9/6/1996 00:00:00
Alternate Name:	ARCO STATION # 5218		
Affected Media:	Ground Water		

UST:

Facility ID: 8788
Install Date: 3/1/1985 0:00
Capacity: 10,000 TO 19,999 GALLONS
Status: Not reported
Tank Name: LEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

ARCO FACILITY #05218 (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001125619

Facility ID: 8788
Install Date: 3/1/1985 0:00
Capacity: 10,000 TO 19,999 GALLONS
Status: Not reported
Tank Name: UNLEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 8788
Install Date: 3/1/1985 0:00
Capacity: 10,000 TO 19,999 GALLONS
Status: Not reported
Tank Name: UNLEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

AR198
WNW
1/2-1
3664 ft.
Lower

MARINE LUMBER SERVICE INC.
525 S CHICAGO ST /PO BOX 80964
SEATTLE, WA 98108

UST U000802483
WA ICR N/A

Site 2 of 3 in cluster AR

WA ICR:

Date Ecology Received Report: 06/28/1994
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 93-36
County Code: 17
Contact: Not reported
Report Title: Not reported

UST:

Facility ID: 11327
Install Date: 7/15/1973 0:00
Capacity: 111 to 1,100 Gallons
Status: Not reported
Tank Name: LEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 11327
Install Date: 7/15/1982 0:00
Capacity: Not reported
Status: Not reported
Tank Name: UNLEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

Distance Distance (ft.) Elevation	Site	Database(s)	EDR ID Number EPA ID Number
AV201 WNW 1/2-1 3680 ft. Lower	ELLIOTT BAY INDUSTRIES INC. 470 SO KENYON ST. SEATTLE, WA 98108 Site 2 of 2 in cluster AV UST: Facility ID: 1883 Install Date: 12/31/1964 0:00 Capacity: Not reported Status: Not reported Tank Name: Not reported Substance: NW Compartment #: Not reported Ecology Region: 1	UST	U003026147 N/A
AR202 WNW 1/2-1 3688 ft. Lower	MILL ENGINEERING & SUPPLY CO 516 S CHICAGO SEATTLE, WA 98108 Site 3 of 3 in cluster AR RCRIS: Owner: MILL ENGINEERING & SUPPLY CO EPA ID: WAD009241142 Contact: Haz-Waste Mgr (206) 575-0450 Classification: N, Small Quantity Generator Used Oil Recyc: No TSDF Activities: Not reported Violation Status: No violations found FINDS: Other Pertinent Environmental Activity Identified at Site: Facility Registry System (FRS) Resource Conservation and Recovery Act Information system (RCRAINFO)	RCRIS-SQG FINDS	1000274152 WAD009241142
AW203 WNW 1/2-1 3734 ft. Lower	ROGERS MACHINERY CO INC 7800 5TH AVE S SEATTLE, WA 98108 Site 1 of 3 in cluster AW FINDS: Other Pertinent Environmental Activity Identified at Site: Facility Registry System (FRS)	FINDS	1005102149 000009061266
AW204 WNW 1/2-1 3734 ft. Lower	ROCKWELL AUTOMATION 500 S. CHICAGO ST SEATTLE, WA 98108 Site 2 of 3 in cluster AW	FINDS	1005186361 000010195934

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

ROCKWELL AUTOMATION (Continued)

Database(s) EDR ID Number
EPA ID Number

1005186361

FINDS:

Other Pertinent Environmental Activity Identified at Site:
AIRS Facility System (AIRS/AFS)
Facility Registry System (FRS)

AW205
WNW
1/2-1
3734 ft.
Lower

ROGERS MACHINERY CO INC
7800 5TH AVE S
SEATTLE, WA 98108

RCRIS-SQG 1001820008
WAD988509386

Site 3 of 3 in cluster AW

RCRIS:

Owner: ROGERS MACHINERY CO INC
EPA ID: WAD988509386

Contact: MICHAEL PROULX
(206) 763-2530

Classification: Small Quantity Generator

Used Oil Recyc: No

TSD Activities: Not reported

Violation Status: No violations found

AT206
South
1/2-1
3745 ft.
Higher

WHITEHEAD COMPANY CORP.
600 SO MYRTLE ST PO BOX 323
SEATTLE, WA 98111

UST U003028946
N/A

Site 2 of 2 in cluster AT

UST:

Facility ID: 9634
Install Date: 12/31/1964 0:00
Capacity: 111 to 1,100 Gallons
Status: Not reported
Tank Name: LEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 9634
Install Date: 12/31/1964 0:00
Capacity: 111 to 1,100 Gallons
Status: Not reported
Tank Name: LEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

AX207
WNW
1/2-1
3763 ft.
Lower

PIPE SPECIALITIES INC
531 S PORTLAND
SEATTLE, WA 98108

RCRIS-SQG 1000198656
FINDS WAD081489551

Site 1 of 2 in cluster AX

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

PIPE SPECIALITIES INC (Continued)

EDR ID Number
EPA ID Number

Database(s)

1000198656

RCRIS:

Owner: PIPE SPECIALITIES INC
(360) 555-1212
EPA ID: WAD081489551
Contact: THOMAS STUDER
(206) 762-5011

Classification: Small Quantity Generator
Used Oil Recyc: No
TSD Activities: Not reported
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

AY208
West
1/2-1
3802 ft.
Lower

EMERSON POWER PRODUCTS INC
426 S CLOVERDALE ST
SEATTLE, WA 98108

RCRIS-SQG 1000658782
FINDS WAD988484382

Site 1 of 2 in cluster AY

RCRIS:

Owner: CASCADE DIESEL ENGINE CO
(206) 764-3850
EPA ID: WAD988484382
Contact: PHYLLIS GANNON
(206) 764-3850

Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSD Activities: Not reported
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

209
ESE
1/2-1
3807 ft.
Higher

BOEING AIR TRAFFIC CONTROL TOW
8200 E MARGINAL WAY S
SEATTLE, WA 98108

RCRIS-SQG 1001081954
FINDS WAR000005181

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

BOEING AIR TRAFFIC CONTROL TOW (Continued)

1001081954

RCRIS:

Owner: BOEING CO
(360) 555-1212
EPA ID: WAR000005181
Contact: WADE WHITTON
(206) 248-5181
Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

210
South
1/2-1
3828 ft.
Higher

ATLANTIC RICHFIELD COMPANY
9525 S 14TH AVE S
SEATTLE, WA 98108

UST U003800990
N/A

UST:

Facility ID: 587780
Install Date: 7/10/1999 0:00
Capacity: 10,000 TO 19,999 GALLONS
Status: Not reported
Tank Name: UNLEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 587780
Install Date: 7/10/1999 0:00
Capacity: 10,000 TO 19,999 GALLONS
Status: Not reported
Tank Name: UNLEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 587780
Install Date: 7/10/1999 0:00
Capacity: 10,000 TO 19,999 GALLONS
Status: Not reported
Tank Name: UNLEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 2

211
WNW
1/2-1
3831 ft.
Lower

SIGNAL MOTOR EQUIPMENT
555 S HOLDEN
SEATTLE, WA 98108

FINDS 1004613480
D10#1086-12-

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

SIGNAL MOTOR EQUIPMENT (Continued)

EDR ID Number
EPA ID Number

Database(s)

1004613480

FINDS:

Other Pertinent Environmental Activity Identified at Site:
National Compliance Database (NCDB)

212
South
1/2-1
3845 ft.
Higher

**BOEING MILITARY AIRCRAFT DC)
9725 E MARGINAL WAY S
SEATTLE, WA 98108**

EMI S101150995
SPILLS N/A

WA SPILL:

Facility ID: 511091
Date Received: 05/17/2000
Business Name: BOEING
Material Desc : OTHER HAZARDOUS
Medium: OTHER
Material Qty: 5
Material Units: GALLON

Facility ID: 523840
Date Received: 01/23/2002
Business Name: BOEING
Material Desc : PETROLEUM - OIL OTHER
Medium: STORM DRAIN PIPE
Material Qty: 1
Material Units: GALLON

WA AIR EMISSIONS:

Facility ID: 0053
SO2 Chemical: 0.1230
VOC Chemical: 6.7495
PM10 Chemical: 0.4920
Local ID: C
NO2 Chemical: 18.8210
CO Chemical: 4.7615

Mailing Name: BOEING MILITARY AIRPLANES (DC)
PO BOX 3707 MS 4H-26
SEATTLE, 53 98124

Year Of Info: Not reported
Mail Add Zip 2: Not reported
Point Num: Not reported
Point Desc: Not reported
Tot Suspended Particulate Tons/Yr: Not reported

AZ213
NNW
1/2-1
3847 ft.
Lower

**PUGET SOUND TRUCK LINES INC
7303 8TH AVENUE SOUTH
SEATTLE, WA 98108**

UST U003028285
LUST N/A

Site 1 of 3 in cluster AZ

LUST:

Facility ID: 7820
Release ID: 2352
Release Status: Cleanup Started
Alternate Name: PUGET SOUND TRUCK SEATTLE
Affected Media: Soil
Ecology Region: North Western
Release Date: 6/12/1991 00:00:00
Status Date: 6/12/1991 00:00:00

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

PUGET SOUND TRUCK LINES INC (Continued)

U003028285

Facility ID: 7820 Ecology Region: North Western
Release ID: 2352 Release Date: 6/12/1991 00:00:00
Release Status: Reported Cleaned Up Status Date: 9/27/1995 00:00:00
Alternate Name: PUGET SOUND TRUCK SEATTLE
Affected Media: Soil

UST:

Facility ID: 7820
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: Not reported
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 7820
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: USED OIL/WASTE OIL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 7820
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: LEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 7820
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: Not reported
Substance: NW
Compartment #: Not reported
Ecology Region: 1

AZ214 PUGET SOUND TRK LINES SEA
NNW 7303 8TH AVE S
1/2-1 SEATTLE, WA 98108
3847 ft.
Lower Site 2 of 3 in cluster AZ

RCRIS-SQG 1001806334
FINDS WAD173274499

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

PUGET SOUND TRK LINES SEA (Continued)

EDR ID Number
EPA ID Number

Database(s)

1001806334

RCRIS:

Owner: PUGET SOUND TRK LINES SEA
EPA ID: WAD173274499
Contact: DAVID EADEN
(206) 654-7304

Classification: N, Conditionally Exempt Small Quantity Generator

Used Oil Recyc: No

TSDF Activities: Not reported

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:

Facility Registry System (FRS)

Resource Conservation and Recovery Act Information system (RCRAINFO)

AZ215
NNW
1/2-1
3847 ft.
Lower

PUGET SOUND TRUCK SEATTLE
7303 8TH AVE. S.
SEATTLE, WA 98108

WA ICR S104487279
N/A

Site 3 of 3 in cluster AZ

WA ICR:

Date Ecology Received Report: 06/12/1991
Contaminants Found at Site: Petroleum products
Media Contaminated: Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Final cleanup report
Site Register Issue: 92-01
County Code: 17
Contact: Not reported
Report Title: Not reported

AX216
WNW
1/2-1
3852 ft.
Lower

GEAR WORKS SEATTLE INC
500 S PORTLAND ST
SEATTLE, WA 98108

RCRIS-SQG 1000115936
FINDS WAD009247305

Site 2 of 2 in cluster AX

RCRIS:

Owner: GEAR WORKS SEATTLE INC
EPA ID: WAD009247305
Contact: BERNIE CONRAD
(206) 762-3333

Classification: Small Quantity Generator

Used Oil Recyc: No

TSDF Activities: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

GEAR WORKS SEATTLE INC (Continued)

1000115936

Violation Status: Violations exist

Regulation Violated:	200(1)(c)(d)
Area of Violation:	GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined:	04/09/1997
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	04/09/1997
Penalty Type:	Not reported
Regulation Violated:	145
Area of Violation:	GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined:	04/09/1997
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	04/09/1997
Penalty Type:	Not reported
Regulation Violated:	180
Area of Violation:	GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined:	04/09/1997
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	04/09/1997
Penalty Type:	Not reported
Regulation Violated:	220
Area of Violation:	GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined:	04/09/1997
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	04/09/1997
Penalty Type:	Not reported

There are 4 violation record(s) reported at this site:

<u>Evaluation</u>	<u>Area of Violation</u>	<u>Date of Compliance</u>
Compliance Evaluation Inspection	GENERATOR-GENERAL REQUIREMENTS	07/18/199
	GENERATOR-GENERAL REQUIREMENTS	06/27/199
	GENERATOR-GENERAL REQUIREMENTS	07/31/199
	GENERATOR-GENERAL REQUIREMENTS	07/31/199

FINDS:

Other Pertinent Environmental Activity Identified at Site:

Biennial Reporting System (BRS)
Facility Registry System (FRS)
National Compliance Database (NCDB)
Resource Conservation and Recovery Act Information system (RCRAINFO)

AY217
West
1/2-1
3859 ft.
Lower

RASMUSSEN EQUIPMENT CO INC
415 SOUTH CLOVERDALE STREET
SEATTLE, WA 98108

UST U003028063
LUST N/A

Site 2 of 2 in cluster AY

LUST:

Facility ID:	721	Ecology Region:	North Western
Release ID:	5528	Release Date:	8/29/1994 00:00:00
Release Status:	Cleanup Started	Status Date:	8/29/1994 00:00:00
Alternate Name:	RASMUSSEN EQUIPMENT		
Affected Media:	Soil		

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

RASMUSSEN EQUIPMENT CO INC (Continued)

EDR ID Number
EPA ID Number

Database(s)

U003028063

Facility ID: 721 Ecology Region: North Western
Release ID: 5528 Release Date: 8/29/1994 00:00:00
Release Status: Reported Cleaned Up Status Date: 6/1/1995 00:00:00
Alternate Name: RASMUSSEN EQUIPMENT
Affected Media: Soil

UST:

Facility ID: 721
Install Date: 6/6/1979 0:00
Capacity: Not reported
Status: Not reported
Tank Name: UNLEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 721
Install Date: 6/6/1979 0:00
Capacity: Not reported
Status: Not reported
Tank Name: Not reported
Substance: NW
Compartment #: Not reported
Ecology Region: 1

BA218
WNW
1/2-1
3919 ft.
Lower

S CHICAGO ST DUMP
251 S CHICAGO ST
SEATTLE, WA 98108

RCRIS-SQG 1001121516
FINDS WAR000009381

Site 1 of 3 in cluster BA

RCRIS:

Owner: WA STATE
(360) 555-1212
EPA ID: WAR000009381
Contact: HATHOR WOODS
(425) 649-7141

Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

BB219
SSE
1/2-1
3922 ft.
Higher

DELTA MARINE INDUSTRIES INC
1608 S 96TH ST
SEATTLE, WA 98108

RCRIS-SQG 1000395279
FINDS WAD052593480

Site 1 of 2 in cluster BB

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

DELTA MARINE INDUSTRIES INC (Continued)

1000395279

RCRIS:

Owner: DELTA MARINE INDUSTRIES INC
EPA ID: WAD052593480
Contact: EVED OWEN
(206) 763-2383

Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported

Violation Status: Violations exist

Regulation Violated: -170 / -070(3)
Area of Violation: GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined: 11/08/2000

Enforcement Action: WRITTEN INFORMAL
Enforcement Action Date: 12/11/2000
Penalty Type: Not reported

Regulation Violated: -070(7)(c)(ii)
Area of Violation: GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined: 11/08/2000

Enforcement Action: WRITTEN INFORMAL
Enforcement Action Date: 12/11/2000
Penalty Type: Not reported

Regulation Violated: -630(7) / -283(3)
Area of Violation: GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined: 11/08/2000

Enforcement Action: WRITTEN INFORMAL
Enforcement Action Date: 12/11/2000
Penalty Type: Not reported

Regulation Violated: -200(2)(c)
Area of Violation: GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined: 11/08/2000

Enforcement Action: WRITTEN INFORMAL
Enforcement Action Date: 12/11/2000
Penalty Type: Not reported

Regulation Violated: -170(3)(b) / 200,201,202,283(3)
Area of Violation: GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined: 11/08/2000

Enforcement Action: WRITTEN INFORMAL
Enforcement Action Date: 12/11/2000
Penalty Type: Not reported

Regulation Violated: 070(3)
Area of Violation: GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined: 06/06/1995

Regulation Violated: 0-70(7)(ii)
Area of Violation: GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined: 06/06/1995

Regulation Violated: 141(1)
Area of Violation: GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined: 06/06/1995

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

DELTA MARINE INDUSTRIES INC (Continued)

EDR ID Number
EPA ID Number

Database(s)

1000395279

Regulation Violated:	200(1)(c)
Area of Violation:	GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined:	06/06/1995
Regulation Violated:	200(1)(d)
Area of Violation:	GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined:	06/06/1995
Regulation Violated:	200(1)(b)&ref 630(3)
Area of Violation:	GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined:	06/06/1995
Regulation Violated:	200(1)(b)&ref 630(5)(a)
Area of Violation:	GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined:	06/06/1995
Regulation Violated:	060(2)
Area of Violation:	GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined:	06/06/1995
Regulation Violated:	200(1)(b)&ref 630(5)(c)
Area of Violation:	GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined:	06/06/1995
Regulation Violated:	200(1)(b)&ref 630(6)
Area of Violation:	GENERATOR-GENERAL REQUIREMENTS
Date Violation Determined:	06/06/1995

There are 15 violation record(s) reported at this site:

<u>Evaluation</u>	<u>Area of Violation</u>	<u>Date of Compliance</u>
Compliance Evaluation Inspection	GENERATOR-GENERAL REQUIREMENTS	01/19/200
	GENERATOR-GENERAL REQUIREMENTS	01/19/200
	GENERATOR-GENERAL REQUIREMENTS	01/19/200
	GENERATOR-GENERAL REQUIREMENTS	01/19/200
	GENERATOR-GENERAL REQUIREMENTS	01/19/200
Compliance Evaluation Inspection	GENERATOR-GENERAL REQUIREMENTS	07/11/199
	GENERATOR-GENERAL REQUIREMENTS	07/11/199
	GENERATOR-GENERAL REQUIREMENTS	07/11/199
	GENERATOR-GENERAL REQUIREMENTS	07/31/199
	GENERATOR-GENERAL REQUIREMENTS	07/31/199
	GENERATOR-GENERAL REQUIREMENTS	07/31/199
	GENERATOR-GENERAL REQUIREMENTS	07/31/199
	GENERATOR-GENERAL REQUIREMENTS	07/31/199
	GENERATOR-GENERAL REQUIREMENTS	07/11/199
	GENERATOR-GENERAL REQUIREMENTS	07/31/199
	GENERATOR-GENERAL REQUIREMENTS	07/31/199

FINDS:

Other Pertinent Environmental Activity Identified at Site:

AIRS Facility System (AIRS/AFS)
Biennial Reporting System (BRS)
Facility Registry System (FRS)
National Compliance Database (NCDB)
National Emissions Trends (NET)
Resource Conservation and Recovery Act Information system (RCRAINFO)
Toxic Chemical Release Inventory System (TRIS)

BB220 DELTA MARINE INDUSTRIES
SSE 1608 S 96TH ST
1/2-1 SEATTLE, WA 98108
3922 ft.
Higher Site 2 of 2 in cluster BB

FTTS 1004628932
N/A

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

DELTA MARINE INDUSTRIES (Continued)

1004628932

FTTS Insp:
Region: 10
Inspected Date: 04/07/98
Insp Number: 04/07/98
Violation occurred: Not reported
Inspector: SOMERS
Investigation Type: EPCRA, Data Quality, SEE Conducted
Facility Function: Manufacturer
Investig Reason: Neutral Scheme, Region
Legislation Code: EPCRA

BA221 NON-FERROUS METALS INC.
WNW 230 S. CHICAGO ST.
1/2-1 SEATTLE, WA 98108
3935 ft.
Lower Site 2 of 3 in cluster BA

TRIS 1003888676
98134NNFRR29

BA222 NON FERROUS METALS INCORPORATED
WNW 230 S. CHICAGO ST.
1/2-1 SEATTLE, WA 98108
3935 ft.
Lower Site 3 of 3 in cluster BA

FINDS 1004612691
110000489695

FINDS: :
Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Toxic Chemical Release Inventory System (TRIS)

223 9326 7TH AVE S BETWEEN 509 99, OFF OF
SW SEATTLE, WA
1/2-1
3954 ft.
Higher

SPILLS S105397605
N/A

WA SPILL:
Facility ID: 518854
Date Received: 06/18/2001
Business Name: UNKNOWN
Material Desc : CHEMICAL
Medium: BUILDING/STRUCTURE
Material Qty: Not reported
Material Units: Not reported

224 KING COUNTY AIRPORT
NE P O BOX 80245
1/2-1 SEATTLE, WA 98108
3993 ft.
Higher

UST U001778182
N/A

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

KING COUNTY AIRPORT (Continued)

Database(s)
EDR ID Number
EPA ID Number

U001778182

UST:

Facility ID: 102223
Install Date: 1/1/1960 0:00
Capacity: Not reported
Status: Not reported
Tank Name: LEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

BC225
NNW
1/2-1
4016 ft.
Lower
CUSTOM ELECTRIC
7136 8TH AVE S
SEATTLE, WA 98101
Site 1 of 3 in cluster BC

FTTS 1004628472
N/A

FTTS Insp:
Region: 10
Inspected Date: 09/16/96
Insp Number: 09/16/96
Violation occurred: Yes
Inspector: MCDERMOTT
Investigation Type: Section 6 PCB Federal Conducted
Facility Function: User
Investig Reason: Neutral Scheme, Region
Legislation Code: TSCA

BC226
NNW
1/2-1
4022 ft.
Lower
8TH S
7130 8TH S
SEATTLE, WA 98108
Site 2 of 3 in cluster BC

RCRIS-SQG 1000199625
WAD981765779

RCRIS:
Owner: MANCHESTER LABORATORY
(360) 555-1212
EPA ID: WAD981765779
Contact: LAURENCE ASHLEY
(425) 885-1900
Classification: Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported
Violation Status: No violations found

BC227
NNW
1/2-1
4022 ft.
Lower
NELSON TRUCKING CO INC
7130 8TH AVE S
SEATTLE, WA 98108
Site 3 of 3 in cluster BC

RCRIS-SQG 1001969492
FINDS WAD150089787

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

NELSON TRUCKING CO INC (Continued)

1001969492

RCRIS:

Owner: NELSON TRUCKING CO INC
(206) 763-4294
EPA ID: WAD150089787
Contact: BILL HARTSTROM
(206) 763-4294

Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

**BD228
SW
1/2-1
4046 ft.
Higher**

**DESIMONE TRUST / HOMEPLACE
9365 7TH AVE S
SEATTLE, WA 98168**

**UST U003750442
CSCSL NFA N/A**

Site 1 of 3 in cluster BD

WA NFA:

Facility/Site Id : 91322212
Ecology Status : Independent Remedial Action
Independent Status Code : Final Independent RA Report received
WARM Bin Number : Not reported
NFA Code : NFA after Assesment IRAP or VCP
NFA Date : 1/12/2000 00:00:00

UST:

Facility ID: 539649
Install Date: Not reported
Capacity: 111 TO 1,000 GALLONS
Status: Not reported
Tank Name: DIESEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 539649
Install Date: Not reported
Capacity: 1,101 TO 2,000 GALLONS
Status: Not reported
Tank Name: BUNKER C
Substance: NW
Compartment #: Not reported
Ecology Region: 1

**BD229
SW
1/2-1
4046 ft.
Higher**

**DESIMONE TRUST PROPERTY
9365 7TH AVE. S.
SEATTLE, WA 98168**

**WA ICR S104586242
N/A**

Site 2 of 3 in cluster BD

WA ICR:

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

DESIMONE TRUST PROPERTY (Continued)

EDR ID Number
EPA ID Number

Database(s)

S104586242

Date Ecology Received Report: 12/07/1999
Contaminants Found at Site: Petroleum products
Media Contaminated: Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Final cleanup report
Site Register Issue: 98-27
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 11/15/1999
Contaminants Found at Site: Petroleum products
Media Contaminated: Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 98-27
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 06/18/1996
Contaminants Found at Site: Petroleum products
Media Contaminated: Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 98-27
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 04/01/1992
Contaminants Found at Site: Petroleum products
Media Contaminated: Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 98-27
County Code: 17
Contact: Not reported
Report Title: Not reported

BD230
SW
1/2-1
4046 ft.
Higher

DESIMONE TRUST PROPERTY TWO REPORTS)
9365 7TH AVE. S.
SEATTLE, WA 98168
Site 3 of 3 in cluster BD

WA ICR S104586216
N/A

WA ICR:
Date Ecology Received Report: 12/08/1999
Contaminants Found at Site: Petroleum products
Media Contaminated: Soil
Cause of Contamination: Not reported
Region: North Western
Type of Report Ecology Received: Final cleanup report
Site Register Issue: 98-20
County Code: 17

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

DESIMONE TRUST PROPERTY TWO REPORTS) (Continued)

EDR ID Number
EPA ID Number

Database(s)

Contact: Not reported
Report Title: Not reported

S104586216

BE231
NW
1/2-1
4072 ft.
Lower

PACIFIC TERMINALS LIMITED
660 S OTHELLO
SEATTLE, WA 98108

RCRIS-SQG 1000252120
FINDS WAD988467700

Site 1 of 2 in cluster BE

RCRIS:

Owner: PACIFIC TERMINALS LIMITED
(206) 763-2110
EPA ID: WAD988467700
Contact: WILLIAM HITE
(206) 763-2110

Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

BE232
NW
1/2-1
4089 ft.
Lower

DINOL US INC SEATTLE
650 S OTHELLO ST
SEATTLE, WA 98108

FINDS 1004990972
000007560594

Site 2 of 2 in cluster BE

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)

BF233
NW
1/2-1
4099 ft.
Lower

MODERN IRON & STEEL INC
7619 5TH AVE SO.
SEATTLE, WA 98108

UST U000586792
N/A

Site 1 of 4 in cluster BF

UST:

Facility ID: 1496
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: Not reported
Substance: NW
Compartment #: Not reported
Ecology Region: 1

BF234
NW
1/2-1
4099 ft.
Lower

GLOBAL, INC
7619 - 5TH AVE S
SEATTLE, WA 98108

FINDS 1005186357
000010195896

Site 2 of 4 in cluster BF

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

GLOBAL, INC (Continued)

EDR ID Number
EPA ID Number

Database(s)

1005186357

FINDS:

Other Pertinent Environmental Activity Identified at Site:

AIRS Facility System (AIRS/AFS)

Facility Registry System (FRS)

**BG235
NNW
1/2-1
4101 ft.
Lower**

**BOEING - NORTH FIELD
ELLIS AVE. S. E. MARGINAL WAY
SEATTLE, WA 98108**

**WA ICR S103505628
N/A**

Site 1 of 12 in cluster BG

WA ICR:

Date Ecology Received Report: / /
Contaminants Found at Site: Petroleum products
Media Contaminated: Soil
Cause of Contamination: Not reported
Region: North Western
Type of Report Ecology Received: Not reported
Site Register Issue: 91-27
County Code: 17
Contact: Not reported
Report Title: Not reported

**BG236
NNW
1/2-1
4101 ft.
Lower**

**NORTH BOEING FIELD, BLAST FENCE, APRON A
ELLIS AVE. S. E. MARGINAL WAY
SEATTLE, WA 98108**

**WA ICR S103508404
N/A**

Site 2 of 12 in cluster BG

WA ICR:

Date Ecology Received Report: 08/30/1990
Contaminants Found at Site: Petroleum products
Media Contaminated: Soil
Cause of Contamination: Not reported
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 91-20
County Code: 17
Contact: Not reported
Report Title: Not reported

**BG237
NNW
1/2-1
4101 ft.
Lower**

**BOEING - NORTH BOEING FIELD, PROPOSED BLDG. 3-801
ELLIS AVE. S. E. MARGINAL WAY
SEATTLE, WA 98108**

**WA ICR S103505626
N/A**

Site 3 of 12 in cluster BG

WA ICR:

Date Ecology Received Report: / /
Contaminants Found at Site: Metals
Media Contaminated: Groundwater, Soil
Cause of Contamination: Tank, Spill
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 92-16
County Code: 17
Contact: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

BOEING - NORTH BOEING FIELD, PROPOSED BLDG. 3-801 (Continued)

EDR ID Number
EPA ID Number

Report Title: Not reported

S103505626

BG238
NNW
1/2-1
4101 ft.
Lower

**BOEING - NORTH FIELD BUILDING 3-840
ELLIS AVE. S. E. MARGINAL WAY
SEATTLE, WA 98108**

WA ICR S103505632
N/A

Site 4 of 12 in cluster BG

WA ICR:

Date Ecology Received Report: 03/30/1992
Contaminants Found at Site: Halogenated organic compounds
Media Contaminated: Groundwater
Cause of Contamination: Not reported
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 92-21
County Code: 17
Contact: Not reported
Report Title: Not reported

BG239
NNW
1/2-1
4101 ft.
Lower

**BOEING NORTH FIELD-BLDGS 3-800 3-801 TWO REPORTS)
ELLIS AVE. S. E. MARGINAL WAY
SEATTLE, WA 98108**

WA ICR S103505657
N/A

Site 5 of 12 in cluster BG

WA ICR:

Date Ecology Received Report: 05/10/1993
Contaminants Found at Site: Halogenated Solvents
Total petroleum hydrocarbons
Media Contaminated: Groundwater, Soil
Cause of Contamination: Not reported
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 93-01
County Code: 17
Contact: Not reported
Report Title: Not reported

BG240
NNW
1/2-1
4101 ft.
Lower

**BOEING - NORTH BOEING FIELD BLDG. 3-354
ELLIS AVE. S. E. MARGINAL WAY
SEATTLE, WA 98108**

WA ICR S103505623
N/A

Site 6 of 12 in cluster BG

WA ICR:

Date Ecology Received Report: 11/20/1991
Contaminants Found at Site: Petroleum products
Media Contaminated: Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 92-12
County Code: 17
Contact: Not reported
Report Title: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

Site
Database(s)
EDR ID Number
EPA ID Number

BG241
NNW
1/2-1
4101 ft.
Lower
BOEING NORTH FIELD
ELLIS AVE. S. E. MARGINAL WAY
SEATTLE, WA 98108
Site 7 of 12 in cluster BG

WA ICR **S103512410**
N/A

WA ICR:
Date Ecology Received Report: 01/18/1995
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Cause of Contamination: Unknown
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 94-40
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 12/02/1996
Contaminants Found at Site: PCB's
Petroleum products
Media Contaminated: Groundwater, Soil
Cause of Contamination: Spill
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 94-50
County Code: 17
Contact: Not reported
Report Title: Not reported

BG242
NNW
1/2-1
4101 ft.
Lower
BOEING - NORTH FIELD BUILDING 3-354
ELLIS AVE. S. E. MARGINAL WAY
SEATTLE, WA 98108
Site 8 of 12 in cluster BG

WA ICR **S103505631**
N/A

WA ICR:
Date Ecology Received Report: 04/01/1992
Contaminants Found at Site: Total petroleum hydrocarbons
Media Contaminated: Soil
Cause of Contamination: Not reported
Region: North Western
Type of Report Ecology Received: Final cleanup report
Site Register Issue: 92-21
County Code: 17
Contact: Not reported
Report Title: Not reported

BG243
NNW
1/2-1
4101 ft.
Lower
BOEING NORTH FIELD JP4 TANKS
ELLIS AVE E MARGINAL WAY
SEATTLE, WA 98108
Site 9 of 12 in cluster BG

CSCSL **S102258021**
N/A

SHWS:
Facility ID: 2053
Responsible Unit: NW
Latitude: 47 32 20
Longitude: 122 19 14
Ecology Site Status relative to the MTCA cleanup process:
Awaiting Site Hazard Assessment (SHA)

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

BOEING NORTH FIELD JP4 TANKS (Continued)

EDR ID Number
EPA ID Number

Database(s)

S102258021

Radioactive Wastes: Not reported
Asbestos: Not reported
Conventional Contaminants, Organic: Not reported
Conventional Contaminants, Inorganic: Not reported

BG244
NNW
1/2-1
4101 ft.
Lower

BOEING - NORTH FIELD BUILDING 3/360/361/365
ELLIS AVE. S. E. MARGINAL WAY
SEATTLE, WA 98108

WA ICR S103505633
N/A

Site 10 of 12 in cluster BG

WA ICR:
Date Ecology Received Report: 03/30/1992
Contaminants Found at Site: Halogenated organic compounds
Metals
Petroleum products
Non-halogenated solvents
Media Contaminated: Groundwater
Cause of Contamination: Not reported
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 92-21
County Code: 17
Contact: Not reported
Report Title: Not reported

BF245
NW
1/2-1
4106 ft.
Lower

509 S AUSTIN ST
SEATTLE, WA

SPILLS S105394684
N/A

Site 3 of 4 in cluster BF

WA SPILL:
Facility ID: 514107
Date Received: 10/17/2000
Business Name: METAL WORKING SHOP
Material Desc : PETROLEUM - OIL OTHER
Medium: SURFACE WATER-FRESH
Material Qty: Not reported
Material Units: Not reported

BF246
NW
1/2-1
4106 ft.
Lower

MACHINISTS INC PLANT 2
509 S AUSTIN ST
SEATTLE, WA 98108

FINDS 1004990799
000007558792

Site 4 of 4 in cluster BF

FINDS:
Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)

247
South
1/2-1
4127 ft.
Higher

AAAA MINI STORAGE
1421 S 96TH ST
SEATTLE, WA 98108

RCRIS-SQG 1000838390
FINDS WAD988511689

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

AAAA MINI STORAGE (Continued)

EDR ID Number
EPA ID Number

1000838390

RCRIS:

Owner: AAAA MINI STORAGE
(360) 555-1212
EPA ID: WAD988511689
Contact: KAREN BLACKBURN
(206) 241-4800
Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

248
SSW
1/2-1
4137 ft.
Higher

FRUEHAUF TRAILER SERVICES, INC.
9426 8TH AVE S
SEATTLE, WA 98108

UST U003025233
WA ICR N/A
LUST

LUST:

Facility ID: 101856 Ecology Region: North Western
Release ID: 449549 Release Date: 4/25/1998 00:00:00
Release Status: Cleanup Started Status Date: Not reported
Alternate Name: Not reported
Affected Media: Soil

Facility ID: 101856 Ecology Region: North Western
Release ID: 449549 Release Date: 4/25/1998 00:00:00
Release Status: Cleanup Started Status Date: Not reported
Alternate Name: Not reported
Affected Media: Ground Water

Facility ID: 101856 Ecology Region: North Western
Release ID: 449549 Release Date: 4/25/1998 00:00:00
Release Status: Reported Cleaned Up Status Date: 4/17/1999 00:00:00
Alternate Name: Not reported
Affected Media: Soil

Facility ID: 101856 Ecology Region: North Western
Release ID: 449549 Release Date: 4/25/1998 00:00:00
Release Status: Reported Cleaned Up Status Date: 4/17/1999 00:00:00
Alternate Name: Not reported
Affected Media: Ground Water

WA ICR:

Date Ecology Received Report: 05/20/1998
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 98-04
County Code: 17
Contact: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

FRUEHAUF TRAILER SERVICES, INC. (Continued)

EDR ID Number
EPA ID Number

Database(s)

U003025233

Report Title: Not reported
Date Ecology Received Report: 04/12/1999
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Final cleanup report
Site Register Issue: 98-15
County Code: 17
Contact: Not reported
Report Title: Not reported

UST:

Facility ID: 101856
Install Date: 10/1/1974 0:00
Capacity: 111 TO 1,000 GALLONS
Status: Not reported
Tank Name: USED OIL/WASTE OIL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

BH249
South
1/2-1
4164 ft.
Higher

CLARKLIFT OF WASHINGTON ALASKA, INC.
1313 S 96TH
SEATTLE, WA 98108

UST U003604814
N/A

Site 1 of 2 in cluster BH

UST:

Facility ID: 496565
Install Date: Not reported
Capacity: 2,001 TO 4,999 GALLONS
Status: Not reported
Tank Name: DIESEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 496565
Install Date: Not reported
Capacity: 1,101 TO 2,000 GALLONS
Status: Not reported
Tank Name: USED OIL/WASTE OIL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 496565
Install Date: Not reported
Capacity: 1,101 TO 2,000 GALLONS
Status: Not reported
Tank Name: DIESEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BI250 STERNOFF METALS
NNW 7201 E MARGINAL WY S
1/2-1 SEATTLE, WA 98108
4166 ft.
Lower Site 1 of 4 in cluster BI

CSCSL S104320391
N/A

SHWS:

Facility ID: 2057

Responsible Unit: NW

Latitude: 47 32 20

Longitude: 122 19 14

Ecology Site Status relative to the MTCA cleanup process:

Independent Remedial Action

Independent Site Status - those sites undergoing an independent cleanup:

Not reported

WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):

5 - Lowest assessed risk to human health and to the environment

Affected Media: Soil

Media Status: C (Confirmed) - The presence of hazardous substances above MTCA cleanup levels has been confirmed by laboratory analysis (or field determination in the case of petroleum contamination)

Arsenic Code: Not reported

Base/Neutral/Acid Organics: Not reported

Halogenated Organic Compounds: Not reported

Horizontal Collection Method: 3

EPA Priority Pollutants - Metals and Cyanide: Confirmed above MTCA cleanup levels

Metals - Other non-priority pollutant metals: Not reported

Polychlorinated biPhenyls (PCBs): Confirmed above MTCA cleanup levels

Pesticides: Not reported

Petroleum Products: Not reported

Phenolic Compounds: Not reported

Non-Halogenated Solvents: Not reported

Dioxin: Not reported

Polynuclear Aromatic Hydrocarbons (PAH): Not reported

Reactive Wastes: Not reported

Corrosive Wastes: Not reported

Radioactive Wastes: Not reported

Asbestos: Not reported

Conventional Contaminants, Organic: Not reported

Conventional Contaminants, Inorganic: Not reported

Facility ID: 2057

Responsible Unit: NW

Latitude: 47 32 20

Longitude: 122 19 14

Ecology Site Status relative to the MTCA cleanup process:

Independent Remedial Action

Independent Site Status - those sites undergoing an independent cleanup:

Not reported

WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):

5 - Lowest assessed risk to human health and to the environment

Affected Media: Surface Water

Media Status: S (Suspected) - Due to preliminary investigations or the nature of business operations or manufacturing processes, certain contaminants are suspected to be present at the site

Arsenic Code: Not reported

Base/Neutral/Acid Organics: Not reported

Halogenated Organic Compounds: Not reported

Horizontal Collection Method: 3

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

STERNOFF METALS (Continued)

S104320391

EPA Priority Pollutants - Metals and Cyanide: Suspected to be present
Metals - Other non-priority pollutant metals: Not reported
Polychlorinated biPhenyls (PCBs): Suspected to be present
Pesticides: Not reported
Petroleum Products: Not reported
Phenolic Compounds: Not reported
Non-Halogenated Solvents: Not reported
Dioxin: Not reported
Polynuclear Aromatic Hydrocarbons (PAH): Not reported
Reactive Wastes: Not reported
Corrosive Wastes: Not reported
Radioactive Wastes: Not reported
Asbestos: Not reported
Conventional Contaminants, Organic: Not reported
Conventional Contaminants, Inorganic: Not reported

Facility ID: 2057
Responsible Unit: NW
Latitude: 47 32 20
Longitude: 122 19 14

Ecology Site Status relative to the MTCA cleanup process:

Independent Remedial Action

Independent Site Status - those sites undergoing an independent cleanup:
Not reported

WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):
5 - Lowest assessed risk to human health and to the environment

Affected Media: Ground Water

Media Status: C (Confirmed) - The presence of hazardous substances above MTCA cleanup levels has been confirmed by laboratory analysis (or field determination in the case of petroleum contamination)

Arsenic Code: Not reported

Base/Neutral/Acid Organics: Not reported

Halogenated Organic Compounds: Not reported

Horizontal Collection Method: 3

EPA Priority Pollutants - Metals and Cyanide: Confirmed above MTCA cleanup levels

Metals - Other non-priority pollutant metals: Not reported

Polychlorinated biPhenyls (PCBs): Confirmed above MTCA cleanup levels

Pesticides: Not reported

Petroleum Products: Confirmed above MTCA cleanup levels

Phenolic Compounds: Not reported

Non-Halogenated Solvents: Not reported

Dioxin: Not reported

Polynuclear Aromatic Hydrocarbons (PAH): Not reported

Reactive Wastes: Not reported

Corrosive Wastes: Not reported

Radioactive Wastes: Not reported

Asbestos: Not reported

Conventional Contaminants, Organic: Not reported

Conventional Contaminants, Inorganic: Not reported

BI251 STERNOFF METALS FORMER) TWO REPORTS)
NNW 7201 E. MARGINAL WAY S.
1/2-1 SEATTLE, WA 98108
4166 ft.
Lower Site 2 of 4 in cluster BI

WA ICR S104485687
N/A

WA ICR:
Date Ecology Received Report: 06/07/1999
Contaminants Found at Site: PCB's

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

STERNOFF METALS FORMER) TWO REPORTS) (Continued)

EDR ID Number
EPA ID Number

Database(s)

S104485687

Media Contaminated: Petroleum products
Cause of Contamination: Groundwater, Soil
Region: Not reported
Type of Report Ecology Received: North Western
Site Register Issue: Interim cleanup report
County Code: 98-17
Contact: 17
Report Title: Not reported
Not reported

BI252
NNW
1/2-1
4166 ft.
Lower

REMEDCO INC
7201 E MARGINAL WY S
SEATTLE, WA 98108

FINDS 1004612854
C10#10-97041

Site 3 of 4 in cluster BI

FINDS:
Other Pertinent Environmental Activity Identified at Site:
National Compliance Database (NCDB)

BI253
NNW
1/2-1
4166 ft.
Lower

REMEDCO INC
7201 E MARGINAL WAY SOUTH
SEATTLE, WA 98108

FTTS 1004644958
N/A

Site 4 of 4 in cluster BI

FTTS Insp:
Region: 10
Inspected Date: 09/16/96
Insp Number: 09/16/96
Violation occurred: Yes
Inspector: MCDERMOTT
Investigation Type: Section 6 PCB Federal Conducted
Facility Function: User
Investig Reason: Neutral Scheme, Region
Legislation Code: TSCA

BG254
NNW
1/2-1
4167 ft.
Lower

REMARKABLE TIRE
7115 E MARGINAL WAY S
SEATTLE, WA 98108

UST U000592053
N/A

Site 11 of 12 in cluster BG

UST:
Facility ID: 7577
Install Date: 12/31/1964 0:00
Capacity: 111 to 1,100 Gallons
Status: Not reported
Tank Name: USED OIL/WASTE OIL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

REMARKABLE TIRE (Continued)

U000592053

Facility ID: 7577
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: Not reported
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 7577
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: Not reported
Substance: NW
Compartment #: Not reported
Ecology Region: 1

BG255
NNW
1/2-1
4167 ft.
Lower

BUDGET PROPERTIES
7115 E MARGINAL WAY
SEATTLE, WA 98108
Site 12 of 12 in cluster BG

UST U001122898
N/A

UST:

Facility ID: 2797
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: LEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 2797
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: UNLEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

BH256
South
1/2-1
4168 ft.
Higher
PACIFIC UTILITY EQUIPMENT CO
1303 S 96TH ST
SEATTLE, WA 98108
Site 2 of 2 in cluster BH

RCRIS-SQG 1001490220
FINDS WAD009481078

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

PACIFIC UTILITY EQUIPMENT CO (Continued)

1001490220

RCRIS:

Owner: UTILITY EQUIPMENT INC
(503) 620-0611
EPA ID: WAD009481078
Contact: WAYNE MILLER
(206) 764-5025
Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

257
South
1/2-1
4193 ft.
Higher

S 96TH ST & DESMOINES WAY
S 96TH ST & DESMOINES WAY
SEATTLE, WA

ERNS 90154862
N/A

258
SSE
1/2-1
4234 ft.
Higher

S 96TH ST DITCH
S 96TH ST DUWAMISH RIVER
SEATTLE, WA 98108

CSCSL S102258309
N/A

SHWS:

Facility ID: 2058
Responsible Unit: NW
Latitude: 47 31 28
Longitude: 122 18 8
Ecology Site Status relative to the MTCA cleanup process:
Awaiting Site Hazard Assessment (SHA)
Independent Site Status - those sites undergoing an independent cleanup:
Not reported
WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):
Not reported
Affected Media: Air
Media Status: S (Suspected) - Due to preliminary investigations or the nature of business operations
or manufacturing processes, certain contaminants are suspected to be present at the
site
Arsenic Code: Not reported
Base/Neutral/Acid Organics: Not reported
Halogenated Organic Compounds: Suspected to be present
Horizontal Collection Method: 99
EPA Priority Pollutants - Metals and Cyanide: Suspected to be present
Metals - Other non-priority pollutant metals: Suspected to be present
Polychlorinated biPhenyls (PCBs): Not reported
Pesticides: Suspected to be present
Petroleum Products: Suspected to be present
Phenolic Compounds: Suspected to be present
Non-Halogenated Solvents: Suspected to be present
Dioxin: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation

Site

MAP FINDINGS

Database(s)

EDR ID Number
EPA ID Number

S 96TH ST DITCH (Continued)

S102258309

Polynuclear Aromatic Hydrocarbons (PAH): Suspected to be present
Reactive Wastes: Suspected to be present
Corrosive Wastes: Suspected to be present
Radioactive Wastes: Suspected to be present
Asbestos: Not reported
Conventional Contaminants, Organic: Suspected to be present
Conventional Contaminants, Inorganic: Suspected to be present

Facility ID: 2058
Responsible Unit: NW
Latitude: 47 31 28
Longitude: 122 18 8

Ecology Site Status relative to the MTCA cleanup process:
Awaiting Site Hazard Assessment (SHA)

Independent Site Status - those sites undergoing an independent cleanup:
Not reported

WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):
Not reported

Affected Media: Soil

Media Status: C (Confirmed) - The presence of hazardous substances above MTCA cleanup levels has been confirmed by laboratory analysis (or field determination in the case of petroleum contamination)

Arsenic Code: Not reported

Base/Neutral/Acid Organics: Not reported

Halogenated Organic Compounds: Suspected to be present

Horizontal Collection Method: 99

EPA Priority Pollutants - Metals and Cyanide: Confirmed above MTCA cleanup levels

Metals - Other non-priority pollutant metals: Confirmed above MTCA cleanup levels

Polychlorinated biPhenyls (PCBs): Suspected to be present

Pesticides: Suspected to be present

Petroleum Products: Confirmed above MTCA cleanup levels

Phenolic Compounds: Suspected to be present

Non-Halogenated Solvents: Suspected to be present

Dioxin: Suspected to be present

Polynuclear Aromatic Hydrocarbons (PAH): Confirmed above MTCA cleanup levels

Reactive Wastes: Suspected to be present

Corrosive Wastes: Suspected to be present

Radioactive Wastes: Suspected to be present

Asbestos: Not reported

Conventional Contaminants, Organic: Suspected to be present

Conventional Contaminants, Inorganic: Confirmed above MTCA cleanup levels

Facility ID: 2058
Responsible Unit: NW
Latitude: 47 31 28
Longitude: 122 18 8

Ecology Site Status relative to the MTCA cleanup process:
Awaiting Site Hazard Assessment (SHA)

Independent Site Status - those sites undergoing an independent cleanup:
Not reported

WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):
Not reported

Affected Media: Sediments

Media Status: C (Confirmed) - The presence of hazardous substances above MTCA cleanup levels has been confirmed by laboratory analysis (or field determination in the case of petroleum contamination)

Arsenic Code: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

S 96TH ST DITCH (Continued)

S102258309

Base/Neutral/Acid Organics:	Not reported
Halogenated Organic Compounds:	Suspected to be present
Horizontal Collection Method:	99
EPA Priority Pollutants - Metals and Cyanide:	Confirmed above MTCA cleanup levels
Metals - Other non-priority pollutant medals:	Confirmed above MTCA cleanup levels
Polychlorinated biPhenyls (PCBs):	Suspected to be present
Pesticides:	Suspected to be present
Petroleum Products:	Confirmed above MTCA cleanup levels
Phenolic Compounds:	Suspected to be present
Non-Halogenated Solvents:	Suspected to be present
Dioxin:	Suspected to be present
Polynuclear Aromatic Hydrocarbons (PAH):	Confirmed above MTCA cleanup levels
Reactive Wastes:	Suspected to be present
Corrosive Wastes:	Suspected to be present
Radioactive Wastes:	Suspected to be present
Asbestos:	Not reported
Conventional Contaminants, Organic:	Suspected to be present
Conventional Contaminants, Inorganic:	Suspected to be present

Facility ID: 2058
Responsible Unit: NW
Latitude: 47 31 28
Longitude: 122 18 8

Ecology Site Status relative to the MTCA cleanup process:
Awaiting Site Hazard Assessment (SHA)

Independent Site Status - those sites undergoing an independent cleanup:
Not reported

WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):
Not reported

Affected Media: Ground Water
Media Status: S (Suspected) - Due to preliminary investigations or the nature of business operations or manufacturing processes, certain contaminants are suspected to be present at the site

Arsenic Code:	Not reported
Base/Neutral/Acid Organics:	Not reported
Halogenated Organic Compounds:	Suspected to be present
Horizontal Collection Method:	99
EPA Priority Pollutants - Metals and Cyanide:	Suspected to be present
Metals - Other non-priority pollutant medals:	Suspected to be present
Polychlorinated biPhenyls (PCBs):	Suspected to be present
Pesticides:	Suspected to be present
Petroleum Products:	Suspected to be present
Phenolic Compounds:	Suspected to be present
Non-Halogenated Solvents:	Suspected to be present
Dioxin:	Suspected to be present
Polynuclear Aromatic Hydrocarbons (PAH):	Suspected to be present
Reactive Wastes:	Suspected to be present
Corrosive Wastes:	Suspected to be present
Radioactive Wastes:	Suspected to be present
Asbestos:	Not reported
Conventional Contaminants, Organic:	Suspected to be present
Conventional Contaminants, Inorganic:	Suspected to be present

Facility ID: 2058
Responsible Unit: NW
Latitude: 47 31 28
Longitude: 122 18 8

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

S 96TH ST DITCH (Continued)

EDR ID Number
EPA ID Number

Database(s)

S102258309

Ecology Site Status relative to the MTCA cleanup process:
Awaiting Site Hazard Assessment (SHA)
Independent Site Status - those sites undergoing an independent cleanup:
Not reported
WARM Bin Number indicates the outcome of the Washington Ranking Model (WARM):
Not reported
Affected Media: Surface Water
Media Status: S (Suspected) - Due to preliminary investigations or the nature of business operations or manufacturing processes, certain contaminants are suspected to be present at the site
Arsenic Code: Not reported
Base/Neutral/Acid Organics: Not reported
Halogenated Organic Compounds: Suspected to be present
Horizontal Collection Method: 99
EPA Priority Pollutants - Metals and Cyanide: Suspected to be present
Metals - Other non-priority pollutant medals: Suspected to be present
Polychlorinated biPhenyls (PCBs): Suspected to be present
Pesticides: Suspected to be present
Petroleum Products: Suspected to be present
Phenolic Compounds: Suspected to be present
Non-Halogenated Solvents: Suspected to be present
Dioxin: Suspected to be present
Polynuclear Aromatic Hydrocarbons (PAH): Suspected to be present
Reactive Wastes: Suspected to be present
Corrosive Wastes: Suspected to be present
Radioactive Wastes: Suspected to be present
Asbestos: Not reported
Conventional Contaminants, Organic: Suspected to be present
Conventional Contaminants, Inorganic: Suspected to be present

BJ259
WNW
1/2-1
4259 ft.
Lower

GLITSA AMERICAN INC
327 S KENYON ST
SEATTLE, WA 98108

FINDS 1005106759
000009112952

Site 1 of 2 in cluster BJ

FINDS:
Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)

BJ260
WNW
1/2-1
4259 ft.
Lower

GLITSA AMERICAN INCORPORATED
327 SOUTH KENYON STREET
SEATTLE, WA 98108

UST U003027657
LUST N/A

Site 2 of 2 in cluster BJ

LUST:
Facility ID: 6178 Ecology Region: North Western
Release ID: 3910 Release Date: 9/2/1992 00:00:00
Release Status: Cleanup Started Status Date: 6/1/1995 00:00:00
Alternate Name: GLITSA AMERICAN INC
Affected Media: Soil

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

GLITSA AMERICAN INCORPORATED (Continued)

U003027657

UST:

Facility ID: 6178
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: Not reported
Substance: NW
Compartment #: Not reported
Ecology Region: 1

261
NW
1/2-1
4261 ft.
Lower

RED-D INC
7510 5TH AVE SO
SEATTLE, WA 98108

UST U001122178
N/A

UST:

Facility ID: 850
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: LEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

BK262
NE
1/2-1
4265 ft.
Higher

NORDSTROM INC
7979 PERIMETER RD SO
SEATTLE, WA 98108

UST 1000192842
N/A

Site 1 of 2 in cluster BK

UST:

Facility ID: 8045
Install Date: 12/9/1985 0:00
Capacity: 10,000 TO 19,999 GALLONS
Status: Not reported
Tank Name: AVIATION FUEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 8045
Install Date: 3/31/1986 0:00
Capacity: 111 to 1,100 Gallons
Status: Not reported
Tank Name: USED OIL/WASTE OIL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NORDSTROM INC (Continued)

1000192842

Facility ID: 8045
Install Date: 12/9/1985 0:00
Capacity: 10,000 TO 19,999 GALLONS
Status: Not reported
Tank Name: AVIATION FUEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

BK263
NE
1/2-1
4267 ft.
Higher

AERO-COPTERS, INC.
8013 PERIMETER RD S
SEATTLE, WA 98108

Site 2 of 2 in cluster BK

UST **U003028462**
N/A

UST:

Facility ID: 8340
Install Date: 9/15/1981 0:00
Capacity: 10,000 TO 19,999 GALLONS
Status: Not reported
Tank Name: DIESEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

BL264
NE
1/2-1
4272 ft.
Higher

8075 PERIMETER ROAD SOUTH
SEATTLE, WA

Site 1 of 2 in cluster BL

HMIRS **9999061135**
N/A

BL265
NE
1/2-1
4272 ft.
Higher

8075 PERIMETER ROAD SOUTH
SEATTLE, WA

Site 2 of 2 in cluster BL

HMIRS **9900006533**
N/A

BM266
NE
1/2-1
4272 ft.
Higher

SEATTLE CITY LIGHT MUNICIPAL BOEING FIEL
7777 PERIMETER RD
SEATTLE, WA 98108

Site 1 of 7 in cluster BM

FINDS **1004613819**
110#19890417

FINDS:

Other Pertinent Environmental Activity Identified at Site:
National Compliance Database (NCDB)

BM267
NE
1/2-1
4272 ft.
Higher

GALVIN FLYING SERVICES INC
7777 PERIMETER ROAD S.
SEATTLE, WA 98108

Site 2 of 7 in cluster BM

WA ICR **S105124714**
N/A

WA ICR:

Date Ecology Received Report: 10/22/2001

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

GALVIN FLYING SERVICES INC (Continued)

EDR ID Number
EPA ID Number

Database(s)

S105124714

Contaminants Found at Site: Petroleum products
Vinyl chloride
Media Contaminated: Soil, Groundwater
Cause of Contamination: Not reported
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 98-41
County Code: 17
Contact: Not reported
Report Title: Release Notification

BM268
NE
1/2-1
4272 ft.
Higher

MCCAW FLIGHT OPERATIONS
7777 PERIMETER RD S
SEATTLE, WA 98108

FINDS **1005106744**
000009112796

Site 3 of 7 in cluster BM

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)

BM269
NE
1/2-1
4272 ft.
Higher

SEATTLE CITY LIGHT MUNICIPAL B
7777 PERIMETER RD
SEATTLE, WA 98108

RAATS **1000160386**
N/A

Site 4 of 7 in cluster BM

BM270
NE
1/2-1
4272 ft.
Higher

OTTER CORP (IMPORTER)
7777 PERIMETER RD S
SEATTLE, WA 98108

FINDS **1005367531**
000012299598

Site 5 of 7 in cluster BM

FINDS:

Other Pertinent Environmental Activity Identified at Site:
National Compliance Database (NCDB)

BM271
NE
1/2-1
4272 ft.
Higher

OTTER CORP (IMPORTER)
7777 PERIMETER RD SOUTH
SEATTLE, WA 98108

FTTS **1004655339**
N/A

Site 6 of 7 in cluster BM

FTTS Insp:

Region: 10
Inspected Date: 10/03/01
Insp Number: 10/03/01
Violation occurred: Yes
Inspector: SCHULZE
Investigation Type: Specific Product Review
Facility Function: Port of Entry
Investig Reason: For Cause, Government
Legislation Code: FIFRA

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BM272
NE
1/2-1
4272 ft.
Higher
MCCAW FLIGHT OPERATIONS
7777 PERIMETER RD S
SEATTLE, WA 98108
Site 7 of 7 in cluster BM

RCRIS-SQG **1001969487**
WAD103351284

RCRIS:

Owner: MCCAW FLIGHT OPERATIONS
(360) 555-1212

EPA ID: WAD103351284

Contact: TIMOTHY ANDERSON
(206) 762-6000

Classification: N, Small Quantity Generator

Used Oil Recyc: No

TSDF Activities: Not reported

Violation Status: No violations found

BN273
SSW
1/2-1
4277 ft.
Higher
SUNNYDALE CONSTRUCTION CO., INC.
1119 S 96TH
SEATTLE, WA 98108
Site 1 of 6 in cluster BN

UST **U001125772**
LUST **N/A**

LUST:

Facility ID: 9109
Release ID: 417097
Release Status: Cleanup Started
Alternate Name: Not reported
Affected Media: Soil

Ecology Region: North Western
Release Date: 6/2/1997 00:00:00
Status Date: 2/13/1997 00:00:00

Facility ID: 9109
Release ID: 417097
Release Status: Reported Cleaned Up
Alternate Name: Not reported
Affected Media: Soil

Ecology Region: North Western
Release Date: 6/2/1997 00:00:00
Status Date: 5/21/1997 00:00:00

UST:

Facility ID: 9109
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: UNLEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 9109
Install Date: 12/31/1964 0:00
Capacity: 111 to 1,100 Gallons
Status: Not reported
Tank Name: LEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

SUNNYDALE CONSTRUCTION CO., INC. (Continued)

U001125772

Facility ID: 9109
Install Date: 6/1/1978 0:00
Capacity: 2,001 TO 4,999 GALLONS
Status: Not reported
Tank Name: DIESEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 9109
Install Date: 6/1/1978 0:00
Capacity: 111 to 1,100 Gallons
Status: Not reported
Tank Name: USED OIL/WASTE OIL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

BN274 1115 S. 96 TH ST.
SSW 1115 S. 96 TH ST.
1/2-1 SEATTLE, WA
4281 ft.
Higher Site 2 of 6 in cluster BN

ERNS 877026
N/A

BN275 M.A. SEGALE, INC.
SSW 1115 S 96TH
1/2-1 SEATTLE, WA 98108
4281 ft.
Higher Site 3 of 6 in cluster BN

UST U003027197
LUST N/A

LUST:

Facility ID: 4980 Ecology Region: North Western
Release ID: 4137 Release Date: 5/31/1991 00:00:00
Release Status: Cleanup Started Status Date: 5/31/1991 00:00:00
Alternate Name: SEGALE M A ASPHALT PLANT
Affected Media: Soil

Facility ID: 4980 Ecology Region: North Western
Release ID: 4137 Release Date: 5/31/1991 00:00:00
Release Status: Reported Cleaned Up Status Date: 6/1/1995 00:00:00
Alternate Name: SEGALE M A ASPHALT PLANT
Affected Media: Soil

UST:

Facility ID: 4980
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: Not reported
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Map ID
Direction
Distance
Distance (ft.)
Elevation

Site

MAP FINDINGS

Database(s)

EDR ID Number
EPA ID Number

M.A. SEGALE, INC. (Continued)

U003027197

Facility ID: 4980
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: UNLEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 4980
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: Not reported
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 4980
Install Date: 12/31/1964 0:00
Capacity: 111 to 1,100 Gallons
Status: Not reported
Tank Name: USED OIL/WASTE OIL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 4980
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: Not reported
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 4980
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: Not reported
Substance: NW
Compartment #: Not reported
Ecology Region: 1

BN276
SSW
1/2-1
4281 ft.
Higher

**M A SEGALE INC
SEATTLE ASPHALT PLANT
SEATTLE, WA 98108**

Site 4 of 6 in cluster BN

**RCRIS-SQG 1004613873
FINDS WAD980382840**

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

M A SEGALE INC (Continued)

EDR ID Number
EPA ID Number

Database(s)

1004613873

RCRIS:

Owner: MAS RESOURCES INC
(206) 575-2000
EPA ID: WAD980382840
Contact: MARK SEGALE
(206) 575-2000

Classification: N, Conditionally Exempt Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Permit Compliance System (PCS)

BN277
SSW
1/2-1
4283 ft.
Higher

SUNNYDALE CONSTRUCTION
1110 S. 96TH
SEATTLE, WA 98108

WA ICR S104488737
N/A

Site 5 of 6 in cluster BN

WA ICR:

Date Ecology Received Report: 06/02/1997
Contaminants Found at Site: Petroleum products
Media Contaminated: Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Final cleanup report
Site Register Issue: 95-01
County Code: 17
Contact: Not reported
Report Title: Not reported

278
ENE
1/2-1
4289 ft.
Higher

8201 PERIMETER RD S
SEATTLE, WA

HMIRS 9998091090
N/A

BO279
NE
1/2-1
4290 ft.
Higher

US WEST COMMUNICATIONS W00D04
7679 PERIMETER RD S
SEATTLE, WA 98134

RCRIS-SQG 1001490436
FINDS WAD981772742

Site 1 of 6 in cluster BO

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

US WEST COMMUNICATIONS W00D04 (Continued)

EDR ID Number
EPA ID Number

Database(s)

1001490436

RCRIS:

Owner: GALVIN FLYING SERVICE INC
(206) 763-0350
EPA ID: WAD981772742
Contact: ZELMA ZIEMAN
(206) 346-7532

Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSD Activities: Not reported
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

BO280
NE
1/2-1
4292 ft.
Higher

HANGAR HOLDINGS, INC.
7675 PERIMETER ROAD S.
SEATTLE, WA 98108

WA ICR S105225144
N/A

Site 2 of 6 in cluster BO

WA ICR:

Date Ecology Received Report: 08/14/2001
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Final cleanup report
Site Register Issue: 98-43
County Code: 17
Contact: Not reported
Report Title: Release Report and Investigation Summary

BO281
NE
1/2-1
4292 ft.
Higher

HANGAR HOLDINGS, INC.
7675 PERIMETER ROAD S.
SEATTLE, WA 98108

WA ICR S105225145
N/A

Site 3 of 6 in cluster BO

WA ICR:

Date Ecology Received Report: 08/14/2001
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 98-43
County Code: 17
Contact: Not reported
Report Title: Draft Estimated Extent and Volume of Contaminated Soil

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

BO282
NE
1/2-1
4292 ft.
Higher

AVIATION METHODS, INC.
7675 PERIMETER RD S
SEATTLE, WA 98108

Site 4 of 6 in cluster BO

Database(s)
EPA ID Number

EDR ID Number
EPA ID Number

UST
LUST
SPILLS

U003528693
N/A

LUST:

Facility ID: 484990 Ecology Region: North Western
Release ID: 587690 Release Date: 8/14/2001 00:00:00
Release Status: Cleanup Started Status Date: 7/25/1997 00:00:00
Alternate Name: HANGAR HOLDINGS INC (FORMER SHELL OIL)
Affected Media: Soil

Facility ID: 484990 Ecology Region: North Western
Release ID: 587690 Release Date: 8/14/2001 00:00:00
Release Status: Cleanup Started Status Date: 7/25/1997 00:00:00
Alternate Name: HANGAR HOLDINGS INC (FORMER SHELL OIL)
Affected Media: Ground Water

WA SPILL:

Facility ID: 522815
Date Received: 08/14/2001
Business Name: KING COUNTY INTERNATIONAL AIRPORT
Material Desc: PETROLEUM - JET FUEL
Medium: GROUND WATER
Material Qty: 10000
Material Units: CUBIC YARD

UST:

Facility ID: 484990
Install Date: Not reported
Capacity: 10,000 TO 19,999 GALLONS
Status: Not reported
Tank Name: AVIATION FUEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 484990
Install Date: Not reported
Capacity: 30,000 TO 49,999 GALLONS
Status: Not reported
Tank Name: AVIATION FUEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 484990
Install Date: Not reported
Capacity: 10,000 TO 19,999 GALLONS
Status: Not reported
Tank Name: AVIATION FUEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

AVIATION METHODS, INC. (Continued)

U003528693

Facility ID: 484990
Install Date: Not reported
Capacity: 5,000 TO 9,999 GALLONS
Status: Not reported
Tank Name: AVIATION FUEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 484990
Install Date: Not reported
Capacity: 10,000 TO 19,999 GALLONS
Status: Not reported
Tank Name: AVIATION FUEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 484990
Install Date: Not reported
Capacity: 10,000 TO 19,999 GALLONS
Status: Not reported
Tank Name: AVIATION FUEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 484990
Install Date: Not reported
Capacity: 10,000 TO 19,999 GALLONS
Status: Not reported
Tank Name: AVIATION FUEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 484990
Install Date: Not reported
Capacity: 2,001 TO 4,999 GALLONS
Status: Not reported
Tank Name: Not reported
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 484990
Install Date: 9/27/1998 0:00
Capacity: Not reported
Status: Not reported
Tank Name: AVIATION FUEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

AVIATION METHODS, INC. (Continued)

EDR ID Number
EPA ID Number

Database(s)

U003528693

Facility ID: 484990
Install Date: 9/27/1998 0:00
Capacity: Not reported
Status: Not reported
Tank Name: AVIATION FUEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

BO283
NE
1/2-1
4292 ft.
Higher

US DOT FAA SEATTLE HUB AFS
7675 PERIMETER RD S
SEATTLE, WA 98108

RCRIS-SQG
FINDS

1000342736
WA8690590007

Site 5 of 6 in cluster BO

RCRIS:

Owner: US DOT FAA
(360) 555-1212
EPA ID: WA8690590007
Contact: JAMES FIRESTINE
(425) 227-2639
Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSD Activities: Not reported
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

BO284
NE
1/2-1
4292 ft.
Higher

HANGAR HOLDINGS, INC.
7675 PERIMETER ROAD S.
SEATTLE, WA 98108

WA ICR

S105225146
N/A

Site 6 of 6 in cluster BO

WA ICR:

Date Ecology Received Report: 08/14/2001
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 98-43
County Code: 17
Contact: Not reported
Report Title: Ground Water Quality Testing Results

BP285
ENE
1/2-1
4304 ft.
Higher

FLIGHTCRAFT INC SEATTLE
8285 PERIMETER RD S
SEATTLE, WA 98108

RCRIS-SQG
FINDS
CSCSL NFA
WA ICR

1001490315
WAD063351332

Site 1 of 2 in cluster BP

Map ID
Direction
Distance
Distance (ft.)
Elevation

Site

MAP FINDINGS

Database(s)

EDR ID Number
EPA ID Number

FLIGHTCRAFT INC SEATTLE (Continued)

1001490315

RCRIS:

Owner: PAPE PROPERTIES INC
(360) 555-1212
EPA ID: WAD063351332
Contact: DONALD SCHRAM
(503) 331-4263
Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

WA NFA:

Facility/Site Id : 6436627
Ecology Status : Independent Remedial Action
Independent Status Code : Final Independent RA Report received
WARM Bin Number : Not reported
NFA Code : NFA after Assesment IRAP or VCP
NFA Date : 7/23/1996 00:00:00

WA ICR:

Date Ecology Received Report: 02/27/1995
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 93-47
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: / /
Contaminants Found at Site: Petroleum products
Media Contaminated: Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 92-40
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 11/08/1991
Contaminants Found at Site: Petroleum products
Media Contaminated: Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Final cleanup report
Site Register Issue: 92-11
County Code: 17
Contact: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

FLIGHTCRAFT INC SEATTLE (Continued)

1001490315

Report Title:	Not reported
Date Ecology Received Report:	05/05/1999
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Cause of Contamination:	Tank
Region:	North Western
Type of Report Ecology Received:	Final cleanup report
Site Register Issue:	98-15
County Code:	17
Contact:	Not reported
Report Title:	Not reported
Date Ecology Received Report:	07/22/1996
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Cause of Contamination:	Tank
Region:	North Western
Type of Report Ecology Received:	Final cleanup report
Site Register Issue:	95-01
County Code:	17
Contact:	Not reported
Report Title:	Not reported
Date Ecology Received Report:	05/22/1996
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Cause of Contamination:	Tank
Region:	North Western
Type of Report Ecology Received:	Final cleanup report
Site Register Issue:	95-01
County Code:	17
Contact:	Not reported
Report Title:	Not reported
Date Ecology Received Report:	03/13/1996
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Cause of Contamination:	Tank
Region:	North Western
Type of Report Ecology Received:	Final cleanup report
Site Register Issue:	95-01
County Code:	17
Contact:	Not reported
Report Title:	Not reported
Date Ecology Received Report:	01/29/1996
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Cause of Contamination:	Tank
Region:	North Western
Type of Report Ecology Received:	Final cleanup report
Site Register Issue:	95-01
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

FLIGHTCRAFT INC SEATTLE (Continued)

EDR ID Number
EPA ID Number

Database(s)

1001490315

Date Ecology Received Report: 12/21/1995
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 95-01
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 11/17/1995
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 95-01
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 11/16/1995
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 95-01
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 11/09/1995
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 95-01
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 08/07/1995
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 95-01
County Code: 17
Contact: Not reported
Report Title: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

BP286 MCCAW FLIGHT OPERATIONS, INC.
ENE 8285 PERIMETER RD S
1/2-1 SEATTLE, WA 98108
4304 ft.
Higher Site 2 of 2 in cluster BP

Database(s) EDR ID Number
EPA ID Number

UST 1000235019
N/A

UST:

Facility ID: 8044
Install Date: 6/4/1996 0:00
Capacity: Not reported
Status: Not reported
Tank Name: UNLEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 8044
Install Date: 6/4/1996 0:00
Capacity: Not reported
Status: Not reported
Tank Name: AVIATION FUEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 8044
Install Date: 6/4/1996 0:00
Capacity: Not reported
Status: Not reported
Tank Name: AVIATION FUEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 8044
Install Date: 6/4/1996 0:00
Capacity: Not reported
Status: Not reported
Tank Name: AVIATION FUEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 8044
Install Date: 1/1/1985 0:00
Capacity: Not reported
Status: Not reported
Tank Name: AVIATION FUEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Map ID
Direction
Distance
Distance (ft.)
Elevation

Site

MAP FINDINGS

Database(s)

EDR ID Number
EPA ID Number

MCCAW FLIGHT OPERATIONS, INC. (Continued)

1000235019

Facility ID: 8044
Install Date: 1/1/1985 0:00
Capacity: Not reported
Status: Not reported
Tank Name: AVIATION FUEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 8044
Install Date: 1/1/1978 0:00
Capacity: Not reported
Status: Not reported
Tank Name: UNLEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 8044
Install Date: 1/1/1985 0:00
Capacity: Not reported
Status: Not reported
Tank Name: AVIATION FUEL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 8044
Install Date: 12/31/1964 0:00
Capacity: 111 to 1,100 Gallons
Status: Not reported
Tank Name: USED OIL/WASTE OIL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 8044
Install Date: 12/31/1964 0:00
Capacity: 111 to 1,100 Gallons
Status: Not reported
Tank Name: USED OIL/WASTE OIL
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Facility ID: 8044
Install Date: 12/31/1964 0:00
Capacity: 111 to 1,100 Gallons
Status: Not reported
Tank Name: KEROSENE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

287
East
1/2-1
4307 ft.
Higher

BURLINGTON RESOURCE AVIATION
7777 PERIMETER RD HANGAR B
SEATTLE, WA 98108

RCRIS-SQG 1000285950
FINDS WAD980983464

RCRIS:

Owner: BURLINGTON RESOURCE AVIATION
(360) 555-1212
EPA ID: WAD980983464
Contact: JOHN GIBSON
(713) 821-2585

Classification: N, Small Quantity Generator
Used Oil Recyc: No
TSD Activities: Not reported

Violation Status: Violations exist

Regulation Violated: Not reported
Area of Violation: GENERATOR-ALL REQUIREMENTS (OVERSIGHT)
Date Violation Determined: 03/27/1990
Enforcement Action: WRITTEN INFORMAL
Enforcement Action Date: 06/29/1990
Penalty Type: Not reported

There are 1 violation record(s) reported at this site:

Evaluation	Area of Violation	Date of Compliance
Compliance Evaluation Inspection	GENERATOR-ALL REQUIREMENTS (OVERSIGHT)	08/01/199

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

BQ288
NE
1/2-1
4310 ft.
Higher

7607 PERIMETER ROAD
SEATTLE, WA

HMIRS 9998030647
N/A

Site 1 of 14 in cluster BQ

BQ289
NE
1/2-1
4310 ft.
Higher

FEDERAL EXPRESS PERIMETER RD SEA
7607 PERIMETER RD S
SEATTLE, WA 98108

RCRIS-SQG 1000214204
FINDS WAD988474698
WA ICR

Site 2 of 14 in cluster BQ

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

FEDERAL EXPRESS PERIMETER RD SEA (Continued)

EDR ID Number
EPA ID Number

Database(s)

1000214204

RCRIS:

Owner: FEDERAL EXPRESS CORP
(360) 555-1212
EPA ID: WAD988474698
Contact: SALLY MCCORMICK
(206) 762-9408

Classification: Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

WA ICR:

Date Ecology Received Report: 08/08/1991
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Cause of Contamination: Tank
Region: North Western
Type of Report Ecology Received: Final cleanup report
Site Register Issue: 92-06
County Code: 17
Contact: Not reported
Report Title: Not reported

BQ290
NE
1/2-1
4310 ft.
Higher

7607 PERIMETER RD S
SEATTLE, WA
Site 3 of 14 in cluster BQ

HMIRS 9998120772
N/A

BQ291
NE
1/2-1
4310 ft.
Higher

7607 PERIMETER ROAD
SEATTLE, WA
Site 4 of 14 in cluster BQ

HMIRS 97110478
N/A

BQ292
NE
1/2-1
4310 ft.
Higher

BFI FEDERAL EXPRESS STATION
7607 PERIMETER RD
SEATTLE, WA 98108
Site 5 of 14 in cluster BQ

UST U000587551
LUST N/A

LUST:

Facility ID: 2392 Ecology Region: North Western
Release ID: 1676 Release Date: 1/12/1990 00:00:00
Release Status: Cleanup Started Status Date: 1/12/1990 00:00:00
Alternate Name: FEDERAL EXPRESS BOEING FIELD
Affected Media: Soil

Map ID
Direction
Distance
Distance (ft.)
Elevation

Site

MAP FINDINGS

Database(s)

EDR ID Number
EPA ID Number

BFI FEDERAL EXPRESS STATION (Continued)

U000587551

Facility ID: 2392 Ecology Region: North Western
Release ID: 1676 Release Date: 1/12/1990 00:00:00
Release Status: Cleanup Started Status Date: 1/12/1990 00:00:00
Alternate Name: FEDERAL EXPRESS BOEING FIELD
Affected Media: Ground Water

Facility ID: 2392 Ecology Region: North Western
Release ID: 1676 Release Date: 1/12/1990 00:00:00
Release Status: Reported Cleaned Up Status Date: 6/1/1995 00:00:00
Alternate Name: FEDERAL EXPRESS BOEING FIELD
Affected Media: Soil

Facility ID: 2392 Ecology Region: North Western
Release ID: 1676 Release Date: 1/12/1990 00:00:00
Release Status: Reported Cleaned Up Status Date: 6/1/1995 00:00:00
Alternate Name: FEDERAL EXPRESS BOEING FIELD
Affected Media: Ground Water

UST:

Facility ID: 2392
Install Date: 12/31/1964 0:00
Capacity: Not reported
Status: Not reported
Tank Name: UNLEADED GASOLINE
Substance: NW
Compartment #: Not reported
Ecology Region: 1

BQ293
NE
1/2-1
4310 ft.
Higher

7607 PERIMETER ROAD SOUTH
SEATTLE, WA

HMIRS 200114917
N/A

Site 6 of 14 in cluster BQ

BQ294
NE
1/2-1
4312 ft.
Higher

CONTRACT APPLICATIONS INC SEATTLE
7600 PERIMETER RD
SEATTLE, WA 98108

RCRIS-SQG 1000418409
FINDS WAD982652455

Site 7 of 14 in cluster BQ

RCRIS:

Owner: CONTRACT APPLICATIONS INC
(360) 555-1212
EPA ID: WAD982652455
Contact: RICHARD RADOMSKY
(612) 541-8781

Classification: Small Quantity Generator
Used Oil Recyc: No
TSDF Activities: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

CONTRACT APPLICATIONS INC SEATTLE (Continued)

EDR ID Number
EPA ID Number

Database(s)

Violation Status: No violations found

1000418409

FINDS:

Other Pertinent Environmental Activity Identified at Site:

Facility Registry System (FRS)

Resource Conservation and Recovery Act Information system (RCRAINFO)

BQ295
NE
1/2-1
4314 ft.
Higher

**ARMORED TRANSPORT MAINTENANCE PERIMETER
7595 PERIMETER RD
SEATTLE, WA 98108**

RCRIS-SQG
FINDS

1000878808
WAD988521332

Site 8 of 14 in cluster BQ

RCRIS:

Owner: ARMORED TRANSPORT MAINT
(360) 555-1212

EPA ID: WAD988521332

Contact: ROBERT REDD
(702) 273-7383

Classification: N, Small Quantity Generator

Used Oil Recyc: No

TSDF Activities: Not reported

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:

Facility Registry System (FRS)

Resource Conservation and Recovery Act Information system (RCRAINFO)

BQ296
NE
1/2-1
4317 ft.
Higher

**AMERIFLIGHT INC HANGER 5
7585 PERIMETER RD S
SEATTLE, WA 98108**

RCRIS-SQG
FINDS

1000878807
WAD988521324

Site 9 of 14 in cluster BQ

RCRIS:

Owner: AMERIFLIGHT INC
(360) 555-1212

EPA ID: WAD988521324

Contact: ROBERT REDD
(213) 668-9283

Classification: N, Small Quantity Generator

Used Oil Recyc: No

TSDF Activities: Not reported

Violation Status: No violations found

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

AMERIFLIGHT INC HANGER 5 (Continued)

1000878807

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

BQ297
NE
1/2-1
4320 ft.
Higher

7575 PERIMETER RD S
SEATTLE, WA

Site 10 of 14 in cluster BQ

WA SPILL:

Facility ID: 507991
Date Received: 11/18/1999
Business Name: UNITED PARCEL SERVICE
Material Desc : PETROLEUM - HYDRAULIC OIL
Medium: ROADWAY-PAVED
Material Qty: 20
Material Units: GALLON

SPILLS S105391118
N/A

BQ298
NE
1/2-1
4320 ft.
Higher

7575 PERIMETER RD. S, BOEING FIELD FACIL
SEATTLE, WA

Site 11 of 14 in cluster BQ

WA SPILL:

Facility ID: 505736
Date Received: 08/06/1999
Business Name: SHIPPING
Material Desc : PETROLEUM - HYDRAULIC OIL
Medium: ROADWAY-PAVED
Material Qty: 10
Material Units: GALLON

SPILLS S105389962
N/A

BQ299
NE
1/2-1
4320 ft.
Higher

UPS BOEING FIELD
7575 PERIMETER RD S
SEATTLE, WA 98108

Site 12 of 14 in cluster BQ

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)

FINDS 1005106522
000009110256

BQ300
NE
1/2-1
4320 ft.
Higher

7575 PERIMETER ROAD
SEATTLE, WA

Site 13 of 14 in cluster BQ

HMIRS 9998090650
N/A

BQ301
NE
1/2-1
4320 ft.
Higher

7575 PERIMETER ROAD SO
SEATTLE, WA

Site 14 of 14 in cluster BQ

SPILLS S105390070
N/A